
A CHILTON PUBLICATION

FOR 1961



Every size and type of Perfect Circle ring is designed to have the correct radial pressure distribution for the type of engine in which it is to be used.

Processes and equipment are carefully developed, through the use of precision gauges, to produce the exact pressure required. Radial pressure is accurately measured at 17 points around the ring and the measurements are then graphically plotted.

Testing such as this is your assurance that Perfect Circle rings are built to take it. Rely on Perfect Circles—the most preferred piston rings.





PISTON RINGS - PRECISION CASTINGS - POWER SERVICE PRODUCTS - SPEEDOSTAT HAGERSTOWN, INDIANA - DON MILLS, ONTARIO, CANADA



"Big plus . . . added little services not found in any plan"

say J. F. HUNTER and WM. A. SARCONI, JR., partners in Jess Hunter Motors, Ford dealer, Pueblo, Colo.

"We have used Commercial Credit Plan for the past 14 years because their retail and wholesale finance plans have always been competitive. The big plus with Commercial Credit has been the added little services they have rendered that are not found in any plan. To keep our side of the bargain, we have one employee who specializes in financing to help close time sales. We also pay bonuses and have other inducements for salesmen for deals closed on the house plan."


Commercial Credit dealers are <u>successful</u> dealers

Write or call the nearest Commercial Credit Corporation office for complete information on the benefits of Commercial Credit Plan. Why not do it, today?



A service offered in principal cities of the United States and Canada by subsidiaries of Commercial Credit Company — Capital and Surplus over \$240,000,000.

Thompson Products makes the...



for automatic transmissions

ana

anna,

Thompson Products
designed it and built it! New
car manufacturers adopted it—
and for good reasons! Thompson's
new Slipper-Type Pump prolongs
automatic transmission life...does not
lose efficiency through prolonged service.

This new Thompson design outwears other types of automatic transmission pumps and maintains higher efficiency for a longer lifetime of use because the wide, strong "slippers" are self-sealing. As wear occurs, the "slipper contacts" widen and seal tight against the pump bore to maintain full oil volume, thus preventing slippage in many cases.

Whether it's seals or pumps, gaskets or gears—go Thompson Products all the way. Our warehousing and distribution facilities assure full-line, overnight service for all your automatic transmission requirements.

Sold thru the world's finest jobbers.



Thompson Products Replacement Division

Thompson Ramo Wooldridge Inc.

Cleveland 3. Ohio



My PRIDE Cushion-Grip Screwdriver is the finest ever made. The Neoprene grip never slips, even when my hand is wet or oily. I can turn screws more tightly, but the grip never hurts my hand.

It's got a precision cross-ground point . . . a bolstered blade of high grade, hardened alloy tool steel . . . winged shank for extra strength . . . is hammer and shockproof . . . and oil, brake fluid, gas or dirt don't hurt the Neoprene handle.

No wonder everyone wants to borrow my PRIDE Cushion-Grip Screwdriver.

They ought to get their own. You can, too. Just ask your Purolator Supplier.



The Mechanic's Screwdriver

See the companion line — PRIDE Redhead Screwdrivers
...80 different sizes for every need

RUSSELL W. CASE, JR., Publisher

Charles W. Hevner, Assistant Publisher E. H. Miller, Advertising Manager E. W. Hevner, Circulation Manager H. C. Parris, Marketing Assistance Manager John H. Kofron, Chilton Research Director

Address Mail to Motor Age Chestnut & 56th Sts., Phile. 39, Pa. Phone: SHerwood 8-2000

REGIONAL MANAGERS

ATLANTA 3, GEORGIA John W. Sengston 9!! William Oliver Bldg. 32 Peachtree St., N.E. Phone JAckson 3-679!

CHICAGO I, ILLINOIS George R. Ives, Jr. Suite 418 360 North Michigan Ave. Phone RAndolph 6-2166

CLEVELAND 15, OHIO Ben E. Ball 930 B. F. Keith Bldg. Euclid Ave. and E. 17th St. Phone SUperior 1-2860

DALLAS 6, TEXAS William J. Smyth Room 189, Meadows Bldg. Expressway at Milton Phone EMerson 8-4751

DETROIT 2, MICHIGAN Duane Jones 1015 Stephenson Bldg. Phone TRinity 5-2090

LOS ANGELES 57, CALIF. L. H. Jackson 198 S. Alvarado St. Phone DUnkirk 7-4337

NEW YORK 17, N.Y. Fred Maxted, Jr.—Len Kestell 100 E. 42nd St. Phone OXford 7-3400

SAN FRANCISCO 3, CALIF. Frank W. McKenzie 1355 Market St. Phone UNderhill 1-9737

WASHINGTON EDITORIAL OFFICE National Press Bldg., Washington 4, D.C.

One of the Publications Owned by



CHILTON COMPANY

Executive Offices
Chestnut & 56th Sts.
Philadelphia 39, Pa., U.S.A.

Officers and Directors
G. C. BUZBY, President

Vice Presidents

P. M. FAHRENDORF
L. V. ROWLANDS
ROBERT E. McKENN
MAURICE E. COX
EVERIT B. TERHUNE, JR.
CHARLES A. S. HEINLE
GEORGE E. CAMERON

STANLEY APPLEBY, Comptroller

CHILTON'S

MOTOR AGE

FRANK P. TIGHE, Editor

William H. Wolfe, Managing Editor · John K. Montgomery, Technical Editor · William M. Montgomery, News Editor · Terrence J. McCabe, Service Editor · Marcus Ainsworth, Statistical Editor · Harold Nelson, Specifications Editor · Howard Kohlbrenner, Art Director · Edward Janicki, Detroit News Editor · Joseph Geschelin, Engineering Editor · Paul Murphy, Chilton's Flat Rate & Service Manuals Editor · Ken Rose, Midwest Editor · Ray Kay, Pacific Coast Editor · George H. Baker, Neil Regeimbal, David R. Heinly, Washington News Editors · Paul Wooton, Washington Member of the Editorial Board · Charles C. Tapscott, Editorial Consultant · Robert Gunning, Readability Consultant

NOVEMBER 1960

Volume 79, No. 12

IN THIS ISSUE

| NEWS | Newscoop | 33 |
|-------------|--|-----|
| | News about New Products—New Products Shopping Center | 63 |
| | | |
| ARTICLES | Truck Highlights for 1961—begins on | 38 |
| | Tips on Alternator Service | 43 |
| | Spotting System Leaks Electronically | 46 |
| | Winterizing Check-ups Spur Sales & Service | 48 |
| | For Longer Valve Life Check the Old Ones | 50 |
| | Photographs Help Body Shop Volume | 54 |
| | Independent Garage Owners of America in Action | 56 |
| | What to Do When You Run Into Trouble (BEARINGS) | 58 |
| | Ford Ignition Timing (Chilton Automotive Manuals Page) | 95 |
| | | |
| | | |
| DEPARTMENTS | Editorial Comment Page | 37 |
| | New Car Registrations Table | 59 |
| | Tune-up and Alignment Specifications | 60 |
| | Readers' Clearing House (Troubleshooting Problems) | 6 |
| | Current Price, Weight and Body Table | 62 |
| | Shop Kinks for Cars and Trucks | 6 |
| | Tips for the Body Shop. | 70 |
| | New Literature Information | 8 |
| | Calendar of Coming Events | 8: |
| | Advertisers' Index | 11 |
| | Last Laff | 113 |








MOTOR AGE. Published monthly by Chilton Company, Chestnut & 56th Sts., Philadelphia 30, Pa. Second-class mail privileges authorized at Philadelphia, Pa. with additional entry at Easton Pa. Subscription price: United States, United States Possessions, \$4.00 for one year, \$7.00 for two years; Canadian, Foreign, \$5.00 per year, \$8.00 for two years; single copies 40 cents. COPYRIGHT 1960 by CHILTON COMPANY.

RACK IDEA



helps you give better COOLING SYSTEM SERVICE

You buy one rack-Victor keeps it current year after year

Here's a brand-new idea to help you get more cooling system service business. This combination storage-display rack will keep your Victor

water outlet gasket assortment always up to date.

The secret of this new rack is a renewable backboard printed with numerical identification and outline of gaskets in Victor's latest assortment. Victor keeps your rack current to cover the latest models by supplying you with a new backboard year after year. No need to buy a new rack each year; you'll just change the backboard—and it's

The Victor water outlet gasket assortment is carefully selected to cover "90% of the cars on the road." With this rack and this assortment, you'll always have the right gasket to help build more cooling system business.

Order now from your Victor Jobber by these numbers: No. JV147D for the rack; No. JV137J for the gasket assortment.

Victor Mfg. & Gasket Co., P.O. Box 1333, Chicago 90, Ill. Canadian

Plant: St. Thomas, Ont.



The big gasket assortment for this rack -No. JV137J-gives you 24 different numbers (260 gaskets total) for water outlets, thermostat housings, thermostats and water bypasses, covering all current makes and models, including 1960's. For smaller shops, assortment No. JV138G gives you only the gaskets for the most popular cars—12 numbers, 120 pieces total.

Sealing Products Exclusively

PACKINGS OIL SEALS

The 100% Coverage Line . . . for Cars, Trucks, Tractors, Stationary Engines



NEED A NEW Britain TOOL? CALL YOUR NAPA JOBBER!



Any Tool you ever need is no further away than a 'phone call to your NAPA Jobber! No need to wait for service! Check YOUR Tool Kit right now. Just pick up the 'phone and get that New Britain Tool immediately that you have been needing or intending to buy. It will make money for you. Remember! The cost of Tools you use in your work is deductible from your income tax.

HAND TOOLS

THE NEW BRITAIN MACHINE COMPANY NEW BRITAIN . CONN. Presenting

Slipper Type Autothermic Heavy-Duty Aluminum A Complete Line of

PISTONS

ALUMINUM ALLOY AUTOTHERMIC CAST IRON

Making superior pistons for all types of cars, trucks, buses and tractors has been a special art with Permite for the past forty years. Permite engineers *introduced* the aluminum alloy piston to the automotive industry!

All Permite Preferred pistons are factory designs, with emphasis on strength, heat-resistance, positive control of thermal expansion, and accuracy of finish. You can use them with complete assurance that they will fit and perform efficiently.

TOP QUALITY PINS AND BUSHINGS

Piston pin cases are of excellent wearing quality and maximum strength. Case depth and core refinement are carefully checked. Bushings are solid or steel-backed.



The Most Complete Line of Engine and Chassis Parts Available
... Bearings, Pistons, Cylinder Sleeve Assemblies, Valves,
Water Pumps, King Bolt Sets, Tie Rod Ends, Drag Link Assemblies,
Spring Bolts and Shackles, Stabilizer Links, Ball Joints,
Front End Suspension Parts ... Today's Bigger and Better
Line of Permite Preferred Parts. Call Your Jobber!

ALUMINUM INDUSTRIES, INC., Cincinnati 11, Ohio

ermite preferred

by vehicle manufacturers / car and truck dealers / garage and service men / fleet operators

How to make your customers purr-r-r-r-r

Give them the richest, most complete motor oil in the world—Pennzoil Z-7. So rich it gives double the protection demanded. So complete you never need extra additives.

They'll be "regulars" from then on—for all the Pennzoil motor oils and lubricants you handle. Because they get longer, trouble-free engine performance. Actually increase gas mileage.

You'll get increased traffic, boost sales of all your services and products—and add up more extra profits than ever before!

Easy to keep track of all customer service needs with Pennzoil's exclusive Kontax System ... 4-to-1 favorite among dealers everywhere.

Call your Pennzoil distributor today about this 100% pure Pennsylvania motor oil and all Pennzoil quality products and profit-building programs.

He's listed in the Yellow Pages.





FOR PROFIT... FOR PERFORMANCE

MOPAR MUFFLERS

You've got big "plus" features working for you when you handle MoPar's best-selling Sono 4X Mufflers.

These mufflers install easily, quickly, give you more time for additional business. They also give you standardization which reduces inventory, saves storage space. You can always count on immediate availability.

MoPar Sono 4X Mufflers give your customers quiet operation, excellent performance—help turn casual customers into regulars.

Now is the time to stock an adequate supply of MoPar Mufflers and Tail Pipes. Call your MoPar Wholesaler or your Valiant, Plymouth, Dodge, De Soto, Chrysler, Imperial or Dodge Truck Dealer.





SELL THE LINE THAT KEEPS YOUR CUSTOMERS SOLD ON YOU-MOPAR

Free Booklet—The MoPar Muffler Story: Here's a handy booklet which gives you all the vital information about MoPar Mufflers and how they can help improve your profit picture. Ask your MoPar Wholesaler for a FREE copy.



For Extra Headlamp Profits:

Replace Obsolete 7"Lamps



New 6000 series Vision-Aid Headlamps with Spotlight Low Beams make all 5000 series headlamps obsolete. They vastly improve visibility in all types of driving ... they give 2-headlamp cars more of the 4-headlamp efficiency. Switch over your customers and gain extra profits in the bargain.

New Vision-Aid Headlamps with Spotlight Low Beams
— initial equipment choice of leading car manufacturers
— insure these extra profits. The Spotlight Low Beam is

scientifically positioned where it's needed most — down the right side of the road, away from the headlights of oncoming traffic. The more powerful high beam makes visibility on the open highway safer and easier. These Vision-Aid headlamps are long on reliable service, too.

Insure your service work and your profits. Tell your supplier to make 'em Vision-Aid Headlamps with Spotlight Low Beams. Automotive Products Division, Tung-Sol Electric Inc., Newark 4, New Jersey.



HEADLAMPS . MINIATURE LAMPS . FLASHERS

NEW B&D AIR COOLED 1/4" HEAVY SHORTY GIVES A GUY A BREAK!

Gets into the tightest spots!

Ends knuckle busting stiff necks . . sore muscles

Ever try pulling a bad core plug? Or blind drilling a bumper bracket? Then, brother, the new Black & Decker 1/4" Heavy-Duty Shorty Drill is your kind of tool! It's so compact it goes just about any place your hand goes... gives you finger room even on flush jobs, too.

And cool! This drill has two fans for drilling comfort! If you're sick and tired of hot-handling tools . . . want to save on tape and liniment . . . get 60% more power for 32% less money than ever before . . . mail coupon right away. Your jobber will be out to demonstrate.

It's yours for as little as 14c a day!





Hard to reach spots are duck soup for a B&D Shorty.



Try it in the maze of tail pipe, shocks and springs.

THE BLACK & DECKER MFG. Co., Dept. 5111 Towson 4, Maryland. (In Canada: Brockville, Ont.)

- ☐ Please arrange a demonstration of 1/4" Shorty.

☐ Please send additional information on,

City.



"STAGECOACH WEST"
ABC-TV every other
Tuesday evening,
beginning Oct. 4
in most areas. See
local listing for time.

COMING AT YOU!

Not just one, but two thrilling network TV shows to help Delco Battery dealers! Each is a full hour show, packed with adventure and action, designed to entertain millions of car owners during your peak battery sales period. If you are a Delco Battery dealer, stock up now to gain top profit

from the kind of selling support you get only from Delco. If you don't presently carry Delco, better get the whole story fast on America's No. 1 Battery from your United Motors Service supplier.


DELCO DC-12 . . . Best to START with . . . Best to STAY with

Another reliable
General Motors Product
distributed nationally through



DELCO DRY CHARGE BATTERY

"THE ISLANDERS"
ABC-TV every other
Sunday evening,
beginning Oct. 9
in most areas. See
local listing for time.



in Electric Windshield Wipers that reduce the dangers of "dirty weather" driving.

Give yourself and your drivers the extra protection of ROBERT BOSCH *Electric* Windshield Wipers. Dependable even in the foulest weather... Powered by a rugged ROBERT BOSCH *electric* motor that's independent of engine speeds. Millions in use. Won't falter even when you step hard on the gas, or climb a hill—won't stall even if your engine stalls. Play safe in "dirty weather." Install ROBERT BOSCH *Electric* Windshield Wipers now. They're inexpensive, easily installed.

ROBERT BOSCH CORPORATION

40-25 Crescent St., Long Island City 1, N.Y. • 225 Seventh St., San Francisco 3, Calif.

® Reg. U. S. Pat. Off. ROBERT BOSCH GMBH Stuttgart



PROTECTOR



Wagner Lockheed HEAVY DUTY BRAKE FLUID surpasses S.A.E. specification 70R1

—meets State laws, and also conforms to Federal specifications . . . It definitely is a heavy-duty fluid—yet is moderately priced. Performance proves it to be the best brake fluid in its price range.

Wagner Lockheed SUPER HEAVY DUTY BRAKE FLUID is the very finest on the market

It surpasses S.A.E. specifications 70R1 and 70R3, meets State laws, and conforms to Federal specifications . . . Recommended for use on all heavy-duty trucks, also for modern high-horsepower passenger cars.



Wagner Fluid-Bal makes bleeding the brake system a one-man operation.



Wagner Lockheed—the best known name in brake service.

LOCKHEED BRAKE PARTS, FLUID, BRAKE LIMING and LIMING PRAKE SHOES . AIR HORMS . AIR BRAKES . TAGHOGRAVID

of LIVES!

Wagner Lockheed BRAKE FLUID

protects brake systems...and lives of your customers

Your customers literally stake their lives on your choice of brake fluid. For that reason you should use Wagner Lockheed – a really safe brake fluid that actually protects brake systems. Safe brake performance helps protect the lives of those whose cars you service.

It's no wonder that Wagner Lockheed is the world's largest selling brand of brake fluid. This superior quality product is compounded of the finest ingredients *chemically balanced* to function efficiently under all driving conditions—in all seasons.

Wagner Lockheed Heavy Duty and Super Heavy Duty have these features:

• Chemically balanced—with the correct proportion of all ingredients required to provide an all-season fluid that maintains high operating temperature characteristics, yet functions in sub-zero temperatures.

- Chemically balanced—with just the right amount of costly type lubricant to provide proper lubrication to all parts of the brake system without causing cups or hose to swell.
- Chemically balanced—with exactly enough moisture absorbing properties so that metal parts in the brake system are protected against corrosion.

Remember—"Safe Brakes Protect Lives"...
There's a supplier of Wagner Products near you.
Look to him for Wagner Lockheed Brake Fluid,
Brake Parts, Power Brake Repair Kits, Brake
Lining, and Lined Brake Shoes... One call
gets all!

GET DETAILS on how easily you can qualify to become a Wagner Lockheed Franchised Dealer . . . It pays to be identified with a leader. For complete information, ask your supplier of Wagner Products, or write us.





Wasner Electric Corporation

6492 Plymouth Ave., St. Louis 33, Mo., U.S.A. (Branches in principal cities in U.S. and in Canada)

I'm inverested in:

- ☐ Details on Wagner Lockheed Brake Fluid
 ☐ Information on Franchised Dealer Plan
- Free Catalog AU-1

NAME


FIRM...

ADDRESS

CITY & STATE

WFRO-1

Free* G-E "Cap-Trap" cuts gas cap losses —saves time, money, customers too!



- * POWERFUL 21/4" MAGNET HOLDS GAS CAPS TIGHT
- * FITS FLAT... WON'T CATCH ON LICENSE PLATE
- * HAS WITTEK "SURE-TITE" CLAMP

A lost gas cap can cost you anything from a few dollars—to a few customers. But a G-E "Cap-Trap" can eliminate these losses. It keeps gas caps handy, and in the same place every time. You save steps and money. You pay nothing extra for the G-E "Cap-Trap"—and it doesn't come out of your profits! It's free with a purchase of 12 G-E SUBURBAN Headlamps and 10 G-E rear lamps. Ask your General Electric Headlamp supplier about a "Cap-Trap" today.

GENERAL ELECTRIC'S NATIONAL ADVERTISING WILL HELP YOU SELL G-E SUBURBAN HEADLAMPS TWO-AT-A-TIME! Many thousands of people will see G-E SUBURBAN Headlamp ads this Fall in LOOK, LIFE, POST, SPORTS ILLUSTRATED, TRUE, MECHANIX ILLUSTRATED and POPULAR MECHANICS. They'll see how a lot of people are actually throwing away both headlamps when one still works—and switching to G-E SUBURBAN Headlamps! These are the only 7" headlamps with the low beam filament on focus to give a "spotlight" effect down the right side of the road. They give twice the light where it's needed most. General Electric Co., Miniature Lamp Dept. M-030, Nela Park, Cleveland 12, Ohio.

Progress Is Our Most Important Product

GENERAL @ ELECTRIC

Make clean-up jobs easier and faster with . . .

DITZ-0 4-4-0





Use DITZ-O on acrylics, lacquers and enamels . . . removes silicones.

zips off old waxes and greases...gives undercoats a bulldog grip

DITZLER'S DITZ-O DX-440 is a fast-acting solvent that speedily removes old wax and grease. It leaves a *chemically clean* surface to which undercoats adhere more doggedly.

• The "floating action" of DITZ-O loosens and

dissolves old polishing waxes, silicone particles, greases, oils, tar, and road dirt imbedded in the pores of the old finish. It floats them to the surface where they can be quickly wiped off. Unless thoroughly removed, these undesirable materials can cause new finishes to blister, flake and peel.

• Although strong enough to dissolve wax and dirt, DITZ-O will not soften old or new paint film. And you can safely use it with primer-

surfacer as it will not lift featheredge or cause wrinkling at moldings.

• DITZ-O has no unpleasant odor. It's easy on the hands. You'll like its economy, too, as it goes farther than other solvents.



To remove stubborn silicone particles use SILICON-OFF

Ditzler's Silicon-Off DX-515 is especially formulated to clean finishes on which polishes containing silicone have been used. Unless thoroughly cleaned off, silicone particles can interfere with proper

flow, leveling and adhesion. They can cause craters or "fish eyes." With SILICON-OFF you quickly remove all traces of silicone as well as waxes, greases and oils. Can be used safely on acrylic finishes.

Ditzler Color Division, Pittsburgh Plate Glass Company . Detroit 4, Mich. . Torrance, Calif.




DITZLER

PAINTS . GLASS . CHEMICALS . BRUSHES . PLASTICS . FIBER GLASS

PITTSBURGH PLATE GLASS COMPANY

IN CANADA: CANADIAN PITTSBURGH INDUSTRIES LIMITED

Save Time and Money ...



Make ONE CALL, THAT'S ALL!



FOR ALL YOUR FORD REPLACEMENT PARTS

You want quality. You want service. Most of all you want the part that will do the job and satisfy your customer. Your Ford Dealer can give you all

three!

He has Super-Quality Parts... the parts that are made to the highest quality standards in the world. And he's as close as your telephone!


Genuine Ford Parts are readily available in your neighborhood. Your Ford

Dealer is anxious and able to serve you. Give him a ring!

So, get the parts that are made right . . . to fit right . . . and last longer. A phone call will quickly prove to you that your Ford Dealer is in a favorable position to offer them at supermarket prices!

P.S. Don't forget that Ford Super Quality is now available in universal parts for different-make cars and trucks.





"Years ago, any bearing would do the job...

... but in today's modern, high compression engines you've got to use the best. That's why I rely on Monmouth. After 41 years in the business, I know that Monmouth's trouble-free performance means satisfied customers."

If you want performance that pays off, use Monmouth Bearings in all of your engine rebuilds. For instant service, call on your NAPA jobber. He carries the complete Monmouth line to meet all of your engine bearing requirements.

Low premium "customer insurance" is yours when you install . . .

MONMOUTH Engine Bearings

CLEVITE SERVICE: Cleveland Graphite Bronze . Division of Cleville Corporation . Cleveland 3, Ohio

says R. E. Lucas, Owner Broaddus & Lucas Richmond, Virginia



HIGHEST SILICONE CONTENT

SILICONE WEMICANT AND PRESERVATIVE FOR RUSSER PARTS IGNITION SYSTEMS AND SATTERY TERMINALS In 12 oz. spray cans 2 oz. and 8 oz. tubes

Stops Squeaks!

4X SILICONE

LUBRICATES . PRESERVES . INSULATES

Recommended By Leading Auto Makers . . . For Finer Garage Service

Silicone-rich 4X guards weatherstripping, wiring, batteries, and rubber parts against heat, cold, moisture, weathering and corrosion. It stops squeaking and sticking of rubber to metal; aids electrical performance; keeps locks and antenna working smoothly. All of this means that Dow Corning 4X makes car owners happier ... with your service!



KEEPS LOCKS TROUBLE FREE

4X lubricates locks, keyholes, radie antenna. Prevents freezing and corrosion. Never gums or runs. Excellent for window channels, too.



PROTECTS IGNITION SYSTEMS

Keeps moisture out of plugs, wiring, distributor, magneto. Eliminates electrical leakage. Aids engine performance—helps prevent misfires.



PROLONGS BATTERY LIFE

Minimizes corrosion build-up on cables, case, terminals; prevents power loss. Helps assure quick starts — maximum battery life. Eases cleaning.



STOPS SQUEAKS AND STICKING

Preserves weatherstripping around doors, trunks, hoods, windows. Keeps it flexible, stick-proof. Helps preserve rubber mounts and fan belts for more dependable service.

NONMELTING, NONFREEZING, NONGUMMING ... FROM -40° TO 400° F.1

There's no substitute for SILICONES for better car care . . . and Dow Corning 4X is highest in silicone content! Order from your jobber now!



Dow Corning CORPORATION

MIDLAND, MICHIGAN

TLANTA BOSTON CHICAGO CLEVELAND DALLAS LOS ANGELES NEW YORK WASHINGTON, D. C.





Get It Now for Christmas Giving!

AUTOLITE STOCK CAR RACING GAME

Manufactured by American Flyer especially for Autolite! This electric, remote-controlled racing game (\$34.98 value) can be yours when you purchase Autolite Spark Plugs.

Watch the kids' faces light up when they discover this realistic, all-electric racing game under the Christmas tree. There's nothing like it anywhere that provides as much fun and excitement as this spine-tingling racing game now offered by Autolite. It duplicates the spills and chills of real racing . . . with authentic-looking hot rods . . . with figure-8 grooveless track that gives each player an equal chance to win . . . with remote dual control transformer to make the cars go. It's a wonderful gift . . . one that's easy to get now and lay away for Christmas! Don't delay. Your Autolite Spark Plug Wholesaler has all the money-saving details. Call him today!

THE ELECTRIC AUTOLITE COMPANY, TOLEDO 1, OHIO







AUTOLITE B

PROVED IN COMPETITION FOR ALL CARS

BE SURE TO TUNE IN "NEWS ON THE HOUR" NBC RADIO-SPONSORED BY AUTOLITE.

1St choice in the Ryder System MODEL SHOP

> ... and in more shops throughout the country than all others combined ...

VALVE GRINDING EQUIPMENT

"Choose with Confidence!"

Look for SIOUX in the yellow pages under "Tools, Electric" or write to

ALBERTSON & CO., INC.

SIOUX CITY, IOWA, U.S.A.

Air Impact Wrenches • Air Screwdrivers • Electric Impact Wrenches • Drills • Screwdrivers • Grinders • Senders • Polishers • Flexible Shafts • Portable Saws • Valve Grinding Machines • Abrasive Discs.

*Ryder System
of Miami, Fla. is made up
of a large motor common carrier or a large motor common carrier operation and a vast national rental and leasing network. It owns close to 25,000 vehicles. The Miami Model Shop is the first experimental model shop of its kind in the country. It is designed and engineered to

test new equipment and techniques

to achieve maximum results with a minimum of lost motion,





There's nothing like a new car!







Everybody's talking about the new cars, everybody's thinking about the new cars! And once again, "There's Nothing Like a New Car" is the theme of a big, colorful advertising campaign to stimulate customer traffic at General Motors dealers. The ads are designed to help funnel today's ever-growing mountain of disposable income straight into *your* dealership, to convince the millions of readers that they haven't lived until they've driven a new '61 GM car. Read the ads yourself. Note the fun and excitement, and the common-sense sales appeal of GM's performance, reliability and big selection. It's great to be a GM dealer! . . . GENERAL MOTORS







An original product design will always be copied, but the genuine article keeps the confidence of the user by dependability. AERO-SEALS laugh at vibration and corrosion... hang on tightly...never shake loose or snap open. And they won't damage hose. Bands and housings are of 302-13-8 stainless steel. No extra cost for quick-attach Jets. Regular AERO-SEALS are also available.

Complete range of sizes from 7/16" up.

BREEZE

BREEZE CORPORATIONS, INC.

700 Liberty Avenue, Union, New Jersey Cable Address: Breeze, Union, N. J.

DIRT-SEALED trigger



- Easy-Out Replaceable Bushing. You don't have to buy a new hammer case when you want to re-
- Life Guard Commutator. Exclusive 1-R construction prevents motor damage, permits easy dressing, provides long brush life.

place the bushing on an I-R Impactool.

- Job-Tailored Motor. Not "adapted" but built specifically for rugged Impactool duty.
- "2-Pack" Construction. Either the impact mechanism "pack" or the motor "pack" can be serviced individually without disturbing the other.
- Electronic Precision. Special electronic equipment double-checks machined parts for perfect mating of all surfaces and bores.

best design—biggest line look for the red ball extras

Ingersoll-Rand
11 Broadway, New York 4, N. Y.

56A-18

How long does it change a set

If you haven't checked lately, you're in for a surprise!

- Starting with '58 models, plugs are much easier to reach
- More and more of your customers are driving "quick change" sixes
- Champion's Plug-Master wrench slashes time on "tough jobs"

LESS TIME MEANS MORE PROFIT

You'd be surprised how much more profitable spark plug jobs are these days. One reason is that, since 1958, manufacturers have been designing engines so that plugs are easier to reach. For example, before 1958, Ford V-8's had spark plugs *under* the manifold. This job took approximately 30 to 35 minutes. Since '58, spark plugs have been *above* the manifold on many engines — and the job can be done in 24 minutes or less.



Ford V-8 with plugs under manifold requires 30 to 35 minutes for change



Newer models, with plugs above manifold, take only 20 to 25 minutes


Your profit on 8 plugs (at 45¢ per plug) is \$3.60. If the job takes only 24 minutes, this is

equal to an hourly rate of \$9.00! And that does not even include any installation charge to the customer. (The times shown here are averages — using a Champion Plug-Master wrench and Plug-Mate socket — and can easily be improved upon with a little practice.)

And "times have changed" for other new V-8's, too. (Chryslers, for example, now require only a half hour or less for plug changes, instead of the pre-1958 time of 40 to 50 minutes!)

MORE COMPACTS AND "QUICK CHANGE" SIXES ON THE ROAD TODAY

Of course, spark plug changing is even easier and faster on 6-cylinder engines — averaging only about 15 minutes per job. And there are more and more 6-cylinder cars being sold every day. 40% of 1960 U.S. production was in sixes. And the growing popularity of compacts promises to raise this figure even higher for 1961.



It takes about a quarter of an hour to change plugs in any 6-cylinder car—a quick, easy profit

CHAMPION SPARK PLUG

really take to of spark plugs?

PLUG-MASTER AND PLUG-MATE SLASH TIME ON ALL PLUG JOBS

You can change even the hardest-to-reach plugs easily with the time-and-trouble-saving team of Champion's Plug-Master wrench and Plug-Mate socket. The Plug-Master's flex-handle saves time and knuckles as it gets into hard-to-reach places, while the Plug-Mate's magnetic socket holds plugs in a firm grip that doesn't let them drop and break.



Low-cost Plug-Master and Plug-Mate available from your regular Champion supplier



AND YOU CAN NOW CHECK PLUGS FASTER, TOO-WITH A CHAMPION PLUG-SCOPE



Champion Plug-Scope makes spark plug checking as easy as watching TV

The Champion Plug-Scope is the fastest, easiest way ever to check spark plugs. You can check a whole set *electronically* — right in the engine — in less than 60 seconds!

And, best of all, your customers can see test results for themselves on the Plug-Scope — a real sales clincher for you! Ask your Champion representative or supplier for a free Plug-Scope demonstration — and see how easy plug checking can be!

With spark plugs easier to reach in new engines, and Champion tools that speed up the job, plug changing is now more profitable than ever before. Order a supply of Champion spark plugs, and see for yourself!



COMPANY . TOLEDO 1, OHIO

Stop Ring Plugging Worries

with Pedrick
Formflex Chrome
Piston Rings

Reproduction of unretouched photograph of piston after normal life's service in an engine—showing free and open condition of Pedrick Formflex Chrome Oil Ring. Protect and build your reputation for the most successful piston-ring and engine-over-haul jobs by guarding against ring plugging. Always use Pedrick Formflex Chrome oil rings. Pedrick's exclusive 4-piece construction gives you the greatest assurance that any tendency to plug will be broken up at the start. All four pieces are free to move independent of each other in the groove. Each one fights against plugging. In abutment-type oil rings, only Pedrick has such effective means to stop plugging.



in addition, PEDRICK FORMFLEX CHROME PISTON RINGS are:

- Easy to install!
- Effective in Side Sealing!
- More conformable!
- All-Purpose—for any kind of service!
- Chrome-faced for longer life!

DEPEND ON

Gedrick
FOR THE BEST RING JOB

MEMA Announces "Key" Committee Plan To Aid Industry



By Thomas S. Rose

President of the Motor and Equipment Manufacturers Association and Assistant Treasurer, Sealed Power Corp.

CHANGES in the automotive aftermarket are normal at any time. But they have greatly accelerated in recent years to alter this market in which members of the MEMA have a mutual and abiding interest. I believe it is vitally important for all of us to participate in a critical reappraisal of that market.

Call Your Attention

It is scarcely necessary to call to your attention that conditions in our industry to which I refer. Loose distributive practices, inThe many fast and swift changes in the service industry prompts action by trade association

adequate legislative controls in some areas, and over-restrictive ones in others, loss of contact between manufacturer and customer, the growing lack of skilled mechanics to deal with today's more complicated cars—these are but a few of the symptoms of the change in the aftermarket which we regard as occasions for general concern.

Take Remedial Action

To the extent that these symptoms represent changes in the tempo of our times, it is up to us to understand them. We must accommodate ourselves to them. To the extent that they represent a challenge to the continued growth and well being of the industry, we must get at their source and take whatever remedial action is required.

After consulting with my fellow officers and the executive staff of MEMA, I am happy to tell you that we have decided on a course of action which, in our opinion, will go far toward returning the aftermarket to the stability which it has traditionally enjoyed for so many of its years.

Briefly, our plan calls for the establishment of "key" committees, one for each area of the aftermarket which calls for analysis and effort. Each of these committees will be responsible to MEMA membership through a central "coordinating committee"—each will be charged with the development and implementation of program designed to clarify and improve the situation as they find it.

Meet the Challenge

For more than fifty years the MEMA has contributed to the progress of the automotive aftermarket. I am convinced that its members will meet the challenge of today's critical conditions actively, effectively, and constructively.

Welding's role in




Operator inspecting nearly completed weld build-up.

RISING costs of reconditioning expensive parts are causing unit rebuilders to search for more economical means of performing these tasks. Crankshafts are a good example of a rebuilt-exchange unit. Of course, there are many other items being reclaimed in the replacement field. However, crankshafts seem to be among the most dominant.

Although new cars are equipped with new crankshafts, almost all replacement crankshafts are rebuilt exchanges.

Closeup shows are welding build-up of worn journal.



Grinding built-up journal down to desired tolerance.



Crankshaft Rebuilding

Discussion of a faster build-up method as presently being used by a Los Angeles firm

Worn bearing surfaces are builtup oversize; then ground down to the desired tolerance. In the past, the build-up has been accomplished primarily by a metal spray process using the oxyacetylene flame to melt a special wire. This in turn is blown onto the metal shaft surface by compressed air.

Today, a faster method of crankshaft build-up has been introduced in Southern California by Absco, Inc. The firm is a progressive welding supply distributor in Los Angeles. Various welding processes have been tried for this particular application. But it was not until the advent of Sigma short arc welding that a new means of crankshaft build-up was found.

Short arc welding is a "low heat input" metal inert gas fusion welding process which produces very sound weld metal. All of these features are valuable when the process is applied to crankshaft rebuilding. It deposits a steel bond on the shaft which is equal to the shaft in density. In fact, the alloy of the shaft mixes with that of the welding wire to form a homogenous deposit. The deposit blends perfectly with the original metal. The machined surface appears to be original metal throughout. All or part of the worn bearing surfaces can be rebuilt into a full fusion weld, which eliminates any tendency to chip or loosen. The low heat of the process minimizes distortion.

Journal is ready for grinding.



Plant superintendent checking newly rebuilt crankshafts.



THE

PULSE

OF

AUTOMOTIVE

BUSINESS

Automotive Wholesaler's Sales and Inventories

Data from the Bureau of the Census, Dept. of Commerce

| | | Per C Sales | in- Inventories | | | |
|--------------------|------------------------------|------------------------------|----------------------------------|------------------------------|------------------------------|--|
| Region | Aug. 1960 from Aug. | Aug. 1960 from July | 8 Mos. 1960 from 8 Mos. | Aug. 1960 from Aug. | Aug. 1960 from July | |
| | 1959 | 1960 | 1959 | 1959 | 1960 | |
| New England | +10 | +16 | +8 | | +2 | |
| Middle Atlantic | +11 | +17 | +4 | - 1 | -2 | |
| East North Central | + 9 | + 9 | +7 | +16 | -2 | |
| West North Central | + 9 | +16 | +1 | + 7 | -4 | |
| South Atlantic | +17 | + 9 | + 3 | + 6 | 0 | |
| East South Central | + 5 | + 6 | + 2 | + 7 | 0 | |
| West South Central | 0 | + 4 | - 3 | + 4 | -4 | |
| Mountain | + 6 | + 5 | - 6 | + 8 | -3 | |
| Pacific | + 5 | + 7 | + 5 | - 2 | +2 | |
| Jnited States | +18 | +11 | +11 | + 9 | -1 | |

Monthly Sales of Automotive Jobbers incl., Tire and Tube Wholesalers*

All Data are in Millions of Dollars

| Month | 1960 | 1959 | Per Cent Change |
|-----------------------------|--|--|--|
| JanFeb. MarAprMay. JuneJuly | \$ 374 383 418 449 443 469 427 | \$ 352 333 375 392 389 429 419 | + 6.15 +15.01 + 9.87 +14.54 +13.88 + 9.32 + 1.91 |
| Aug | 476 | 405 428 439 429 | +17.53 |
| Total—Year Total—8 Months | \$3,439 | 379 \$4,789 \$3,094 | +11.15 |

^{*} Estimated by the Bureau of the Census,

Monthly Sales of Franchised Car Dealers*

All Data are in Millions of Dollars

| Month | 1960 | 1959 | Change | |
|------------------------------|----------|----------------------|--------|--|
| Jan | \$ 2,577 | \$ 2,531 | + 1.81 | |
| Feb | 2,670 | 2,450 | + 8.98 | |
| Mar | 3,038 | 2,921 | +4.00 | |
| Apr | 3,120 | 2,482 | +25.20 | |
| May | 3,054 | 3,033 | + 0.69 | |
| June | 3.075 | 3,198 | -3.85 | |
| July | 2,467 | 2,903 | -15.02 | |
| Aug | 2,604 | 2,772 | - 6.06 | |
| Sept | *** | 2,305 | *** | |
| Oct | *** | 2,986 | | |
| Nov | *** | 2,284 | *** | |
| Dec | *** | 2,177 | *** | |
| Total—Year Total—8 Months | \$22,605 | \$32,472 \$22,750 | - 0.64 | |


Monthly Sales of Gasoline Service Stations*

All Data are in Millions of Dollars

| Month | 1900 | 1959 | Per Cent Change |
|------------------------------|----------|----------------------|--------------------|
| Jan | \$ 1,356 | \$ 1,282 | +5.77 |
| Feb | 1,286 | 1,197 | +7.68 |
| Mar | 1,388 | 1,318 | +4.85 |
| Apr | 1.457 | 1,348 | +8.09 |
| May | 1,489 | 1,427 | +4.34 |
| June | 1.525 | 1,450 | +5.17 |
| July | 1,587 | 1,516 | +4.68 |
| Aug | 1,578 | 1.504 | +4.92 |
| Sept | *** | 1,419 | *** |
| Oct | *** | 1.482 | *** |
| Nov | | 1,433 | *** |
| Dec | *** | 1,437 | *** |
| Total—Year Total—8 Months | \$11,666 | \$16,793 \$11,042 | +5.65 |

MONTHLY SALES OF AUTOMOTIVE WHOLESALERS— INCLUDING TIRE AND TUBE WHOLESALERS

(All Data in Millions of Dollars)





Miss Autolite (Miss Suzy Smith) is, above, being crowned by TV Celebrity Dave Garroway. Over 100,000 votes were cast by Autolite spark plug dealers across the nation to select Suzy from 12 beauty-queen finalists.

Lee Motor Products Makes Acquisition

Lee Motor Products, Inc., Warehouse Distributor in Cleveland, Ohio, have purchased the business and facilities of Akron Warehouse Distributors, Inc., Akron, Ohio. A separate corporation, the new organization will be known as Lee Motor Products of Akron, Inc.

James E. Beason, who had been president of Akron Warehouse Distributors, will remain in the capacity of president and general manager of Lee Motor Products of Akron, Inc.

General Trading Sold To Gould-National

David E. Bright, chairman of the board of H & B American Corporation of Los Angeles announced the sale of General Trading Company, a 99.3 per cent H & B owned subsidiary, to Gould-National Batteries, Inc., of St. Paul, Minn.

General Trading, also with headquarters in St. Paul, is a wholesale distributor of automotive and industrial supplies and agricultural equipment. It operates 43 distribution centers in the six north central states.

ASIA Suggests Form For Redistribution Reports

According to J. L. Wiggins, Executive Secretary of the Automotive Service Industry Association, one of the major problems in the field of redistribution has been the lack of uniformity. Also a problem has been the need for simplification of reporting forms required by manufacturers for approving functional compensation payments in connection with redistribution sales.

A.S.I.A. through its Redistribution Practices Subcommittee, has been studying this particular problem. It has viewed the problem from the standpoint of eliminating undue hardship in reporting on the part of redistributors while, at the same time, providing essential information for manufacturers utilizing this channel of distribution.

A suggested reporting form was carefully reviewed by manufacturer, warehouse distributor, redistributing wholesaler and wholesaler (jobber) member of the A.S.I.A. Marketing Research Committee and Board of Directors at their recent meetings. It was unanimously approved.



Earl Nightingale (left) presents the first recording of "HOW TO REALIZE YOUR AMBITIONS IN THE AMAZING AUTOMOTIVE SERVICE INDUSTRY" to J. L. Wiggins (right), Executive Secretary of A.S.I.A. This LP (30 minute) recording by Columbia Records was especially written and produced for the Automotive Service Industry Association by Mr. Nightingale.

Although the suggested form "may not meet all requirements of every firm, it is recommended that the $8\frac{1}{2}$ " x 11' format size in quadruplicate snap-out type form, and similar certification, be generally adopted by the industry," states Mr. Wiggins.



Bendix Corp. engineers and California Highway Patrol officials cluster around one of the brake units used in a recent special braking demonstration at the Calif. Highway Patrol Academy. A tractor-trailer laboratory designed and operated by Bendix Corp.'s Products division participated in the heavy duty brake tests.



1961 Pacific Automotive Show officers, seated left to right: Harold Littrell, 1st vice pres.; J. K. Wilkinson, president; William D. Henderson, 2nd vice pres. Standing, left to right: Andrew D. Shaw, treas.; and S. B. Sturtevant, secretary.

Robert Abbott

Robert Abbott, recent Raybestos-Manhattan director and president and general manager of Raybestos-Manhattan (Canada), Ltd. of Peterborough, Ont. died October 9 at his home in Peterborough.

Mr. Abbott started with the Raybestos Company, now the Raybestos Division, in Bridgeport, Conn., in 1918. He helped organize the Canadian plant in 1920 and became its first manager.

Mr. Abbott retired in January 1956 and continued to live in Canada.

W. L. Tomlinson

W. L. Tomlinson, manager of automotive sales for the Glass Division of Pittsburgh Plate Glass Co., died suddenly in Detroit from a heart attack on Sept. 30.

Mr. Tomlinson, age 53, had served as manager of automotive glass sales since 1950. He was widely known in the automobile industry.

He joined Pittsburgh Plate Glass in 1928 at its Detroit branch where he later served for seven years as Detroit district manager of industrial glass sales.

Thermoid Offices

The Thermoid Division Offices are now located in the H. K. Porter Building in downtown Pittsburgh.

The Industrial and Automotive management are now consolidated in one office rather than separated as previously with one in Philadelphia and the other in Trenton, N.J.

A Clarification

In last month's article on the history of the Automotive Advertisers' Council we noted that C. C. Tapscott was the first president of the Council.

"Chuck" Tapscott, former advertising manager for McQuay-Norris Mfg. Co.—the position held today by Noble Hale—joined MOTOR AGE as an editorial consultant following his retirement from McQuay-Norris.

PAS Presents 1961 IASI Show

Automotive Service Industry manufacturers and wholesalers are preparing for the 1961 International Automotive Service Industries Show in Los Angeles. Presenting this "manufacturer-through - wholesaler - to - retailer" event, which will draw service industry key personnel from all over the world, is the Pacific Automotive Show.

J. K. Wilkinson, Pomona Motor Parts, Pomona, Calif. is Show president for 1961. The Show will be held in the Los Angeles Memorial Sports Arena and Portico Annex, February 16-19, 1961.

Show President Wilkinson reports that hundreds of space applications have been received. More than a thousand booths will be filled with new parts, tools, equipment, supplies and accessories. Many of them are for the new models now being manufactured by the Automotive Industry.

Send reservation forms to the Pacific Automotive Show Housing Bureau, 714 West Olympic Blvd., Rooms 504-505, Los Angeles, Calif.



E. J. Muldoon (photo above) has been appointed general manager of the National Automotive Parts Association according to D. N. Test, Jr., NAPA president.



Cecil Morris (2nd from right) receives the first Pacco Pioneer Award, commemorating the fact that he was the first automotive jobber to purchase a Pacco Carburetor Tune-Up Kit. Mr. Morris, owner of the Battery and Electric Co., Greenville, S.C., accepts his plaque from Murray Ferber (right), sales manager of Precision Automotive Components Co., Manchester, Mo. Looking on are B. M. Smith(left), general partner of the National Parts Warehouse, Atlanta, Ga., and William T. Ellis, Pacco southeastern regional manager.

Management Institutes

The Automotive Service Industry Association has announced a program of sales management courses for automotive wholesaler members to be conducted at two leading universities in the United States.

A preliminary meeting of the Planning Committee was held at the La Salle Hotel in Chicago, recently, to outline the major elements to be included in the curriculum at the Top Management Course.

This course will be held at the University of Illinois the week of May 14-19, 1961.

The Planning Committee members includes Edward Kukuk, President, United Auto Sales, Inc., Aurora, Illinois; Richard Derebey, Sales Manager, Albany Park Service, Chicago, Illinois; and Robert Sirotek, Vice President, Illinois Auto Electric Co., Chicago, Illinois.

The A.S.I.A. Wholesaler Executive Courses are under the staff direction of Richard A. Melvin, Executive Assistant, A.S.I.A., with the assistance of Howard McMurchie, A.S.I.A. Promotion Manager. Subject matter for the Management Institute will include sales management techniques, training for salesmen, financial management, advertising, and other popular management problems.

The cost will be \$130.00, all inclusive of tuition, room and board.

Hall-Toledo Appointee

Hall-Toledo, Inc., has announced the appointment of Robert Hollis as a direct factory sales representative. He will be responsible for sales and customer relations in Ohio, Indiana, Illinois, and various other market areas continguous to these states.



Nov. 15—Connecticut Automotive Trades Assn. convention, Statler Hotel, Hartford.

Nov. 16-17—South Carolina Automotive Wholesalers Assn. convention, Wade Hampton Hotel, Columbia.

Nov. 17-20—California Automotive Wholesalers Assn. convention, Hotel El Dorado, Sacramento.

Nov. 17–19—Florida Automotive Wholesalers Assn. convention, Washington Hotel, Jacksonville.

Nov. 17-18—Seventh Annual National Forum of Automotive Air Conditioning, Sheraton Hotel, Dallas, Texas.

Nov. 18-20—Automotive Wholesalers of Illinois convention, St. Nicholas Hotel, Springfield, III.

Dec. 2-9—Automotive Electric Assn. annual meeting, Edgewater Beach Hotel, Chicago.

Dec. 4-5—Georgia Automotive Wholesalers Assn. annual meeting, Atlanta.

Jan. 28-Feb. I, 1961—National Automobile Dealers Assn. annual convention, San Francisco.

Feb. 13-14, 1961—Automotive Booster Clubs, International annual meeting, Statler-Hilton Hotel, Los Angeles, Calif.

Feb. 14, 1961—General Membership Meeting, Automotive Affiliated Representatives, Biltmore Hotel, Los Angeles, Calif.

Feb. 14-15, 1961—Automotive Service Industry Assn. national convention, Biltmore Hotel, Los Angeles, Calif.

Feb. 16-19, 1961—Pacific Automotive Show presents ASI Show, Sports Arena, Los Angeles Memorial Coliseum, Los Angeles, Calif.

Motor Age's

WHO'S WHO



Richard A.
Riley has been
named president of Firestone Rubber
and Latex Products Company, a
division of The

Firestone Tire & Rubber Company, in Fall River, Mass.



John T.
Davis, photo,
has been appointed advertising manager
of McCord Corporation. He
succeeds Edwin

O. Bodkin who retired after holding the position of advertising manager for 37 years.

Donald R. Vance has been appointed supervisor of Perfect Circle Corporation's Engine Testing. He will be responsible for verification and testing of original equipment piston ring applications using customers' own makes of engines.



Richard E.
Ruhe has been appointed assistant to the manager, accessory sales of the Schrader Division of Scovill

Manufacturing Company, Inc.



Joseph P. Foley has been named marketing manager for the Electronics Division of Van Norman Industries, Inc. The

Electronics Division manufactures electronic test equipment. Donald V. Miller and Walter J. Tesch have been appointed regional sales managers for Holley Carburetor Co.

Virgil E. Urbine has been named manager of quality control for The Electric Autolite Company's Bay City, Michigan, division.

P. J. (Pete) Manus has been appointed manager of the Northeast district of Bendix Products Division, The Bendix Corporation. W. T. (Bill) Mallon will be assistant district manager (Brake).



Norman K. Anderson, left, has been appointed vice president in charge of marketing for Allen Electric and Equipment Co. Promotion of V. Joseph Giuffre from field sales manager to manager, automotive sales, was also announced.

Pete Pages has been named a territory manager for Merit Mufflers in N.J., New York City and Phila.

Carroll B. Clark has been promoted to zone manager of the Southeastern District for Purolator Products, Inc.

H. C. "Bud" Foster has been appointed general sales manager for both Gillett & Eaton, Inc. and its subsidiary, Arrow Head Steel Products Company of Howell, Michigan.



Robert G.
Raab of Toledo
has been appointed adverting manager of
The AP Parts
Corporation. He
is also on the

board of governors of the Advertising Club of Toledo.



L. D. Van Gundy, photo, has been appointed sales coordinator for the Grizzly Brake Division of MarPro, Inc.

Ray Eifel has been appointed western regional sales manager for the division.

John B. Holland has been appointed automotive division manager of Oakite Products, Inc. He will headquarter in Detroit.



George A.
Schumm, Jr.,
photo, has been appointed associated products marketing manager for the Ford Division of

Ford Motor Company. He succeeds H. D. Hubbs who retired.



Ancel S. Page has been elected vice president of Dura Corporation. He is also general manager of Page and Page

Co. Division, which was acquired by Dura in August, 1960.



Robert G. Bosart has been appointed to the position of manager of advertising and sales promotion, Consumer Products

Division of Arvin Industries, Inc.

MOTOR AGE

newscoop

Detroit's Greatest Show!
Twelve-Month Warranties
Six-Cyl. Aluminum Engine
Imports In Trouble
Business Upturn Predicted
Compacts vs. Standards
Servicing The Compacts

In the days ahead HERE'S WHAT TO LOOK FOR !!!

(Items gathered and edited by Ed Janicki, Bill Montgomery and Neil Regeimbal)

Detroit's Greatest And Most Successful Show

THE 43RD NATIONAL AUTOMOBILE SHOW, held in Detroit last month, turned out to be one of the greatest and most successful spectacles in automotive history.... It proved that more people than ever are interested in automobiles.... If their interest spurs actual buying, then industry should look forward to one of its best sales years.

Detroit's first national automobile show received a tremendous reception.... AMA officials are now thinking about making it a permanent Detroit fixture.... Final decision, however, will not be made until late this month.

Records of all sorts were smashed.... Attendance soared to 1,400,000 before the lights were finally turned off.... That is a world record, topping even the famous Paris Auto Show, which drew 800,000 this year.... Previous record for a national auto show in this country was set in New York in 1956.... It had a total attendance of 320,000.

Twelve-Month Warranties Come With The '61's

TWELVE-MONTH WARRANTIES became a reality last month... One of the Big Three was first to reveal publicly that the warranty on its cars is being extended to 12,000 miles or one year, whichever comes first... It came as a surprise.... Within a few days all other companies joined bandwagon, announced similar action.

Warranties cover everything but normal maintenance items and include parts and labor costs... As you know, there have been warranties of this nature right along... But they were strictly a matter of policy (General Motors has had a 12-12 warranty in effect since 1941)... However, such warranties applied only in certain situations and only on certain major repairs... Warranties were never publicized direct to public... They were limited to 3000-miles-or-90-days warranties in most cases.

Use Care When Lifting '61 Compacts

DEALERS AND GARAGES ARE CAUTIONED to use care when lifting 1961 compact cars... It is important to have front hoist lifting pads positioned properly when car is lifted... If care is not exercised here, part or all of the front end weight will be supported by the steering arms and linkage... Lifting a car on arms and linkage can destroy front wheel alignment... Also weaken the arms or linkage.

Chrysler Corporation's 6-Cyl. Aluminum Engine

CHRYSLER CORPORATION OFFICIALS confirm reports that company is shaping up a six-cylinder aluminum engine... Motor Age has been discussing Chrysler lightweight powerplant for some time now.

Latest developments: corporation will go into limited production of engine within next two months.... Present schedules call for some 15,000-25,000 units to be turned out at Trenton, Mich., engine plant.... Engine will be installed in Plymouths, Valiants, Dodge Darts and Dodge Lancers going to fleet customers, some general buyers and a few corporation cars.

Slant six engine has a die-cast aluminum block with non-removable cast-in-place iron cylinder bore liners .100" thick.... Liners, however, can be rebored up to a maximum of .040" oversize.

Profits In The Automotive After-Market

PROFITS IN AUTOMOTIVE AFTER-MARKET was theme of MOTOR AGE Editor Frank P. Tighe's recent address before New Jersey Automotive Trade Association... He stressed importance of personal contact with car owner by car dealer management... "The car-owning public can be sold a variety of replacement items and repair work.... What is needed is for the car dealer's service personnel to put on a smile when they put on their shop coats."

Creeping In Cars With Automatic Transmissions Stopped

HOW TO ELIMINATE CREEPING in automatic transmission when car is idling in gear? This has long been a problem... Now one company comes up with a device which it says will solve this.

Developed by Gaylord Products, Inc. of Chicago, device, says the Company, maintains pressure in brake lines when car comes to full stop.... Pressure is released when the accelerator is pressed.... Several car companies reportedly are showing interest in Gaylord device.

Imports Face A Dismal Future

LOOK FOR MORE IMPORTS TO PULL OUT of U.S. market.... Things aren't getting any better for foreign makers.... Many are resorting to price cuts.... Also high bonuses to dealers.... Many extra cost equipment items are being thrown in as buyer incentives.

Import sales in July were the worst in three years.... Sales for year may plummet to 350,000 units.... Compared with a record 609,000 last year.... Even best-selling Volkswagen is headed for trouble, some observers say.... Dealers note a growing number of VWs at auction lots.... VW trade-in value is slipping, too.... No. 2 Renault also has been skidding....

Price Stability In The Auto Industry?

AUTO INDUSTRY HAS HELD LINE on car prices.... Actually, average industry decrease in prices is just a shade under those for 1960 models.

Some prices are unchanged.... Some have decreased slightly.... Others are up a bit.... But it all amounts to a general price decrease.... Prices were reduced substantially on certain high-price makes.... But at the same time certain standard equipment items were removed.... They are now extra options.... In other cases, equipment was added, but prices weren't changed.

Sharp Business Upturn Predicted

LOOK FOR HEALTHY BUSINESS UPTURN.... It will bring sharp economic raises in some areas and industries.... Should be evident in next few weeks, according to new economic forecasts... Upturn will start with a surge of consumer spending following pre-election hesitancy.... This will lead up to record Christmas sales.... Early next year, momentum will carry into basic industries—steel, aluminum, machine tools.... Then another solid upturn will be underway.

Sales response to 1961 models in October reinforced this belief.... Government forecasters expect sales of compacts to approach 50 percent of all new-car sales as a result of some carry-over spending reluctance (instead of 40 percent predicted earlier)... They also expect spending for repairs to older cars to creep upward in areas which won't feel economic improvement right away.

Compact vs. Standard Car

HOW HAVE THE COMPACT CARS FARED in fleet operations so far? Some indication of their performance comes from Lee Associates, fleet leasing consultants.... A Ford Fairlane 6 and a Falcon 6 were compared.

The results: it costs $8\frac{1}{2}$ mills per mile, or less than a penny a mile, to operate the Falcon than the Ford Fairlane... Total operating cost per mile for Falcon amounted to 2.7¢ compared with 3.55¢ for Ford Fairlane... Largest savings occurred in cost of gasoline and oil... With Falcon registering 22 mpg compared with 15 for Fairlane in stop—and—go city driving.

Difference in maintenance cost was very insignificant, according to Lee's records.... Maintenance savings on Falcon, including greasing and washing, amounted to a mere half mill per mile... An additional half mill per mile savings was realized on tires, including replacement costs.

Ford's Small Car May Be Built In U.S. And Europe

HERE'S LATEST TIP ON FORD'S UPCOMING VOLKSWAGEN-TYPE CAR, tentatively named the Cardinal... Reliable reports say two sets of dies are being readied in Germany.... This leads to obvious conclusion that Cardinal will be made in Europe and the United States.

Car may initially be built at one of Ford's plants overseas to keep costs down.... Then imported here.... However, because of strong pressure from the union, Ford may decide to build the car in the U.S.... Later may produce a similar version abroad for its market there.

Servicing Cooling System On Cars With Aluminum Engine

CAR COMPANIES ADVISE TO USE CAUTION in maintaining the cooling system on cars with aluminum engines.... American Motors suggests using permanent type antifreeze specifically recommended by manufacturers.... Alcohol base anti-freezes should not be used in an aluminum engine, AMC's service department cautions.

AMC says coolant solution should be drained and replaced each year for effective protection... Many radiator cleaners contain strong chemicals... They should not be used in aluminum cylinder blocks... Proper precautions should be taken to protect engine against corrosion... Use of water containing chlorides in excess of 100 parts per million should be avoided.

Income Of Auto Repair And Service Firms Up

TOTAL INCOME OF AUTO REPAIR, service, and vehicle rental firms almost doubled between 1954 and 1958.... Rising from \$2.2 billion to \$3.9 billion.... This was largest increase in receipts of any branch of the service industry, according to new figures from U.S. Census Bureau based on its latest business census.

In same four-year period, number of firms in the category rose from 94,342 to 125,240.... Auto and truck rental service portion reported that receipts doubled.... From \$300 million in 1954 to \$600 million in 1958.

Comparison of New Cars With 1960's Models

NOW THAT THE '61'S ARE HERE, how do they stack up against 1960 models? Average wheelbase of all 1961 cars has been trimmed to 117.9 inches.... Compared with 120.6 inches last year.... Overall lengths have been cut from 210.9 in. to 204.7 in.

With addition of many economy engines, horsepower ratings really took a dive.... Average horsepower on 1961 cars dropped to 214.5 from last year's average of 248.... Chrysler's 413 cu. in. engine leads industry with a 350 HP rating.... Corvair's 80 HP job is the smallest.

Government Promoting Car Redesign For Safety

U.S. PUBLIC HEALTH SERVICE distributing article by Roswell Park Memorial Institute contending highway deaths could be cut in half by changing auto design.... Suggested are: Installing a strong "bolt action" door lock and a sealed governor set at 70 mph; eliminating "hard top styling" to return to strong top supports; redesigning truck rear structures to prevent new low cars from running under them; removing all pointed objects from interiors.

Compacts Easy To Service

SERVICING OF THE FOUR NEW COMPACT CARS presents no great problems....
They're simple to work on, in most cases.... The number of special new tools that dealers and garages will need has been kept at a minimum.

Outlays for new tools range from \$279 for Dodge Lancer to \$356 for Pontiac Tempest.... That's cheap, considering cars are completely new from bumper to bumper—new engines, transmission, axles, etc.

Service departments are trying feverishly to hold tool costs down.... Engineers are constantly coming up with designs that simplify servicing... There's a closer liaison between engineers and service people than ever.

Students Make Good Customers

STUDENTS CONTINUE TO RISE IN IMPORTANCE as customers for service, accessories, fuel, and other sales as their number increases... This fall, some 48.6 million persons will enter schools and colleges... 10.2 million of which are in high schools and another 4 million are in colleges and universities... Number of students who drive is still rapidly increasing, government school experts say.



WHO WILL HIT THE JACKPOT?

THE cup of confusion runneth over. When car factories announced the 12,000 mile or 12 months new car warranty everybody...factory, dealer, and buyer suddenly got \$ marks in their eyes. Now no one seems to know whether it is a plague or a promised land.

The National Automobile Dealers Association has called on factories for a spelling out of the 12-12 warranties. The NADA Board has said that there are numerous misconceptions on the part of the public regarding what the new warranties provide in parts replacement, repairs and maintenance.

NADA's announcement pointed out that numerous inquiries have indicated that new car buyers do not understand that the warranties only apply to the workmanship, performance and the parts assembled at the factory level which may subsequently prove defective and require replacement.

Dealers have had to explain that the manufacturers' warranties do not cover ordinary maintenance, care or repairs required as a result of normal operation. routine wear or owner neglect.

One dealer was asked to replace a front fender after the owner had skidded into a pole. The warranty, of course, didn't apply. Nor does it to such items as tires, batteries and other units covered by separate guarantees. Meantime, back at the factories, there is little inclination to talk about the warranties. It is expected that it will take about three months to iron everything out. (And, if the owner has any problems within that period, he is still covered by the old 90-day warranty.)

A top Independent Garage Owners of American spokesman said that he expected little difficulty with the 12-12 warranties. "Car owners come to us for service, anyway." The new car buyer will be inclined to take his car back to the dealer during the warranty period but for satisfaction and service they end up with us anyway. If the owner wants the right kind of service they'll have to take it to the independent and pay for it." There's enough in the jackpot for everyone.

¶ The IGOA spokesman sounded a little disgruntled. He had bought a new car and was having trouble with his selling dealer at the time. \blacksquare If the 12-12 warranties mean the continuing improvement in Quality Control at the factories, much good will be accomplished.

Faithfully yours,

Frank Plighe.

TRUCK HIGHLIGHTS

A round-up of the host of items in the 1961 new truck picture



Above: Dodge Power Wagon.

Right: Corvair 95 Rampside pickup.



AKING a look alphabetically at some of the truck highlights for 1961, we can start with Chevrolet:

Refinements in the highly successful chassis design introduced a year ago, further expansion of models, and styling identification changes mark the Chevrolet truck line.


New cab features for 1961 emphasize a lower and narrower floor tunnel on most light-duty models for improved foot and leg room with the 3-speed or Powerglide transmission.


Included in the 1961 line are three new 4-wheel drive models for light-duty, maximum traction application. The 127-inch wheelbase, ½-ton vehicles are available as cab-chassis, wide-box pickup and conventional box pickup models rated from 4900 to 5600 pounds gross vehicle weight.

Chevrolet also has introduced the "Corvair 95"—a new series of short wheelbase, rear powered, light-duty trucks. With a 95-in. wheelbase and short overall length of less than 15 ft., it has a short turning radius and

for 1961

by the Editors of Motor Age





Transtar by Studebaker available as chassis-cab, platform or with stake type bodies.

is highly maneuverable in and out of traffic.

Comprising a panel delivery and two pickup models, the "Corvair 95" line incorporates innovations for easy loading and cargo accessibility. One of the pickup models has a unique, swing-down, side-loading ramp.


A stylish new Dart half-ton pick-up and two new economical 6-cylinder engines highlight the 1961 line of Dodge trucks. In announcing the new line of trucks, Dodge emphasized the passenger car styling and handling characteristics of the Dart pickup and the exceptional fuel economy to be derived from the slant-6 engines.

A new drop center frame, coupled with balanced design suspension and wide treads, it is said, gives the Dart "remarkable road stability and makes it as easy as a passenger car to drive."

Standard on the Dart pick-up is a 140horsepower, 225-cubic-inch, overhead valve 6-cylinder engine inclined 30 degrees. The slanted engine makes possible a low hood Continued on the next page

1 - 0

The White Motor Company's PDQ features a new "M" Series for delivery of milk and dairy products. It has a unitized insulated fiberglas sandwich body.



Cutaway of the 1961 Dodge truck 140-horsepower 6-cylinder engine. Modern casting techniques re-duce section thicknesses and weight.





The 1961 Champ by Studebaker features passenger car type instrument panel, safety cone steering wheel and a wrap-around windshield. It is suitable for routine jobs and heavy duty work.



Ford's 1961 light-duty F-100 Styleside pickup features a new type integral cab and body. Choice of 135-hp 6 or 160-hp V-8 engines.



1961 Chevrolet Corvair 95 Truck has an easily removable floor panel for access to 95 engine for tuneup and adjustment operations.

height and helps make for easy servicing.

This engine produces 215 lb.-ft. torque from 1,600 to 2,800 RPM. Its maximum RPM is 3,900.

Ford's new 1961 truck line marks the greatest commercial vehicle expansion in Ford Motor Company's 58 year history. More than 100 heavy duty, diesel and gasoline powered trucks have been added to the Ford line for 1961.

Ford also will have a wide selection in the economy pickup field with three completely different models—the conventional F-100 pickup on wheelbase of 114 and 122 inches, the passenger-car-styled Falcon Ranchero on a 109.5-inch wheelbase and the cab-forward

Econoline Pickup with a short 90-inch wheel-base.

Pick-up, Van, and 8-passenger Station Bus models represent the Econoline Series of light commercial vehicles introduced by Ford. Mounted on 90-in. wheelbase, these vehicles employ Falcon chassis components with the 144.3-cu. in. 6-cylinder engine standard.


The 12-volt electrical system uses components from other Ford vehicles, with a 25-amp. generator standard, and a 30-amp. low cut-in generator and regulator optional. Electrical components associated with the engine are located under the engine cover for accessibility.

Continued on the next page



GMC Junior Van, only 14feet long was one of the featured displays at the Auto show at Cobo Hall, Detroit.

Ford's engine cooling air comes in through the front grille with ducts to radiator on Econoline series.



Ford's new Econoline series pickup with many components from the Falcon included.



A colorful lineup of trucks, ranging from the compact GMC Junior Van to various heavy-duty highway tractors, appeared in the GMC Truck & Coach Division exhibit at the 43rd National Automobile Show. Trucks included a Suburban station wagon, GMC Junior Van package delivery truck, a Wide-Side pickup, a DF7105 aluminum tilt-cab diesel high-way tractor, a BW5500 tandem-axle tractor powered by a 401 V-6 engine, and an L7000 steel tilt cab tractor.

The smallest model was the Junior Van, a unit shorter than American-made compact cars yet having the bulk load capacity of a one-ton stake truck.

The Studebaker line of trucks includes the new Champ pickups, first introduced in February, 1960, and the Transtar series of medium and heavy duty vehicles.

With its new concept in pickup truck design, the Champ combines an attractively-

styled, comfortable cab with the functional strength of a solidly-built, rugged truck. These well-equipped cabs are mounted on a strong, highly-rated chassis. The sturdy frame assures rugged, long life.

For 1961, the Champ features a new 170 cubic six cylinder overhead valve engine.

The White Motor Company's Reo Division has a new V-8 truck and tractor series with a 90-inch bumper-to-back-of-cab measurement. All models in the D-600 and D-700 series are powered by Reo's Gold Comet V-8 gasoline engines.

The series consists of six models: two single axle tractors with GCW ratings of 65,000 and 78,000 pounds: two tandem axle tractors with GCWs of 70,000 and 78,000 lbs. and two tandem truck models with GVW ratings of 42,000 and 52,000 lbs. respectively.

(Part Two of the 1961 Truck Highlights will appear next month.)



Slip ring and silicon end housing showing method of tieing down brushes prior to assembly of rotor. Light wire or string can be used. Cut and remove when done.

Alternator Service Is Easy and Profitable

New step-by-step procedures for profitable Service

By T. J. McCabe, Service Editor

Remove slip ring end housing screws after removing metal dust covers that direct air to heat sinks.



N recent issues of Motor Age we have covered the basic theory of operation on the alternator. Moreover, details of service and theory on other components such as voltage regulators, selenium and silicon rectifiers have been fully covered.


Continued on next page

Use a screw driver to pry out bearing dust cover and use caution not to damage the alternator casing.






Use a suitable puller or as shown above, a brass drift and hammer against rotor shaft to separate.



After separation, pry apart drive end housing and rotor assembly. (Pulley removed conventionally).

View of slip ring and brush housing with silicon rectifiers on left, stator assembly on the right.



Alternator Service CONTINUED

The alternator as we know it in the automotive field, has been used to produce large amounts of current since 1945. It was reportedly first introduced by the Leece-Neville Company, in conjunction with the military, as part of a joint war effort. The alternator has since increased in use and popularity throughout the years in many fields of industry.

Alternators can be found in use on trucks, buses, marinecraft, railroads, and in 1961 will be standard equipment on one automobile manufacturers complete line of cars and trucks. Because of its simplicity of design and rugged construction, maintenance problems will be kept to a minimum. As for service, you'll find it very similar to a conventional generator, both as to assembly and disassembly. As for testing, the same instruments are used that you now have on hand. Just keep in mind that when checking voltages from the alternator stator terminals that the current is alternating, thus a D.C. voltmeter cannot be used. However, there is no need for a voltmeter when testing at these points, just use a test lamp as covered later in this text.

With no special tools required to service the alternator, they really are a simple and profitable service item. Most important, however, is that you must bone up on more theory and practical training on the new alternators. Contact your jobber about the many alternator service clinics that are now run very frequently each year in your area. Much time and effort is put into this training program by everyone concerned. This is done so that you will have available the kind of profitable service training you need to keep alert and prosperous in an ever changing age of motoring.

Trouble Shooting:

Two conditions usually indicate some fault

Any suitable puller arrangement can be used to remove rotor bearing and slip ring assembly.

in the charging system. One is that of an under-charged battery. The other an over-charged battery. The first thing to check under any of these conditions is the battery itself. Use the procedure recommended by the battery manufacturer in making a battery test. Test cell-by-cell voltage. Check each cell with a hydrometer for specific gravity. Then make an overall voltage and load test. After checking battery condition, next check the alternator drive line.

Test for slipping drive belt: Try to turn fan of alternator with one finger. If it can be turned then its too loose. Adjust as required. In checking belt, look for incorrect pulley or belt. Worn belt or pulley. Glazed belt or pulley. Finally check for misalignment of drive and driven pulleys. If belt is glazed, replace it. Readjust belt after a few minutes running to correct for belt seating and stretch.

Over-charged Battery Or High Charge Rate:

With the above conditions; check for high voltage regulator setting. Use a test light or voltmeter and check the ground circuit of voltage regulator and alternator. Remove regulator cover and check for burned-out jumper wire from voltage regulator bottom contact to ground. Check for open circuited regulator coil.

Discharged Battery Or Low Charging Rate:

Check for low voltage regulator setting. Remove regulator cover and examine jumper wires in regulator field circuit for open's. Check for correct wiring from ignition switch to regulator ignition terminal. Remember, some vehicles have a resistance built into the ignition switch or primary wire. This will affect the voltage delivered. Make sure that battery voltage is being supplied to the "IGN" terminal of the regulator. The alternator doesn't utilize residual magnetism for initial Continued on page 82






When soldering leads to silicon rectifiers keep iron contact with rectifier to the minimum.




After pressing on collector ring and soldering field coil leads true-up on lathe.



Test silicon rectifiers using test lamp. Lamp lights in only one direction.



Using extension hose to sniff air conditioning compressor shaft seal for leakage.



The electronic probe will flash red should a leak be indicated in the radiator top tank.

DETECTING system leaks ELECTRONICALLY

Halogen leak detection techniques and their automotive applications

By Warren C. Hutchins, Manager Application Engineering, General Electric Co., Instrument Dept.

THE objective of this article is to provide the serviceman with information on leak testing equipment, Techniques will be discussed. Profits to be derived from pinpointing leaks during automotive service will also be mentioned.

First, let's take air conditioning units. Service shops that repair air conditioners are often alarmed at the cost of locating and repairing leaks. Too frequently the leak is not located. The irate customer returns again to demand better service.

Usually the loss of only 8 or 10 ounces of refrigerant reduces cooling capacity to where the customer should return for service. Three or four leaks, each at a rate of only 5 or 6 ounces per year, means the unit will need recharging in a few weeks. If the customer must return for service more than once a year, he may go elsewhere.

There are two main types of detectors available for locating leaks of R-12, R-22, and R-114. The halide torch was for many


Continued on page 100




Sniffing exhaust with electronic probe leak detector. Flash of probe indicates water seapage.



All connections can be probed to detect leaks of 1/2 ounce per year seapage of refrigerant.





Setting sniffer to desired rate of leak detection sensitivity by use of Halogen Leak Standard.



Charging tubeless tire with F-12 and using Halogen probe, slightest leak can be detected.

Winterizing Check-ups Spur Sales & Service

Your shop or station should be promoting winterizing services and repairs. All cars should be checked and repaired to insure trouble-free driving this winter

By William M. Montgomery, News Editor

HE cold months are here: Have you been promoting all your winterizing sales and services? This is the time to "turn on the heat" not only in your garage, but on pulling in your customers for winterizing services. Before the snow and ice appear, all cars should be checked over to be sure that they are safe for driving in the coming months. Items that are checked may become a profit sale for you. Don't miss this excellent opportunity to sell your sales and services.

Motorists should be urged to have their cars checked thoroughly. Here are major areas that the mechanic should inspect in a winterizing checkup. Check the battery for condition and charge. The battery has more troubles during the winter because voltage drops with the temperature. It must always be fully charged. Connections must be tight. Corrosion can be discouraged by removing film on the battery case with a solution of water and baking soda.

Look the exhaust system over very care-Continued on page 86 BRAKE CHECK STICKER—One way to make extra profits is to put a sticker next to the oil change sticker. It should state when the brakes were last relined or adjusted. You can then check the brakes regularly and charge for each adjustment. Also you can tell the customer when it is time for new lining before the drums are scored or a brake failure occurs.





COFFEE BREAKS—This is the sales technique that I use. Every morning we have a coffee break at 10 a.m. This includes customers as well as our employees. It makes everyone a bit happier. I furnish all coffee, cream and sugar. The customer feels very satisfied for being treated so well while his car is being serviced. Mrs. Fred F. Wagner, Erie, Pa.



BRAKE PARTS DISPLAY—Convince car owners that brakes need periodic attention and replacement by using a brake display. Displaying a complete brake assembly that has been replaced after wearing to the danger point makes a very impressive exhibit. Place it where customers can see it. R. Blagden, East Hampton, Conn.

SPONSOR CAR WASH—You can help a local service club raise money and also increase your station's business by sponsoring a car wash. You provide the water, soaps and towels free. The customers that they will bring in may become your permanent customers. After their cars are washed offer them a 50-star flag with every lube job or oil change. Ted McFee, Drexel Hill, Pa.



GOODWILL BUILDER—Periodically we buy old clunkers and park them behind the station. We advertise that anyone can have any part for two bucks. That means a door, window, fender, etc. Our investment in the few old cars is well justified, thru the free advertising and new customers we get. Often we get to repair or install these parts. Henry Joseph, Sr., Gardenville, Pa.



For longer VALVE life check the old ones

Look'em over before you pitch them out. It can help get longer life from the next set

> By A. K. Hannum, Chief Engineer, Replacement Division Thompson Products and Toledo Steel Products, Thompson-Ramo-Wooldridge, Inc.

O, you've got an engine with bad valves!
Whether early failure or normal life, look these valves over before you pitch them out. They can help you answer the all-important question, "Why did these valves fail like they did?" When you know that, you'll get longer valve life.

Check the appearance of the old valves against the wear patterns shown here. You'll get a clue to what might need correcting to keep your new valves out of the junk box too early in their life. Be thorough. More than one picture might apply to your valve-failure problem.



APPEARANCE: Face burning USUAL CAUSE: Seat distortion CAN BE DUE TO . . .

· Block and head faces not flat or burr-free

Improper head-bolt torque

Dirty or blocked coolant passages

Improper torque or misfit intake manifold, especially on V-8's



APPEARANCE: Face and head burning USUAL CAUSE: Pre-ignition CAN BE DUE TO ...

Glowing combustion deposits because of incorrect fuel and/or lube

Spark plugs too hot or cracked
Valve edge too thin

 Detonation because of too-low-octane fuel and/or excessive spark advance

Excessive engine load

· Air/fuel ratio too lean




APPEARANCE: Face guttering (as shown) or Deposit flake-off (Valve shown has been cleaned)


CAN BE DUE TO . . .

• Inadequate seating force caused by weak spring, seating surface too wide, or no interference angle

Rotator inoperative or required

Unsuitable fuel





APPEARANCE: Face burning with carbon build-up on stem USUAL CAUSE: Sticking

CAN BE DUE TO ...

Worn or bell-mouthed guides

Missing or worn stem seals
 Over-lubrication

Unsuitable lube oil

MORE ON NEXT PAGE

VALVES . . .

CONTINUED






APPEARANCE: Circular face grooving CAN BE DUE TO . . .

• Self-rotation because of over-speeding

and/or weak springs

 Use of unleaded or "dry" fuels with valve or seat of incorrect material



APPEARANCE: Face peening USUAL CAUSE: Hard deposits CAN BE DUE TO ..

Unsuitable fuel and/or lube

• Too soft a face. Harder faced valve might be desirable



APPEARANCE: Pie-shaped breaks (as shown) or radial cracking CAN BE DUE TO ...

• Frequent, sudden changes in engine output

Abruptly shutting down engine after a high-speed run, not allowing valve to cool gradually
 Too light a valve for the work. Heavier

duty model might be desirable



APPEARANCE: Stem neck-down USUAL CAUSE: High-temperature erosion CAN BE DUE TO ..

Engine operation beyond normal output

 Air/fuel ratio too lean because of poor fuel distribution, faulty carburetion, leaking intake manifold

Incorrect spark timing at operating speed

Exhaust back pressure too high


Stuck heat-riser valve

Too light a valve for the work. Heavier duty model might be desirable




APPEARANCE: Stem fatigue break. Note curved lines radiating from point where break began CAN BE DUE TO . . .

- Face or seat off-square or run-out
- Seat distortion because of block and head faces not flat or burr-free, improper head-bolt torque, dirty or blocked coolant passages, improper torque or misfit intake manifold especially on V-8's
- Excessive stem-to-guide clearance
- Bell-mouthed guides
- Distorted or cocked valve spring



APPEARANCE: Stem impact break. Note (1) how lines in enlarged cross-section view differ from those at left and (2) the "step"-type break CAN BE DUE TO...

- Excessive tappet clearance
- Over-speeding and/or weak springs
- · Worn, starved, or stuck hydraulic lifters
- Excessive spring pressure
- Valve sticking open and being hit by piston
- Broken seat insert
- Foreign pieces between face and seat



444

APPEARANCE: Head cupping USUAL CAUSE: Excessive heat CAN BE DUE TO ...

- Engine operation beyond normal output
- Air/fuel ratio too lean because of poor fuel distribution, faulty carburation, leaking intake manifold
- Incorrect spark timing at operating speed
- Exhaust back pressure too high
- Stuck heat-riser valve
- Too light a valve for the work
- Insulating effect of face deposits
- Excessive stem-to-quide clearance
- Valve and/or seat not ground properly, leaving too much of valve head in combustion chamber
- Reversed interference angle
- Valve springs too strong or wrong height
- Excessive valve lash



PHOTOGRAPHS SELL body shop services

Investment in a picture-in-a-minute camera has resulted in increased work volume and profit for this body shop

estimate on body work necessitated by an accident, we take along our "instant" camera," says Ellsworth G. Pritz, owner of Pritz Autobody and Radiator Service, York, Pa. "We snap a picture of the damages estimated on the car. Then we attach this to the estimate that we give the insurance adjuster or insurance company. Because our estimate charges can be compared to the attached photograph, the adjuster seldom tells the motorist to hunt around for more than the single estimate on the car. As a result, we get the jobs more quickly."

Pritz points out that operating the picturein-a-minute camera is simple. Any employee sent to estimate on a job can handle it. The photographs are also used by the shop in preparing estimates when someone other than the shop owner or his service manager goes out to estimate on a job. In addition to the written report of all the necessary repair work required on the car, several pictures taken from different angles adds a more comprehensive description of the body work necessitated on the car. The combination of the report and the photographs, therefore, offers the shop owner or his service manager a better opportunity of estimating the cost or repairs to the particular vehicle.

"We take photographs of cars that are brought in for our own files as well," says Pritz. "Whenever we realize that a motorist does not intend to fix the necessary damage at an early data because of personal or legal reasons, we always take a picture of the damages that we have estimated. We attach it to the duplicate estimate that we have and file it."

"If the motorist brings his car in to have the work done, we may notice that it requires more work than was originally noted on our estimate. We not only have the duplicate estimate to show the customer but also a photograph of the damages that we originally estimated. Suppose he should have more damage



Ellsworth Pritz, owner of the body shop takes a picture of customer's damaged car. Photo will be kept as a permanent record of damage.



Picture-in-a-minute camera is easily handled by any shop employee who is sent out to estimate autobody damages.

to his car than was originally there when he first came in? We can point out to him that this was not part of the original estimate when he made his initial visit here."

The shop also uses the camera to take before-and-after pictures of work that has been done. It posts them on a bulletin board where motorists can see them. He uses these pictures to point out the quality of his workmanship to customers who are discussing different repairs on their cars. Almost every type of damage and wrecked car has been pictured in this shop. The "after" photographs show the quality type of workmanship that is done here. As a result, the shop operator has found these before-and-after pictures to be "salesmen" for his services.

Pritz also places before-and-after pictures of all work done on cars in folders which he gives to the car owner. An imprint on this folder gives the complete name and identification of this shop. All who review these (Continued on page 76)



One minute after picture is taken it is removed from the camera. It can be sent to the insurance adjuster or kept on permanent file.

Here is the picture that was snapped by Ellsworth Pritz with his camera.





IGO of North Carolina had a splendid turnout for their recent annual convention. Bryan Davis, known for his enthusiastic travels through North Carolina on behalf of IGO, retired as president. George Miller took over as the new prexy of IGO of N.C. From left: Charles Barnes, vice president; Harold Smith, vice president; J. L. "Roy" Orr, secretary-treasurer; Davis; and Miller.

I G D

Pictorial report on some of the happenings in IGO units around the country

... by W. H. Wolfe, Managing Editor

A very active IGO group is the IGO of Metropolitan Denver. Officers that are serving for 1960 are shown here. From left to right, back row: Gerald Davis, vice pres.; Ross Gentzler, treas.; James Kientz, sec. Seated, left, is Frank Carmichael, immediate past pres.; and Dick Jones, pres. (right).



One of the highlights of the IGO of Kansas state convention earlier this year was the election of officers. Mel Norris was re-elected pres. Other officers of Kansas, front row—left to right: Herman Stiles, 2nd vice pres.; Norris; E. E. Sanders, 1st vice pres. Standing, left, is Al Greiving, treas.; and Roy Corfman, secretary, all of the Independent Garage Owners of Kansas.

Below: Installation of highway signs has been a national project of IGO of America this year. Below, Officers of the Northwest Louisiana Unit in Shreveport look over one of the highway signs. From left: Edgar Bland, sec.-treas.; Monette Bowman, pres.; Worth Hodge, vice pres.; and Maj. R. L. Drake, Shreveport Police Dept.







Connecticut formed a state association of IGO recently. Officers grouped around an IGO plaque are from left: Alexander J. Morris, pres.; Joseph Dastoli, 1st vice pres.; Alexander Zavatsky, treas.; Howard Temple, sec.; and Donald Fantozzi, 3rd vice pres.

What to look for when you run into TROUB

Troubleshooting Engine Bearings Failures

By William M. Montgomery

The Problem

Worn Bearings

Look for:

a. Low oil pressure b. Faulty oil pump

c. Dirty oil

d. Crankthrows out-of-round

e. Ridged & scored journals

f. Insufficient oil clearance

g. Oil starvation

Bearing failure

Look for: a. Diluted oil b. Lack of oil c. Faulty oil pump

Bearing improperly seated

Look for:

a. Dirt between bearing back & bearing seat

b. Filed parting faces c. Filed bearing caps

Connecting rod misalinement

Look for:

a. Bent or twisted connecting rods

Crankshaft troubles

Look for: a. Warped or distorted crankshaft b. Ridged & scored journals

c. Crankpins & journals out-of-round

Excessive bearing clearance

Look for: a. Undersize bearing b. Excessive oil throw-off c. Loss of oil pressure

Low or no oil pressure

Look for:

a. Insufficient oil in crankcase

b. Broken oil line

c. Broken oil pump d. Blocked oil suction screen

e. Broken or plugged oil passage

f. Broken pressure relief valve springs

g. Badly worn bearings

1960 New Passenger Car Registrations*

| STATE | Buick | Cadil- iac | Chev- rolet | Chrys- ler | Comet | De Soto | Dodge | Ford | lm- perial | Lin- coin | Mer- cury | Olds- mobile | Ptym- outh | Pon- tiac | Ram- bier | Stude- baker | All Others | Total |
|--|----------------|----------------|------------------|---------------|--------------|--------------|---------------------------|------------------|---------------|--------------|---------------|-----------------|----------------|----------------|---------------------|--------------------|----------------|--------------|
| Nabama | 228 2437 | 79 945 | 2018 | 54 578 | 200 1151 | 22 203 | 285 2899 | 1450 13302 | 15 124 | 11 | 114 1255 | 276 2962 | 331 3115 | 379 3231 | 307 3184 | 73 744 | 573 5096 | 863 |
| laskaAug. | 7 54 | 8 75 | 38 785 | 8 55 | 9 38 | 16 | 8 76 | 62 725 | 3 25 | 12 | 11 58 | 10 70 | 57 406 | 10 143 | 23 186 | 7 09 | 107 681 | 34 |
| ArizonaAug. | 84 824 | 102 796 | 986 7119 | 46 223 | 103 543 | 5 78 | 199 | 629 6244 | 17 | 17 | 74 | 157 1322 | 266 1914 | 230 1769 | 320 2436 | 92 490 | 343 2891 | 367 |
| ArkansasAug. | 143 | 64 526 | 1239 9037 | 29 225 | 120 | 14 | 160 | 989 7732 | 6 47 | 6 87 | 90 797 | 190 1733 | 217 1653 | 254 1854 | 206 1542 | 53 456 | 238 1840 | 400 306 |
| CaliforniaAug. 8 Mos. | 1142 | 1515 11807 | 10727 96184 | 458 3906 | 1534 9192 | 1032 | 2600 20807 | 9955 93475 | 146 1145 | 129 1716 | 966 9380 | 1917 16515 | 3672 29431 | 2385 20619 | 3592 29029 | 898 7255 | 6297 50640 | 4803 |
| ColoradoAug. 8 Mos. | 152 1441 | 79 778 | 1458 11174 | 53 479 | 123 765 | 14 | 213 2253 | 1000 9119 | 10 93 | 16 157 | 161 1123 | 260 2042 | 286 2585 | 312 2459 | 415 3157 | 118 856 | 300 2966 | 415 |
| Connecticut Aug. 8 Mos. | 142 | 139 | 1760 | 100 | 366 1519 | 30 | 425 | 1644 | 11 | 12 | 132 | 336 | 637 | 369 3540 | 780 5701 | 185 | 1000 | 80 684 |
| Delaware | 1745 46 | 1432 | 15738 591 | 1003 | 42 | 269 | 3818 | 12899 341 | 146 | 201 | 1588 42 | 2984 92 | 5940 101 | 114 | 109 | 1555 | 8418 175 | 18 |
| District of Columbia Aug. | 419 65 | 339 67 | 4109 708 | 145 | 186 | 74 | 871 114 | 2618 420 | 19 7 | 9 | 277 | 123 | 1108 | 855 143 | 739 168 | 222 | 1400 340 | 141: 25 |
| lorida | 432 500 | 572 512 | 4896 3744 | 328 149 | 296 548 | 44 | 1022 | 3358 3425 | 74 48 | 101 | 332 264 | 978 719 | 1879 | 1103 798 | 1243 1015 | 263 191 | 2355 2558 | 1921 |
| icorgiaAug. 8 Mos. | 4846 178 | 4467 96 | 37122 2249 | 1256 43 | 2615 | 435 | 5320 277 | 30631 1734 | 452 | 767 28 | 2560 103 | 296 | 9245 444 | 6913 487 | 331 | 2198 72 | 677 | 720 |
| lawaii | 3049 50 | 1422 23 | 24883 423 | 735 | 1094 32 | 279 | 3509 81 | 20924 | 126 | 211 | 1474 | 3670 37 | 5198 193 | 6231 35 | 3814 | 1191 | 10165 305 | 878 15 |
| dahe | 249 83 | 178 37 | 3048 379 | 142 | 134 | 11 8 | 558 102 | 2449 254 | 18 | 13 | 99 40 | 283 88 | 1783 104 | 286 120 | 471 183 | 242 38 | 2483 140 | 124 |
| Ilinois Aug. | 627 1388 | 362 870 | 3221 10363 | 177 362 | 251 1163 | 64 | 903 1882 | 2674 6428 | 45 62 | 123 | 377 711 | 792 1866 | 862 1868 | 1026 2737 | 1423 2442 | 307 552 | 1126 | 1425 3456 |
| 101VI 8 | 15141 511 | 7884 222 | 88087 3049 | 3827 96 | 5900 289 | 1086 42 | 17304 | 58349 2384 | 756 24 | 1345 27 | 7216 211 | 18483 729 | 17886 538 | 24189 729 | 19426 667 | 5250 390 | 15254 588 | 3071 |
| 8 Mes. | 6242 289 | 2488 119 | 35072 2261 | 1319 | 2016 | 643 29 | 7350 378 | 25613 1918 | 285 | 398 16 | 3063 180 | 8192 396 | 7580 467 | 8768 373 | 7538 579 | 4085 101 | 5653 287 | 1262 76 |
| 8 Mos. | 2429 | 838 | 16369 2243 | 831 67 | 1006 | 239 | 3286 371 | 12622 1710 | 84 12 | 109 | 1625 163 | 3017 | 3774 422 | 3279 383 | 4023 493 | 895 128 | 2306 354 | 564: 73 |
|)8 Mas. | 2577 232 | 925 91 | 16395 1549 | 565 39 | 813 151 | 197 | 3070 241 | 13367 1232 | 100 | 167 | 1336 116 | 3020 281 | 3360 397 | 3463 329 | 3865 408 | 1027 58 | 3224 369 | 574 55 |
| Contucky | 2096 253 | 691 134 | 14392 2518 | 365 64 | 914 239 | 195 14 | 2561 250 | 11128 1713 | 73 | 101 | 1144 153 | 2622 438 | 3368 286 | 3139 560 | 3068 359 | 677 76 | 2881 521 | 496 76 |
| 8 Mos. | 2257 | 1065 | 19222 | 505 13 | 1077 | 206 | 2319 | 15095 448 | 120 | 141 | 1262 | 3618 | 2780 129 | 4541 97 | 2803 171 | 710 | 5834 236 | 635 |
| MaineAug. 8 Mos. | 685 | 331 | 502 5061 | 194 | 378 | 102 | 1011 | 4485 | 26 | 40 | 522 | 64 692 | 1523 | 1080 | 1892 | 408 | 2189 | 19 216 |
| MarylandAug. 8 Mos. | 276 2521 | 150 1336 | 3474 24017 | 138 1002 | 274 1321 | 38 406 | 746 5342 | 2578 17014 | 160 | 14 | 134 1456 | 434 3286 | 7440 | 4287 595 | 793 5435 1480 | 160 1236 | 977 6940 | 116 834 |
| Massachusetts Aug. 8 Mos. | 434 4150 | 244 2502 | 3508 27781 | 153 1586 | 475 2134 | 50 590 | 747 7289 | 3157 24124 | 19 265 | 48 450 | 2638 2638 | 686 6291 | 992 9379 | 5828 | 11197 | 253 2003 | 10774 | 143 |
| Alichigan Aug. 8 Mos. | 14077 | 594 6350 | 8482 78860 | 288 2689 | 1554 8204 | 76 1186 | 1657 19435 | 7801 71494 | 37 612 | 140 1079 | 764 9737 | 1662 16393 | 1994 20376 | 2082 21438 | 1548 14746 | 283 2764 | 1987 12892 | 323 3021 |
| Immeseta Aug. 8 Mos. | 442 | 146 1565 | 3014 23770 | 137 1113 | 371 1553 | 37 407 | 533 5201 | 2440 18516 | 175 | 267 | 247 | 739 5597 | 752 6895 | 678 5725 | 892 6230 | 226 1896 | 554 4450 | 112 897 |
| Aississippi | 158 1425 | 50 400 | 1201 9058 | 33 270 | 76 383 | 10 | 106 1088 | 731 8652 | 34 | 53 | 58 542 | 208 1804 | 193 1724 | 233 1843 | 169 1298 | 43 448 | 219 2029 | 35 291 |
| Missouri | 513 3956 | 304 1973 | 4922 32609 | 128 950 | 369 1503 | 46 384 | 1110 6836 | 3393 23957 | 17 201 | 27 235 | 223 1964 | 780 5332 | 901 6789 | 1007 6346 | 1150 6723 | 152 1243 | 800 5866 | 158 1068 |
| Montana Aug. | 83 761 | 32 340 | 499 3927 | 20 141 | 80 294 | 10 70 | 152 | 408 3330 | 46 | 5 47 | 64 528 | 108 858 | 115 982 | 114 779 | 159 1175 | 29 314 | 133 1049 | 19 |
| NebraskaAug. 8 Mos. | 126 1300 | 80 673 | 1314 10558 | 65 400 | 93 476 | 11 129 | 272 2418 | 1084 8313 | 8 62 | 5 58 | 107 913 | 229 1817 | 215 2073 | 203 1929 | 349 2497 | 61 519 | 185 1507 | 44 356 |
| Vevada Aug. 8 Mos. | 32 174 | 35 231 | 199 1483 | 21 100 | 43 180 | 2 27 | 64 379 | 207 1448 | 31 | 10 | 36 334 | 50 349 | 71 484 | 91 540 | 80 508 | 16 149 | 173 1221 | 11 |
| New Hampshire Aug. 8 Mos. | 66 514 | 38 262 | 578 4601 | 17 150 | 77 379 | 3 49 | 102 1004 | 434 3576 | 26 | 4 50 | 46 456 | 71 614 | 116 | 79 714 | 205 1649 | 58 540 | 292 2177 | 21 178 |
| New Jersey Aug. 8 Mios. | 607 6403 | 811 | 5187 | 361 | 801 | 80 | 1283 | 4089 33552 | 53 682 | 71 | 321 3862 | 936 9387 | 1484 14956 | 1153 11336 | 1884 13572 | 318 | 1820 | 210 |
| New Mexico Aug. 8 Mos. | 78 | 5558 | 45743 723 | 3671 | 3728 51 | 1061 | 12340 | 824 | 5 | 7 | 57 | 112 | 168 | 134 | 175 | 3268 41 | 15799 175 | 1856 |
| New Yerk 8 Mos. 8 Mos. | 631 1653 | 407 1386 | 5077 12640 | 249 844 | 310 2130 | 164 | 716 3156 | 4182 10423 | 53 133 | 45 162 | 459 830 | 1016 2804 | 1247 3964 | 1098 2888 | 1196 4477 | 359 996 8394 | 1546 5306 | 186 537 |
| North Carolina | 15722 354 | 12502 165 | 98149 2745 | 8061 | 8566 268 | 2009 | 28043 405 | 77043 2458 | 1329 14 | 1555 17 | 9134 138 | 24881 402 | 36144 588 | 25891 560 | 32131 413 | 137 | 39149 914 | 4287 96 |
| North Dakots 8 Mos. 8 Mos. 8 Mos. | 3289 58 | 1292 | 22341 373 | 763 24 | 1346 56 | 259 | 3347 93 | 20715 338 | 110 | 147 | 1443 46 | 3510 79 | 5080 105 | 4807 81 | 3526 116 | 1210 28 | 7200 61 | 801 14 |
| Ohio8 Mos. 8 Mos. 8 Mos. | 1263 | 192 526 | 3616 9453 | 234 281 | 278 1723 | 72 86 | 875 2168 | 3166 7015 | 33 71 | 33 | 493 738 | 1703 | 1014 2272 | 842 2256 | 2075 | 209 493 | 430 1744 | 133 336 |
| (8 Mos.) | 12403 | 5121 105 | 75750 1967 | 2897 55 | 8247 128 | 1275 12 | 20263 256 | 82498 1478 | 559 | 722 | 8103 120 | 15397 347 | 21022 258 | 19490 421 | 16544 395 | 4420 76 | 15741 255 | 2904 |
| 8 Mos. | 1883 114 | 932 | 14371 | 380 17 | 723 106 | 145 | 1935 223 | 11416 558 | 74 | 114 | 982 | 2832 118 | 2442 242 | 2970 192 | 2808 382 | 552 95 | 2273 412 | 488 |
| 8 Mos. | 1446 1134 | 671 679 | 10580 8241 | 346 448 | 806 1109 | 127 205 | 1934 2647 | 8713 6283 | 88 64 | 181 64 | 1015 545 | 1839 1336 | 2841 2486 | 2421 1897 | 4483 2617 | 1348 750 | 5437 2097 | 442 324 |
| 8 Mos. | 10350 | 6026 | 66961 492 | 4588 | 5357 81 | 1974 | 23464 | 49335 547 | 715 | 778 13 | 6338 | 12437 62 | 23412 215 | 15083 71 | 21226 253 | 6132 | 18226 | 2724 |
| 8 Mos. | 886 143 | 448 65 | 4280 1237 | 308 | 336 112 | 76 12 | 1063 | 4638 1081 | 54 5 | 62 | 363 56 | 737 | 1844 335 | 785 245 | 1965 250 | 338 | 2280 290 | 201 |
| 8 Mos. | 1471 | 542 27 | 10052 493 | 321 22 | 687 35 | 120 | 1616 | 9845 420 | 52 | 52 | 659 | 1507 | 2631 107 | 2075 87 | 1968 | 408 24 | 3680 67 | 385 16 |
|) 8 Mas. | 619 248 | 227 131 | 4121 2327 | 175 56 | 202 202 | 61 22 | 835 322 | 3568 1630 | 35 10 | 32 18 | 500 141 | 845 386 | 958 420 | 832 451 | 1037 442 | 289 | 653 | 149 |
| Tennessee | 2710 | 1109 590 | 19606 8688 | 484 197 | 1052 608 | 277 52 | 3178 | 14767 | 100 | 187 53 | 1257 381 | 3423 1704 | 3724 1394 | 4138 1749 | 3767 1371 | 984 | 518 4688 | 854 854 |
| 8 Mos. | 934 8882 | 4681 | 67548 | 1797 | 3187 | 577 | 971 851/ 133 848 | 5568 50705 | 530 | 568 | 3206 | 13056 | 11730 | 13532 | 10139 | 281 2847 | 1663 18818 | 262 |
| Jtah | 89 687 | 42 381 | 422 4078 | 238 | 60 422 | 12 132 | .048 | 390 3740 | 53 | 69 | 572 572 | 126 957 | 150 | 137 | 147 | 24 257 | 225 1640 | 182 |
| /erment | 47 395 | 147 | 325 2784 | 13 155 | 35 164 | 43 | 559 | 305 2435 | 19 | 21 | 248 | 306 | 102 877 | 34 440 | 121 700 | 42 315 | 242 1524 | 112 |
| /irginia | 414 3219 | 201 1442 | 3094 23569 | 126 955 | 380 1625 | 33 453 | 558 4564 | 2478 19584 | 21 168 | 20 241 | 199 1910 | 490 3752 | 7032 | 701 4988 | 507 4433 | 156 1456 | 1606 10003 | 119 896 |
| washingtonAug. | 211 1527 | 95 757 | 1065 9928 | 41 348 | 203 965 | 14 | 302 2231 | 1179 10443 | 8 76 | 10 138 | 122 1085 | 205 1790 | 374 2946 | 324 2664 | 565 4176 | 99 992 | 738 6210 | 58 464 |
| West Virginia Aug. 8 Mos. | 212 1456 | 65 506 | 1057 8784 | 41 413 | 128 566 | 155 | 233 1940 | 764 6692 | 5 67 | 11 79 | 99 | 174 1744 | 321 2841 | 253 1943 | 254 2112 | 78 611 | 273 1932 | 327 |
| Wisconsin Aug. 8 Mos. | 495 4946 | 220 1879 | 3136 26326 | 150 1139 | 358 1670 | 24 352 | 697 6415 | 2475 20825 | 18 171 | 27 286 | 248 2691 | 678 6391 | 559 5014 | 777 8813 | 1246 11912 | 176 1664 | 632 4450 | 111 |
| Wyoming | 68 475 | 22 208 | 324 2547 | 19 | 24 150 | 8 51 | 00 414 | 189 1861 | 3 26 | 3 28 | 31 264 | 58 543 | 75 724 | 87 574 | 83 724 | 19 175 | 97 833 | 11 91 |
| Total August, 1960 Total August, 1969 | 17837 17702 | 11135 10603 | 140595 138200 | 5629 5192 | 17708 | 1557 3865 | 28547 12486 | 110522 128665 | 1039 1194 | 1396 1794 | 9822 12691 | 25359 29078 | 34498 34407 | 30654 34494 | 37482 33237 | 8426 10416 | 43194 59812 | 525 533 |
| | 172509 | 96382 | 1175554 | 52791 | 87169 | 18248 | 256857 | - | - | - | - | - | - | 271515 | - | - | - | - |

^{*} Compiled from official state records. Data property of R. L. Polk & Co. May not be copied, sold or reprinted without Polk permission.

1961 Tune Up—Alignment Specifications

All models shown are 1961 Production Models with the exception of Rambler, Superba, Comet, Falcon, Ford, Lincoln, Marcury and Cadillac which are 1960 Production Models.

| | | EN | GINE | | | TU | NE-UP | ATA | | | | FRONT END ALIGNMENT | | | | | | | |
|--|--|--|--|----------------------------------|--|--|--|--|--|--|--|--|--|---|---|------------------|-----------------|--|--|
| | | | | VALVES IGNITION | | | | | | | | | | | | | | | |
| MAKE AND MODEL | No. of cylinders Bore and | H.P. | Cu | Se An | | Clear Tap Opera | pet | (ln.) | | (Im.) | Tim- ing | | | | | | | | |
| | (In.) | Maximum Brake H | Plug and Size (r | Brake Size (r | Plug and Size (r | Inlet (Deg.) | Exhaust (Deg.) | Inlet (In.) | Exhaust (In.) | Breaker Point Gap | Cam Angle (Deg.) | Spark Plug Gap (I | Spark Occurs T.C. | Steering Axis Inclination (Dep.) | Caster (Deg.) | Camber (Deg.) | Tee-in (in.) | | |
| AMERICAN MOTORS CORP. Rambler American 5-8001 Deluxe, Super American 6-8001 Custom | 6-31/x41/4 6-31/x41/4 6-31/x41/4 8-31/x31/4 8-4x31/4 | 90 125 127 290 250 | CA-14 CA-14 CA-14 CA-14 CA-14 | 45 45 45 30 30 | 45 45 45 45 45 45 | .016C .012H .012H .012H .012H | .018C .016H .016H .014H Hyd | .020 .016 .016 .017 | 39 32 32 30 30 | .035 .035 .035 .035 | 38 88 56 TC TC | 8 8 6°11' 6°11' | 0 to 1/2P 0 to 1/2P 0 to 1/2P 0 to 1/2P 0 to 1/2P | 14N to 14P 14N to 14P 14N to 14P 14N to 14P 14N to 14P | 1 to | | | | |
| SuperbaA-10L | 6-3/6x43/6 6-3/6x43/6 | 80 122 | Ch-18 Ch-14 | 30 30 | 44 | .014H .017H | .014H .023H | .020 | 39 39 | .029 | 48 31/2B | 7 7 | 2P 2P | 14P to 114P 34P to 114P | 10 to 30 | | | | |
| CHRYSLER CORP. Chrysler . Newport 8-RC1-L Windsor 8-RC2-M De Soto . Yerker 8-RC3-H Dodge . Potara 8-RD1-L Beneda F. Soneda 6-R03-L Pioneer 5-RD3-M, Phoenix 6-RD3-A | 8-41-(x3)-6 8-41-(x3)-6 8-41-(x3)-6 8-41-(x3)-8 8-41-(x3)-8 8-41-(x3)-8 | 265 305 350 265 265 325 | AL-14 AL-14 AL-14 AL-14 AL-14 | 45 45 45 45 45 45 | 45 45 46 45 45 45 | Hyd Hyd Hyd Hyd Hyd Hyd | Hyd Hyd Hyd Hyd Hyd Hyd | .017 .017 .017 .017 .017 | 30 30 30 30 30 30 30 | .035 .035 .035 .035 .035 .035 | 10B 10B 10B 10B 10B 714B | 61/2 61/2 61/2 61/2 61/2 61/2 | 0 to 1N 0 to 1N 3/P to 13/P 0 to 1N 0 to 1N 0 to 1N | P to P P to P P to P P to P | A to A to A to A to A | | | | |
| | 6-3}}x4}/g | 145 | AL-14 | 45 | 46 | .010H | .020H | .020 | 43 | .035 | 21/28 | 61/2 | 0 to 1N | 34P to 34Pc | it to i | | | | |
| 8-RD4-L. RD4-M, RD4-H | 8-3}1x3/4 | 230 | AL-14 | 45 | 45 | .010H | .018H | .017 | 30 | .035 | 58 | 61/2 | 0 to 1N | 34P to 34P1 | 1/100 1/1 | | | | |
| | 8-3}}x3/4 | 265 | AL-14 | 45 | 45 | .010H | .018H | .017 | 30 | .035 | 10B 10B | 634 634 | 0 to 1N 0 to 1N | 34P to 34Pt | it to | | | | |
| 8-RD4-L, RD4-M, RD4-H | 8-41/6x33/6 | 305 | AL-14 | 45 | 45 | Hyd Hyd | Hyd | .017 | 30 | .035 | 714B | 01/2 | 0 to 1N | 3/P to 3/P: | 1 to 1 | | | | |
| Dodge Lancer 170-8-RW1-L, 770-8-RW1-H | 8-41/4×33/6 | 101 | AL-14 | 46 | 46 | .010H | .020H | .020 | 43 | .035 | - | 736 | 0 to 1N | 34P to 34P | 1 to 1 | | | | |
| 8-RWI-L, RWI-H (Engine Option) | 6-311x316 6-311x416 | 145 | AL-14 AL-14 | 46 | 46 | .010H | .020H | .020 | 43 | .035 | 21/2B 21/2B | 71/2 | 0 to 1N | 34P to 34P: | in to | | | | |
| Imperial Custom 8-RY1-L Crown 8-RY1-N, Le Baron 8-RY1-L Plymouth Savey 6-RP1-L Belvedere 8-RP1-M, Fury 6-RP1-H | 8-4 tax33 | 350 | AL-14 | 45 | 45 | Hyd | Hyd | .017 | 30 | .035 | 108 | 63/6 | 34P to 134P | 34P to 34P1 | A to | | | | |
| Belvedere 6-RP1-M, Fury 6-RP1-H Savoy 8-RP2-L, Belvedere 8-RP2-M, | 6-311x41/6 | 145 | AL-14 | 46 | 46 | .010H | .020H | .020 | 43 | .035 | 23/2B | 81/2 | 0 to 1N | 34P to 34P1 | if to | | | | |
| Fury 8-RP2-H | 8-3}}x3/4 | 230 | AL-14 | 45 | 45 | .010H | .018H | .017 | 30 | .035 | 58 | 61/2 | 6 to 1N | 34P to 34P1 | A to d | | | | |
| | 8-41/(x33/6 | 305 | AL-14 | 45 | 45 | Hyd | Hyd | .017 | 30 | .035 | 108 | 61/2 | 0 to 1N | 34P to 34P1 | it to | | | | |
| Valiant . V-100-6-RV1-L, V-200-6RV-1-H | 8-41/x33/6 6-31/2x31/6 | 325 101 | AL-14 AL-14 | 45 46 | 45 46 | Hyd .010H | Hyd .020H | .017 | 30 43 | .035 | 71-2B 21-2B | 61/2 71/2 | 0 to 1N 0 to 1N | 34P to 34P1 | it to i | | | | |
| Comet. Comet. Ranger-8 Ranger-8 Ranger-8 Ranger-8 Falcon Fairlane, Fairlane 500, Galaxie-8 Fairlane, Fairlane 500, Galaxie-8 All Models (Engine Option) Thunderbird-8 Lincoln Lincoln, Premiere, Continental-8 Mercury Montelair, Park Lane-8 GENERAL MOTORS CORP. | 6-31-x2) 6-35-x33 8-31-x34 6-31-x2 6-35-x33 8-4x3 8-5x | 90 145 185 300 90 145 185 236 300 350 315 205 280 310 | Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 Ch-18 | 45 45 45 45 45 45 45 45 45 45 45 | 45 1 2 45 | .016H .019H .019H .016H .019H .019H .019H Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hy | .018H .019H .019H .018H .019H .019H .019H Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hyd Hy | .026 .026 .015 .015 .026 .026 .015 .015 .015 .015 .015 .015 | 37 37 27 27 37 37 27 27 27 27 27 27 27 27 27 27 27 27 | .034 .034 .034 .034 .034 .034 .034 .034 | 2B 4B 3B 3B 2B 4B 3B 3B 3B 4B 4B 6B 6B | 7 63 63 63 63 63 63 63 7 7 7 | 1P to 2P 1N to 1P N to 1P N to 1P 1P to 2P 1N to 1P 1N to | P to 1 P P P to 1 P P P to 1 P P P P P P P P P | 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | | | |
| BuickSpecial 8-4000, 4100 Le Sabre 8-4400 | 8-31-2x211 8-41-1x311 | 155 250 | AC-14 AC-14 | 45 45 | 45 45 | Hyd Hyd | Hyd Hyd | .016 | 30 | .033 | 716B 12B | 71/2 | 34N to 134N 36N to 136N | 0 to 34P | 1 to 1 | | | | |
| | 8-4-1-x341 8-4x3% | 325 325 | AC-14 AC-14 | 45 44 | 45 44 | Hyd Hyd | Hyd Hyd | .016 | 30 | .033 | 12B 5B | 9°52′ 6 | 1/2N to 11/2N 1/2N to 11/2N | 0 to 34P 36N to 36P | is to | | | | |
| Chevrolet Biscayne 6-1100, Biscayne Fleetmaster 6-1300, Bel Air 6-1500, Impala 6-1700 Biscayne 8-1200, Biscayne Fleetmaster 8-1400, | 6-3 % x3 18 | 135 | AC-14 | 31 | 46 | Hyd ² | Hyd ² | .019 | 32 | .036 | 6B | 7°11′ | 34N to 34P | 0 to 1P | 1 ¹ 0 to | | | | |
| | 8-37/sx3 | 170 | AC-14 | 46 | 46 | Hyd | Hyd | .019 | 30 | .036 | 4B | 7°11′ | 3/2N to 3/2P | 0 to 1P | is to | | | | |
| | 8-41/(x31/4 8-3/4x231 | 250 80 | AC-14 AC-14 | 46 45 | 46 45 | Hyd Hyd | Hyd Hyd | .019 | 30 | .038 | 8B 4B | 7011 | 15P to 15P | 0 to 1P 0 to 1P | 16 to 1 | | | | |
| Corvair | 8-31/4x244 | 230 155 250 325 | AC-14 AC-14 AC-14 AC-14 | 46 45 | 46 45 45 45 | Hyd Hyd Hyd Hyd | Hyd Hyd Hyd Hyd | .019 .016 .016 | 30 30 30 | .036 .040 .030 .030 | 48 58 58 58 | 71/2 10 10 | 115P to 215P 35N to 115N 0 to 1N 0 to 1N | 36N to 36P 0 to 34P 34N to 34P 34N to 34P | 0 to 3 | | | | |
| Super 88-8-3500 98-8-3500 | | 218 235 110 155 | AC-14 | 30 30 30 46 | 45 45 45 46 | Hyd Hyd Hyd Hyd | Hyd Hyd Hyd Hyd | .016 .016 .016 | 30 75 | .036 .036 .036 | 68 68 68 58 | 4°50′ 4°50′ 6°50′ 6°50′ | 1N to 2N 1N to 2N 1N to 2N 1N to 2N | 14N to 14P 14N to 14P 14P to 112P 12P to 112P | 0 to 1 | | | | |
| STUDEBAKER-PACKARD CORP. Studebaker Lark 6-61S Lark 8-61V Hawk 8-61V | 6-3x4 8-3,4x314 | 112 | Ch-14 Ch-14 Ch-14 | 45 45 45 | 45 45 45 | .024H .024H .024H | .026C .026C .024H | .020 .016 .016 | 35 | .036 .036 .036 | 2B 4B 4B | 1 | N to P | 0 to 1P 0 to 1P 0 to 1P | to to | | | | |

ABBREVIATIONS

!-Left only; right, 0 to 1/2 MP.
!--Series 1300 with std. trans. has

mechanical lifters having a clearance of .009 on intake and .016 on exhaust. AC—A.C. Spark Plug Div. AL—Electric Autolite Co. B—Before top center. C—Cold.
CA—Champien or Autolite.
Ch—Champien Spark Plug Ce.
H—Hot.

Hyd—Hydraulic valve lifters.
N—Negative.
P—Positive.
TC—Top center,

READER'S --CLEARING -HOUSE

MOTOR AGE CLINIC

for troubleshooting

BY JACK MONTGOMERY, TECHNICAL EDITOR

Carburetor Trouble on a 1951 Model Olds' 88

We are confronted with a difficult problem involving a carburetor on a 1951 model Olds 88. The trouble is that quite often when bringing the car to a stop or to idle, it will stall. Then it is hard to start again as the intake manifold gets loaded with gas which pours in two streams from the carburetor main discharge nozzles. The original carburetor on this car was serviced with a repair kit in September 1956. It ran perfectly until last summer when the stalling problem started. We installed a rebuilt carburetor in February of this year. It did the same thing. Finally we decided to really dig into this. We performed a valve grind job on the motor, installed new hydraulic lifters, new points, plugs, condenser, etc. We installed new ignition wiring and a new carburetor. All this we did last May. It ran fine for about six weeks. Then the stalling and loading up with gas problem came back. We have checked the carburetor thoroughly for float level, drop, pontoon centering, needle and seat and all the other adjustments. All checked out OK. Also we put on a new fuel pump and it is producing the proper 41/2 lbs. of pressure with engine running. Can you help us? Why should gas pour out of the main discharge nozzles when engine stalls or is stopped?

> Robert A. Merrill Warren's Sales & Service Eastford, Conn.

A SSUMING that all the modifications have been taken care of correctly, the trouble must still center around the needle valve. A lot of complaints of flooding have been caused by the presence of iron oxide in the system. This can be eliminated by installing a magnetic trap type filter. Also lowering the float about ½2nd of an inch. Make sure the heat damper valve is free and operating properly.

Low Oil Pressure In Overhauled Chevy V-8 Engine

Our shop recently performed a complete major overhaul on a '55 Chev. V-8. It consisted of the following work: connecting rod and main bearings bored .030" over with new pistons and rings. Seats and valves refaced, blocked boiled and oil passages cleaned, and a new oil pump installed. The pump was furnished in a stock Chev. kit as one superseding the original pump and screen. There now seems to be an oiling problem at idle speed. Using 20w oil and when engine is started and run cold, the oil pressure is between 15-20 p.s.i. at idle, but when the temp, reaches 180° F, the pressure has dropped to about 4-5 p.s.i, pressure at 450 R.P.M. Off idle it immediately rises until finally reaching the specified 35-40 p.s.i. at 2000 R.P.M. The oil passage on the distributor body has been checked for proper indexing with the oil gallery, and lifter noise (mech. type with standard transmission) does not seem excessive. Can you furnish any clues as to what might be causing the lower oil pressure?

Howard Bedford Automotive Service San Carlos, California

WOULD say if the oil pressure is reaching the 35 to 40 lbs, per square inch at two thousand RPM's you do not have too much to worry about. But if you would like to increase this on the idle, you could do it by increasing the tension on the oil relief valve spring. You can either stretch this spring at the spacer, or in some cases there are heavier springs which you can buy. I would suggest also, while the pan is off, to make an oil pressure test on it. Use the lightest oil you can get; say 5W or 10W. Install your oil pressure tester and observe where the oil is leaking from the various bearings. If excessive at any one point, I would check the bearings for looseness.

1956 Ford Wanders On Paved or Gravel Roads

I have a steering problem on a 1956 Ford Country Squire Wagon. On a paved road this car has a wander over several hundred yards of road. On a gravel road the wander is more pronounced. To date we have performed the following service work. Checked front suspension for worn or damaged parts, and replaced steering sector shaft Continued on page 84


CURRENT PASSENGER CAR PRICE, WEIGHT AND BODY TABLE

Following are prices at factory for cars with standard equipment as of Oct. 25, 1960 State or local taxes, transportation and finance charges and optional equipment are extra.

| BODY MAKE AND MODEL | List Price at Factory without Federal Taxes | Federal Taxes and Handling Charges | Suggested Price at Factory including Federal Taxes | Shipping Weight | BODY MAKE AND MODEL | List Price at Factory without Federal Taxes | Federal Taxes and Handling Charges | Suggested Price at Factory including Federal Taxes | Shipping Weight | BODY MAKE AND MODEL | List Price at Factory without Federal Taxes | Foderal Taxes and Handling Charges | Suggested Price at Factory including Federal Taxes | Shipping Weight | BODY MAKE AND MODEL | List Price at Factory without Federal Taxes | Federal Taxes and Handling Charges | Suggested Price at Factory including Federal Taxes | Steeling Weight |
|--|---|---------------------------------------|--|-----------------|--|---|---------------------------------------|--|-----------------|---|---|---------------------------------------|--|-----------------|--|---|---------------------------------------|--|-------------------|
| AMERICAN M | OTOR | | P. | | CHRYLSER COL | | | | | FORD MOTOR | 10.0 | 200 | 4 | | GENERAL MO | rors, | cent' | d | |
| RAMBLER American-8 | 1 | 1 | 1 | | DODGE, cont'd Convertible | 2972 | | | 3765 | LINCOLN | | 1 | 1 | | CHEVROLET, co Sedan, 4d | | | | 352 |
| DeLuxe Sedan, 2d Sedan, 4d | | | 1845 1894 2080 | **** | Sta. Wagen, 8p Sta. Wagen, 8p | 3011 3118 | *** | **** | 4115 4125 | Hardtop, 2d Sedan, 4d Hardtop, 4d | **** | *** | | **** | Hardtep, 2d Hardtep, 4d Convertible | 2468 2528 2700 | 236 241 254 257 | 2784 2780 2954 | 348 357 366 |
| Sta. Wagon, 2d. Sta. Wagon, 4d. | **** | *** | 2129 | **** | IMPERIAL Custom | | | | | Promiere Hardtop, 2d | | | | | Sta. Wag., 4d, 6; Sta. Wag., 5p | 2739 2835 | 267 | 2996 | 381 |
| Super-6 Sedan, 2d | **** | *** | 1930 | | Southampt., 2d | 4481 4654 | 442 455 | 4923 5100 | 4715 4740 | Sedan, 4d Hardtop, 4d | **** | *** | **** | **** | CORVAIR | | | | |
| Sedan, 4d | **** | *** | 1979 2165 2214 | | Crown Southampt., 2d | 4928 | 475 | 5403 | 4790 | Continental Hardtop, 2d | **** | *** | **** | **** | Coupe | 1750 | | **** | 23 |
| Sta. Wagon, 4d. Custom-6 | | *** | 2000 | **** | Southampt., 4d Convertible | 5155 5273 | 492 901 | 5647 5774 | 4865 4865 | Sedan, 4d Hardtop, 4d | **** | *** | **** | **** | Sta. Wag | 1800 2075 | *** | **** | 23 |
| Sedan, 2d Sedan, 4d | | *** | 2100 2295 | **** | Le Baron Southampt., 4d | 5870 | 556 | 8426 | 4875 | Town Car | **** | *** | **** | **** | Coupe Sedan, 4d | 1810 | *** | **** | 23 |
| Sta. Wag., 2d Sta. Wag., 4d | **** | *** | 2344 | **** | LANCER | | | | | MERCURY | **** | *** | **** | **** | Sta. Wag | 1860 2135 | *** | **** | 25 |
| Convertible Classic-6 | **** | *** | 2300 | **** | 170 Sedan, 2d | 1832 | | | 2585 | Meteor-6 600 | | | | | 900 Coupe | 2010 | | | |
| DeLuxe Sedan, 4d | | | 2008 | | Sedan, 4d Wagon, 0p | 1889 | *** | **** | 2895 2760 | Sedan, 2d Sedan, 4d | 2201 2251 | *** | **** | **** | 95 Spts. Wag | 2433 | *** | | |
| Sta. Wag., 4d, 2s. Super | **** | *** | 2437 | **** | 770 Sedan, 4d | 1968 | | | 2005 | 800 Sedan, 2d | 2367 | | | | CORVETTE | 3619 | | | |
| Sedan, 4d | **** | *** | 2268 2572 | **** | Hardtop, 2d | 1993 | *** | **** | 2505 | Sedan, 4d | 2417 | *** | **** | **** | Sportscar | 2010 | *** | **** | 29 |
| Sta. Wag., 4d, 3s. | **** | *** | 2007 | **** | Wagon, 6p | 2257 | *** | **** | 2775 | Hardtop, 2d | 2423 2483 | *** | **** | **** | F-85 Sedan, 4d | 2175 | | | 25 |
| Custom Sedan, 4d | | | 2413 2717 | **** | PLYMOUTH†† Savoy-V8 | | | | | Sta. Wag Meteor-S | 2562 | *** | **** | **** | Sta. Wag., 2s Series 88 | 2425 | | | 27 |
| Sta. Wag., 4d, 2s Sta. Wag., 5d, 3s | **** | *** | 2842 | **** | Sedan, 2d Sedan, 4d | 2170 2217 | 174 | 2344 2395 | **** | 800 Sedan, 2d | 2309 | *** | | | Sedan, 2d Celeb, Sedan | 2574 2634 | 261 266 | 2835 | 39 |
| Classic-V8 Super | | | | | Belveders-V8 Sedan, 2d | 2290 | 183 | 2473 | | Sedan, 4d | 2389 | *** | | **** | Hel. Coupe Hel. Spt. Sed | 2687 | 288 | 2900 2956 3034 | 39 |
| Sedan, 4d Sta. Wag., 4d, 2s | | *** | 2397 2701 | **** | Sedan, 4d Hardtop, 4d | 2337 2367 | 187 | 2524 2545 | | Sedan, 2d Sedan, 4d | 2475 2525 | *** | | **** | Convertible | 2750 2991 3065 | 275 293 296 | 3284 | 40 |
| Sta. Wag., 5d, 3s Custom | **** | *** | 2826 | **** | Fury-V8 Sedan, 4d | 2463 | 196 | 2859 | | Hardtop, 2d Hardtop, 4d | 2531 2881 | *** | | **** | Fiesta, 2s Fiesta, 3e | 3165 | 306 | 3363 3471 | 43 |
| Sedan, 4d Sta. Wag., 4d, 2s | **** | *** | 2812 2816 | **** | Hardtop, 2d Hardtop, 4d | 2485 2538 | 198 | 2683 2740 | **** | Monterey Sedan, 4d | 2822 | | | | Super 88 Celeb. Sedan | 2881 | 295 | 3176 | 40 |
| Sta. Wag., 5d, 3a AmbasV8 | | *** | 2941 | **** | Convertible | 2717 | 215 | 2932 | **** | Hardtop, 2d Hardtop, 4d | 2628 2688 | *** | **** | **** | Hol. Coupe Hol. Spt. Sed | 3020 3092 3268 | 305 | 3325 3402 3592 | 40 |
| Super Sedan, 4d | | | 2537 | | DeLuxe, 2d, 6p | 2488 | 198 | 2686 | | Convertible | 2860 | *** | **** | **** | Convertible Fiesta, 2s | 3336 | 324 329 | 3685 | 40 |
| Sta. Wag., 4d, 2s | **** | *** | 2841 2906 | **** | DeLuxe, 4d, 6p Custom, 4d, 6p | 2550 2636 | 203 209 217 | 2753 2845 | **** | Sta. Wag. Commuter | 2870 | | **** | **** | Fiesta, 3s Series 98 | 3436 | 337 | 3773 | 44 |
| Sta. Wag., 5d, 3s Custom | **** | *** | - | **** | Sport, 4d, 8p Sport, 4d, 6p | 2738 2770 | 217 | 2955 2969 | **** | Colony Park | 2852 | *** | | **** | Celeb. Sedan Hel. Sedan | 3533 3656 | 354 | 3987 | 42 |
| Sedan, 4d Sta. Wag., 4d, 2s | | *** | 2682 2886 | **** | Sport, 4d, 9p | 2872 | 227 | 3099 | **** | GENERAL MOT | ORS | CORP | | | Hol. Coupe Hol. Spt. Sed | 3715 | 368 | 4003 | 41 |
| Sta.jWag., 5d, 3s | | | 3111 | | VALLIANT V-100 | | | | | BUICK | | 1 | 1 | | Convertible | 3786 3975 | 387 | 4156 4362 | 43 |
| CHRYSLER CO | RP. | | | | Sedan, 2d Sedan, 4d | 1782 1838 | | **** | | Special Sedan, 4d | 2175 | *** | | **** | PONTIAC Tempest | | 1 | | |
| HRYSLER | 1 | 1 | 1 | 1 | Sta. Wag., 2s V-200 | 2128 | *** | **** | **** | Sta. Wag., 4d Le Sabre | 2425 | *** | **** | **** | Sedan, 4d | 1975 | *** | | 28 |
| Newport Sedan, 4d | 2693 | 271 | 2864 | 3710 | Sedan, 4d | 1927 | | **** | **** | Sedan, 2d Sedan, 4d | 2720 2826 | *** | **** | **** | Sta. Wag., 6p Catalina | 2225 | | **** | 29 |
| Hardtop, 2d Hardtop, 4d | 2750 2824 | 275 | 3025 3104 | 3690 3730 | Hardtop, 2d Stn. Wag., 2s | 1952 2217 | *** | **** | **** | Hardtop, 2d | 2887 2938 | *** | **** | **** | Spt. Sedan, 2d Sedan, 4d | 2390 2456 | 241 246 | 2831 2702 | 36 |
| Convertible Sta. Wag., 2s | 3137 3230 | 305 311 | 3442 3541 | 3760 4070 | | | | | | Convertible Est. Wagon, 2s | 3082 3306 | *** | **** | **** | Spt. Coupe Vista Sed., 4d | 2515 2586 | 251 256 | 2766 2842 | 35 |
| Sta. Wag., 30 | 3305 | 317 | 3622 | 4155 | | | | | | Est. Wagon, 3e | 3406 | *** | **** | **** | Convertible Sta. Wagon, Sp | 2805 2825 | 273 274 | 3078 | 38 |
| Windsor Sedan, 4d | 2920 | 298 | 3218 | 3730 | | | | | | Hardtop, 2d | 3129 | *** | | **** | Sta. Wagon, 8p Ventura | 2925 | 282 | 3207 | 41 |
| Hardtop, 2d Hardtop, 4d | 2999 3059 | 304 | 3363 3367 | 3710 3765 | FORD MOTOR | co. | | | | Hardtop, 4d Convertible | 3192 3290 | *** | **** | **** | Spt. Coupe | 2706 | 265 | 2971 | 36 |
| New Yorker Sedan, 4d | 3752 | 371 | 4123 | 4058 | COMET Sedan, 2d | 1830 | 168 | 1998 | 2399 | Electra Hardtop, 2d | 3460 | | | | Star Chief | 2777 | 270 | 3047 | 37 |
| Hardtop, 2d Hardtop, 4d | 3880 | 375 381 | 4175 4261 | 4065 4100 | Sta. Wag., 2d | 1880 2119 | 173 | 2063 2310 | 2432 2548 | Sedan, 4d Hardtop, 4d | 3466 3566 | *** | **** | **** | Vista Sed., 4d | 2736 2859 | 267 277 | 3003 3136 | 38 |
| Convertible Sta. Wag., 2s | 4188 4348 | 404 416 | 4592 4764 | 4070 4425 | Sta. Wag., 4d | 2158 | *** | **** | 2881 | Electra 225 Convertible | 3795 | | | | Spt. Coupe | 2970 | 285 | 3255 | 38 |
| Sta. Wag., 3s | 4448 | 423 | 4871 | 4455 | FALCON Tudor | 1746 | 166 | 1912 | 2259 | Riveria, 4d | 3942 | | **** | **** | Vista Sed., 4d Convertible | 3040 3175 | 291 301 | 3331 3476 | 38 |
| Hardtop, 2d Convertible | 4952 5352 | 450 450 | 5411 5841 | 4260 4315 | Fordor | 1803 | 171 | 1974 2225 | 2288 | CADILLAC Series 62 | | 10.1 | | | Sta. Wagon | 3225 | 305 | 3530 | 411 |
| | 9942 | 400 | 0011 | 4310 | Sta. Wagon, 4d. | 2074 | 194 | 2208 | **** | Coupe | 4475 | 417 | 4892 | **** | STUDE-PACKA | RD CC | DRP. | | |
| E SOTO Hardtop, 2d | 2827 | 225 | 3062 | | FORD† | | | | | Sedan, 4w Cpe. deVille, 4w. | 4650 4810 | 430 442 | 5080 5252 | **** | STUDEBAKER Lark-6 | 1 | | | |
| Hardtop, 4d | 2888 | 229 | 3117 | **** | Fairlane-V8 Tudor Sedan | 2163 | 214 | 2377 | **** | Convertible Sed. de Ville, 4w. | 5000 5040 | 455 458 | 5456 5498 | **** | DeLuxe Sedan, 2d | 1757 | *** | | 28 |
| Seneca-V8 | | | | | Forder Sedan Fairlane 500-V8 | 2213 | 218 | 2431 | | Biarritz | 5950 | *** | | **** | Sedan, 4d Sta. Wagen, 2d | 1822 2006 | *** | **** | 28 |
| Sedan, 2d Sedan, 4d | 2187 | 210 | 2397 2449 | 3470 3515 | Tudor Sedan Forder Sedan | 2270 2320 | 222 226 | 2492 2546 | **** | Hardtop Series 75 | 5700 | 533 | 6233 | **** | Sta. Wagon, 4d | 2160 | *** | **** | 28 |
| Sta. Wag., 4d, 6p | | 240 | 2815 | 3920 | Galaxie-V8 Tudor Sedan | | 1 | | **** | Sedan | 8750 | 783 | 9533 | **** | Regal Sedan, 4d | 1961 | | | 28 |
| Pioneer-V8 Sedan, 2d | 2310 | 220 | 2530 | 3460 | Forder Sedan | 2420 2470 | 232 236 | 2652 2706 | **** | Limousine | 8950 | 796 | 9748 | **** | Hardtop, 2d Sta. Wagon, 4d | 2043 | *** | **** | 27 |
| Sedan, 4d Hardtop, 2d | 2355 | 223 | 2578 2607 | 3510 3500 | Club Vict | 2478 2536 | 242 | 2713 2778 | **** | CHEVROLETA Biscayne-V8 | 0444 | | - | | Convertible | 2331 | *** | **** | 303 |
| Sta. Wag., 4d, 6p Sta. Wag., 4d, 9p | 2660 2756 | 246 253 | 2906 3011 | 3940 4005 | Starliner Sunliner Sta. WagV8 | 2476 2708 | 237 255 | 2713 2963 | **** | Sedan, 2d | 2156 2206 | 213 217 | 2389 2423 | 3425 3505 | Sedan, 2d | 1875 | *** | **** | 293 |
| Phoenix-V8 Sedan, 4d | 2482 | 233 | 2715 | 3535 | I Tudor Manch | 2465 | 237 | 2702 | | Sta. Wag., 4d, 6p Sta. Wag., 4d, 9p BelAir-V8 | 2519 2615 | 241 | 2763 | 3845 3895 | Sedan, 4d Sta. Wagon, 2d | 1940 2204 | *** | **** | 29 |
| Hardtop, 2d Hardtop, 4d | 2503 2558 | 234 238 | 2737 2796 | 3520 3555 | Forder Ranch | 2530 | 242 | 2772 2888 | **** | BelAir-V8 Sedan, 2d | 2270 | 221 | 2901 | 3435 | Sta. Wagon, 4d | 2278 | *** | **** | 1 |
| Convertible | 2736 | 252 | 2988 | 3580 | Ctry. Sed., 4d, 6p Ctry. Sed., 4d, 9p | 2717 | 255 | 2972 | **** | Sedan, 4d | 2320 | 225 | 2545 | 3520 | Sedan, 4d | 2079 | | | 29 |
| ODGE | | | | | Ctry. Squire, 6p. Ctry. Squire | 2795 2880 | 262 267 | 3057 3127 | 4000 | Hardtop, 2d | 2428 | 228 233 | 2596 2661 | 3480 3555 | Hardton, 2d Sta. Wagen, 4d Convertible | 2161 2417 | *** | **** | 303 |
| | ž. | | | 9700 | THUMBERRIED | | | 1 | | Sta. Wag., 4d, 6p Sta. Wag., 4d, 9p | 2007 | 247 | 2854 | 3880 3910 | Convertible | 2449 | *** | **** | 33 |
| Polara-V8 Sedan, 4d Hardtep, 2d | 2706 2767 | *** | **** | 3700 3890 | THUNDERBIRD Hardtop | 3426 | 329 | 3755 | 3799 | Impala | 2783 | 254 | 2957 | 2010 | Cruiser, 4d Hawk | 2239 | | | |

[†] For 8 cyl. models deduct \$105 from List Price and \$113 from Suggested Delivered Price at Factory.
† For 6 cyl. models deduct \$111 from List Price at Factory and \$119 from Suggested Delivered Price at Factory.
‡ For 8 cyl. models deduct \$111 from List Price and \$119 from Delivered Price at Factory.

[▲] Fer 6 cyl. medels deduct \$100 from List Price and \$107 from Suggested Delivered Price at Factory.



New Products Shopping Center

Gasket & Seal Kits

Designed for automatic transmissions

Jack-Pack Manufacturing Co.: The new Jack-Pack sealing line for automatic transmissions is introduced. It features a mini-



mum number of overhaul kits that cover all passenger and commercial automatic transmissions. According to the manufacturer, each kit is complete for listed model. Low inventory of these overhaul kits means less orders to place and no un-needed parts need be stocked company states. Write: D. L. Poe, Sec. & Treasurer, Jack-Pack Mfg. Co., 2115 N. Mariana Ave., Los Angeles 32, Calif., or 'phone CA 5-3279.

Acrylic Mixing Colors

Adds new mixing colors for use on 1961 cars

Ditzler Color Division, Pittsburgh Plate Glass Co.: Nine new mixing colors for correctly intermixing new colors to be used on 1961 cars have been added to the Duracryl Exact Weight Mixing Set. The new acrylic mixing bases incorporate new pigments that permit the matching of colors that could not previously be intermixed company states. Write: Ditzler Color Division, Pittsburgh Plate Glass Co., 8000 W. Chicago Ave., Detroit 4, Michigan or 'phone WE 3-7903.

Spark Plug Scope

Provides quick reading of spark plug performance

The Electric Autolite Company: A spark plug scope analyzer has



been developed. It is designed to provide quick reading of spark plug performance, company states. Worn spark plugs, deposit-fouled plugs and normal operating plugs are clearly indicated on the big screen. In addition, ignition problems involving the condenser, cap, points, spark plug wire or other ignition trouble can be diagnosed. Scope is contained in a plastic case and weighs ten pounds. It is powered from the car battery and operates on either 6 or 12 volt DC systems. Write: Glenn

Campbell, Dir. of Publicity, The Electric Autolite Co., Champlain St., Toledo 1, Ohio, or 'phone CH 3-3131.

Wire Clamp Pliers

Removes or installs wire clamps in any position

AC Spark Plug Division—General Motors Corp.: A service tool, designed to take the work out of installing and removing spring wire hose clamps, is available. The all-steel wire clamp pliers have tempered jaws with deep slots to hold the clamps securely. The jaws swivel through 180 degrees for removal or installation of wire clamps in any position. There are two different size slots in the



jaws for use on all size clamps. Write: W. J. Oldfield, Dir. of Adv. & Promotion, AC Spark Plug Div., GM Corp., 1300 N. Dort Highway, Flint, Mich. or 'phone CE 4-5611


Continued on page 78

CAR and TRUCK Shop kinks


\$25 for KINK of the month \$10 paid for other KINKS

Opening Rocker Arm Plugged Oil Passages On Ford V8's Karl P. Seckler, 1311 Faircrest Street, S. E. Canton 7, Ohio

Use a rocker arm shaft ent hole to 7/10" and tap for grease fitting. Bolt assembly sage. This will give you 4000 to 8000 pounds pressure to force sludge out and the grease will force out in a stand and cut off above bottom of shaft contour. Drill presto the cylinder head oil pas-1/8" pipe. In this hole screw a minute with the oil.




Removing Rear Wheel Cylinder Without Bleeding System William A. Del Sardo, 114 Hollowhaven Dr., Pittsburgh, Pa. 78. On Chrysler Corporamoving a rear wheel cylinder it necessary to bleed the whole tion cars their master cylinders are up high. When rethe fluid in the reservoir will drain completely. This makes system. Save the rubber plug in each new wheel cylinder. After removing the brake line, put the rubber plug on the end




Jack Mercer, Auer & Ashley Buick Inc., 202 Main St., Lakewood, N.J. Reworking Front Pump On Dynaflow Jobs

pump covers may need to be replaced due to excessive wear from the front pump driving gear and straight. This prevents the driving gear from riding high on the primary pump gouging into the front pump plate. Usually the primary where it fits into the driving all the driving edges of the pump hub wears on a taper, gear. We save this by filing primary pump hub smooth 79. Front hub.



Chuck Shaw, Jr., 701 Whitelock Street, Baltimore, Md. Tool For Removal of Buick Differential Pinion Gear

moval of the differential pin-Cut off the last six inch section of a discarded Buick drive 80° Here is a tool for reion gear in 1956-60 Buicks. shaft at internally splined differential end. Weld a piece of steel rod 1" x 1/4" by 36" long to the cut end.





SELLING SLANT OF THE MONTH!

MONEY-MAKING PACTS FOR DEALERS



Wait till she feasts her eyes on this

automatic griddle!



Take it home to her with this AC Fuel Pump Merchandiser



Big juicy steaks, chops, hamburgers, golden pancakes, heaps of good eating-grilled right at the table with this family-size 11" x 17" Presto Griddle. Just dial Presto's Control Master to the right temperature and start grilling. Exclusive slideout drip tray for easy clean-up. Stick-proof silicone surface. The Control Master (not included in FPM-75) detaches so griddle can be washed completely under water. A wonderful family gift; a top prize for an employees' sales contest.

HERE'S ALL YOU DO: Just place a qualifying order for 6 AC Fuel Pumps of your choice; then add \$17.40 for FPM-75 containing the Presto Griddle, and two popular #4460 Fuel Pumps for 1955-57 Chevrolets. When you sell the two fuel pumps, you recover the \$17.40 you paid for the package. The profit from the two fuel pumps (\$7.82) pays for the Presto Griddle.



FPM-76 CONTROL MASTER PACKAGE

You can order a Control Master with the FPM-76 package by including \$6.50 with your FPM-75 order. This package contains one Control Master and one #4460 Fuel Pump. Sell the fuel pump to \$8.70 and recover the cost of the package . . . Plus, a \$2.20 profit. Your Control Master costs you only \$1.71.

ORDER FROM YOUR

Chilton's MOTOR AGE . November 1960



SUPPLIER!







SELLING SLANTS

Permanent super-compact

Super bright, "
extra-hard aluminum
branches

Long-lasting beaut

Assembles in minutes, easily

> Each branch fully assemble

All-metal

OF THE MONTH!



Put your customers in a merry mood this season with this

Big 6½' Aluminum Christmas Tree

Get it with the SPM-81 Promotion Package

Solve your holiday decorating problems in a jiffy with this big 6½' shimmering aluminum Christmas tree. It's the easiest way possible to fill your place of business with a note of festivity. Such atmosphere sets your service center apart from the ordinary, creates drawing power—and puts your customers in a merrier buying mood. These trees can be used any place—in the front window, office, lube bay, etc. You get one tree with each SPM-81 Promotion Package.

Ornaments included—Each tree comes with a package of "Bold Glow" featherweight styrofoam ornaments.



Here's How to Get SPM-81—The SPM-81 package contains the aluminum tree, styrofoam ornaments and an 8-Pac of 85TS AC Fire-Ring Spark Plugs. You get the aluminum Christmas tree and ornaments in the SPM-81 AC Spark Plug Package for only \$1.94, and the profit from the sale of the 8 spark plugs contained in the package. Your initial investment in the entire package is \$10.50 with any order for AC Spark Plugs.

AC Fire-Rings are used on more new cars than any



other brand—ACs are best for replacement, too—in all cars—thanks to their exclusive "Hot Tip" that heats faster and cools faster to stay clean longer.

Add special glitter to your tree with these two

HANDY FLOODLIGHTS

Get them with the SPM-32 Promotion Package—
Use this pair of weatherproof, indoor-outdoor, blue floodlights to add a new sparkle of beauty to your aluminum tree. Direct them on the tree from any angle; they're fully adjustable. Place them on the floor or attach to wall. Each unit has a 6-foot cord and is completely weatherproofed for outdoor use.

Perfect for diaplay lighting—any season. Get

completely weatherproofed for outdoor use.
Perfect for display lighting—any season. Get
SPM-82 with any AC Spark Plug order. Just
add \$9.95 for the two floodlights and an
8-Pac of AC Fire-Rings. The profit from the
sale of the 8-Pac, plus \$1.39, pays for
the floodlights.



FIRE-RING SPARK PLUGS

ORDER NOW FROM YOUR



SUPPLIER

AG

SELLING SLANTS

MONEY-MAKING FACTS

* Airguide

auto compass

★★ Ice-O-mat ice crusher

TAKE YOUR PICK

1-2-3-4 and 5 Star Awards

This is just a sampling of the 30 valuable prizes you can choose from in the AC-Guide Parade of Prizes. Read how you can get one or more of these exciting prizes—and make extra profits besides!

** Sportline sleeping bag

★ Coleman insulated jug

★ Silex Starburst Carafe

★★★★ Shakespeare spinning outfit

Shakesoeare BHANCED TACKLE

★★★★ Electric

can opener

OF THE MONTH!

Hurry-Hurry It's Pick-Your-Prize Time in the



Parade of Prizes

Yours with the GLM-79 Merchandiser Package

What an assortment of prizes! If you're an outdoor man, you might like a deluxe sleeping bag . . . a Coleman lantern or camp stove . . . a tackle box . . . or a Shakespeare spinning outfit. Or why not thrill the lady in your life with an electric blanket . . . an electric can opener... or a deluxe hair dryer. There are gifts for the whole family, too-30 in all. And now you can get one or more of these wonderful gifts just by stocking and selling "Guide" Lamps-the sealed-beam lamps that are used on more new cars than any other brand.

OR DEALERS

How to get your "Parade of Prizes" Awards

Each GLM-79 Merchandiser Package you buy contains a 1-star Award Certificate-redeemable immediately for one of several 1-star gifts. The more packages you order-the more 1-star certificates you can accumulate for more expensive 2-3-4 or 5 Star Awards, as shown here. To order your prize or prizes, just fill out the certificate and send it to AC Parade of Prizes Headquarters. You pay only \$28.35 for each GLM-79 package containing 16 fast-moving AC Guide sealedbeam lamps. The profit from three 6000 series lamps is your only investment in the valuable 1-star award certificate. You get full profit on the 13 remaining lamp units.

Get on the beam for more sales, prizes and profits

Give your lamp sales a real boost by offering your GLM-79 prize certificate as an employees' sales award,

Used as an incentive, such prizes can quickly build lamp sales and profits.

GLM-79 CONTAINS



VALUABLE 1-STAR AWARD CERTIFICATE

A 1-star Award Certificate comes in each GLM-79 Package. It can be redeemed immediately for a 1-star award by completing the reverse side and mailing to AC Parade of Prizes headquarters. Award Certificates may also be accumulated for larger 2- to 5star awards.



16 FAST-MOVING AC GUIDE LAMPS

Each package contains a balanced inventory for both 2and 4-headlamp cars. The assortment consists of the following types: 5-6006; 5-6012: 2-4001: 4-4002.



AWARDS FOLDER

Fully illustrated, this folder shows all of the prizes available and how many star certificates are required for each prize. There are 30 valuable prizes in all.

ORDER GLM-79 PACKAGES FROM YOUR AC SUPPLIER TODAY



TIPS FOR THE BODY SHOP

Using Filler To Hold Snap In Fender Molding Clips

Snap in fender molding clips have always been a problem. They tend to push back into the molding when installed. When this problem arises, apply a little fibre glass body filler inside the molding and behind the clip. When it has hardened the molding will snap into place perfectly. Roy T. Womack, 1545 Therma St., Fortuna, California.

What To Do When Welding Near Or Around Moldings

When welding near or around moldings which are hard to remove, just apply a coat of carbon from your acetylene torch. When finished welding, wipe off with cloth. Another time saver is to lightly steel wool all moldings before a complete paint job. George Brockelbank, Dunhan's Auto Body, 860 Boston Road, Pinehurst, Mass.


Tool Makes Sandpaper Last Longer & Protects Fingers

I have a tool that is simple and inexpensive. It will make sand-paper go farther and save fingertips from being made sore and tender. Also it will help in sanding a smooth place where filling is done. I took a carpenter square and cut one piece 7 inches long and another one 11 inches, the full length of a sheet of sand-paper. Then I glued a piece of rubber about ¼ inch thick, as wide as the piece of square, to one side of the metal. I also use

it for blocking out plastic, putty and surfacer. George Kowalski, George's Auto Body Shop, Percy, III.

Tool For Removing Dents Without Pulling Upholstery

This tool saves us a lot of time and it is easy to make. Just weld a sheet metal screw on end of a "tee" handle. To use the tool we drill ½ in. holes along the dent. Screw tool in holes and tap edges along dent. We have



straightened many jobs this way. John Orris, Whalley Ford Sales, 12th St. & Graham Ave., Windber, Pa.

Discarded Wrapping Paper Protects Cars From Dust

Some car manufacturers wrap their replacement parts like hoods, fenders, etc., in a wrapping that is four or five sheets thick. Some of these are a good size. Take these sheets apart and use them to lay on a car to keep dust off. They also can be used for masking a car when you only want to paint lower half. Justin D. Tieri, 628 Parkside, N.W., Grand Rapids, Michigan.

Tool For Removing Staples Without Damaging Headliner

In most G.M. cars, the headlining is stapled across the windshield and back glass opening. To remove these staples with the least amount of damage to the headlining I use a tool made in the following manner. I take an ice pick or similar pointed tool. heat the pointed end and bend about 1/2 of the pointed end to right angle of the rest of the ice pick so as to form a hook. By using this hook, the staples may be easily pulled. In replacing the headlining across these openings, apply a little trim cement to the edges. Wait until tacky. Then apply the headlining to the tacking strips around these openings. The glue will hold the lining in place while you tack it. Walter C. Bruss, Body Shop, Mel Bloch Chevrolet, Rolla, Missouri.


Method To Fill Molding Clip Holes On Fenders

When filling chrome clip holes on a fender or hood, I grind off the paint around them first. Then I countersink the holes with a bit larger than the holes. Holding a dolly behind hole, you can easily fill the hole with torch and acid core solder. The dolly cools the solder before it has a chance to run off. Victor Sipla, BB 1, Grand Marsh, Wisc.

BODY SHOP TIPS are worth



If you've developed an Idea that has helped you to do body and fender work or painting better or faster, it may be worth money. Jot down the idea and, if necessary, make a rough sketch. Sometimes a snapshot will help. Just make the description of your BODY SHOP TIP clear, and if it is used, you'll receive a check for \$7.50.







FACTORY FINISHES COME NATURALLY when Heller VIXEN Files are used on body repair jobs... because they're the same files the leading car makers use to produce paintable surfaces without extra filing or polishing.

THERE'S NOTHING FASTER THAN A VIXEN! Exclusive undercut teeth chew off metal in time-saving bites. The forward curve, deep gullets and wide pitch prevent loading and tracking.

SEE A DEMONSTRATION! Your nearby Heller distributor has Heller Vixen Files that fit any flat or curved body surface you'll ever repair. Make a date for a presentation today.



HELLER TOOL CO.



17 -8 17

America's Oldest File Manufacturer NEWCOMERSTOWN, OHIO Subsidiary of Simonds Saw and Steel Co.

Branch Offices and Warshouses: Newark, N. J. @ Detroit @ Chicago @ Shreveport @ Los Angeles @ Portland, Oregon

Chilton's MOTOR AGE . November 1960

NASCAR* CHAMP ACCLAIMS GABRIEL SHOCKS!



Here's what Rex White, who recently clinched the 1960 NASCAR point championship, says about his Gabriel shock absorbers: "I'll give my Gabriel shocks credit for top performance all the way. They gave me a good tight ride and the kind of control you've got to have to thread your way through traffic, fender to fender, at 150 miles an hour. Yes, sir, I've ridden a lot of shocks, but Gabriels are tops with me!"



REX WHITE, 1960 STOCK CAR TITLE HOLDER, GIVES HIS GABRIELS CREDIT FOR "TOP PERFORMANCE ALL THE WAY!"



That's high praise from a high source! And remember: Rex White was not driving an Indianapolis-type car, with special racing equipment. He was driving a stock car, using standard equipment... the same rugged Gabriel shocks you can offer your customers. Be sure to tell those customers about Gabriel's proven superiority... and remind them to get ready for treacherous winter driving now with a Gabriel safety checkup.

*National Association for Stock Car Auto Racing



THE GABRIEL COMPANY . Cleveland 15, Ohio

Bring back new-car safety, new-car performance with DELCO



MORAINE POWER BRAKE SERVICE UNITS

These kits, parts and complete assemblies—along with special service manuals—help you to make quick, accurate repairs as recommended by the original manufacturer. And your customer gets that just-like-it-was-when-I-first-bought-it feeling. Service units and copies of the Delco Moraine power brake service manuals are readily available through car dealers and U.M.S. outlets. Order now.




Service manuals available for all models.

DELCO



MORAINE

Division of General Motors, Dayton, Ohio



BIG 5" SCREEN allows viewing from a distance—shows firing events in brightest light, indoors or out.

FREES THE HANDS! No squinting, no aiming, no fooling around. No peeking required either! You can view the big screen from a distance. Place the Autolite Scope on a fender or bench and watch it while you work!

BOTH YOU AND YOUR CUSTOMERS CAN LOOK!

The screen is that big! You can discuss ignition performance and economy while a customer sees for himself where the pattern indicates a malfunction.






74

Chilton's MOTOR AGE . November 1960

HERE NOW...

AUTOLITE
"BIG SCREEN"
SPARK PLUG
SCOPE



Quick and easy to use, dependably accurate, this highly advanced Autolite Big Screen Spark Plug Scope reveals the toughest ignition problem without removing the plugs.

You can give your customer a complete ignition analysis in just seconds. You can show him the trouble right on big easy-to-see 5" screen. And during the tune-up, you can check your progress while you work, insuring top accuracy and guaranteed customer satisfaction.

More than just another "plug scope," this revolutionary timesaver from Autolite gives you the complete story on plugs, coils, contacts, reverse polarity. In short, all ignition conditions.

For speed, accuracy, and on-the-job convenience, plus the exclusive advantage of no-squint big screen viewing, check out the new Autolite "Big Screen" Spark Plug Scope today. Call your Autolite Spark Plug Wholesaler.

THE ELECTRIC AUTOLITE COMPANY, TOLEDO 1, OHIO



REVEALS lead fouling, oil and gas fouling, electrode wear, cracked insulators—<u>all</u> spark plug conditions!



REVEALS defective coil and contacts, reverse polarity, all ignition conditions.



PERFORMANCE PROVED IN COMPETITION FOR ALL CARS

Body Shop

. Continued from page 55

pictures make a mental note of the shop's name and location.

"Motorists always like to talk about the repair work that was done on their car. They proudly show these before-and-after pictures to their friends, neighbors, co-workers and relatives," points out Pritz. "Every time they show this folder of before-and-after pictures to these people, they are also automatically placing our name before these individuals who have a tendency to remember it. Many prospects have told us that they come to our shop because they saw the type of work that we did on photographs shown to them by our previous customers. This, more than pays for itself many times over."

Pritz points out that the first set of pictures he ever took of a wreck job with his model 80 Polaroid camera was responsible for a \$1,600 job. He took several photos of this wreck. Brought them to the office of the insurance adjuster and went over the cost of repairs to the car. With the pictures in front of the adjuster, no further check of the

car was required by the latter. Approval to handle the \$1,600 job was given immediately.

In addition to the thirty-eight year old reputation of this firm for prompt quality workmanship, business is solicited by direct mail, highway billboard signs and a telephone book listing. Of the three, Pritz points out that his direct mail is the most gainful. Resulting in a 70 percent response from the motorists to whom it is directed.

Once a motorist comes to the shop for an estimate, Pritz shows them around. They can see the modern equipment and tools that his mechanics are working with. He impresses upon them the speed with which their car can be handled. He offers them a "loaner car" if they cannot be without transportation. Coupled with the before-and-after photographs that show them the type of workmanship achieved by this shop, Pritz has been able to keep his fifteen-man shop working on a continual basis.

"We now consider our camera an essential working tool," says Pritz. "It has brought us added business. It provides us with a permanent record of estimates that we give and minimizes the possibility of customer complaints."



...but TRAMCO flexibility lets you buy exactly what you need

A la carte or "full course" . . , the flexible TRAMCO line provides visible packaging & any combination of parts you need. No waste, no shortage, no unwanted surplus. Need a precision-built individual part? A Sub-Assembly Repair Kit? A complete, conveniently packaged Rebuilding Kit? TRAMCO has them all-always.

FOR THE BEST SELECTION IN AUTOMATIC TRANSMISSION AND POWER STEERING PARTS, PUT YOUR TRUST IN TRAMCO.



125 WEST END AVE. . NEW YORK 23, N. Y.

Imported Car Registrations* For Month of August

| 1960 | | 1959 | |
|---|---|--|--|
| Velkswagen Renault Opel Simca Triumph Flat English Ford Austin Healey Valve M.G. | 12.022 5.016 2.239 2.033 1.961 1.889 1.836 1.602 1.347 7.198 11.434 | Volkswagen Renault Fiat Opel English Ford Simca Hillman Triumph Vauxhall M.G. All Others | 6,520 6,611 3,822 3,712 3,608 3,577 2,717 2,326 2,247 1,826 |
| Total | 42,577 | Total | 86,540 |

Eight Months Total

| 1960 | | 1959 | |
|---|---|---|---|
| Volkswagen Renewit Opel English Ford Flat Triumph Austin Healey Simca M.G. Mercedes Benz All Others | 101, 567 49, 896 20, 236 19, 344 16, 018 12, 971 12, 434 11, 850 10, 087 9, 633 92, 821 | Volkswagen Renault English Ford Opel Fiat Simca Hillman Triumph Vauxhall Volvo All Others | 74,472 56,186 29,707 26,781 26,178 25,725 20,137 16,017 15,670 12,751 101,325 |
| Total | 356.827 | Total | 404,951 |

official state records.

GET THE BUSINESS THAT'S THERE!... MORE TIRE SALES COME FROM BETTER TIRE SERVICE

DO THE BEST TIRE GAUGING AND INFLATING JOB YOU CAN



schrader chuck gauge 3650 or 3650c... world's handiest... is the simplest, toughest, most versatile gauge you can use. Use them wherever you service tires. One finger control for gauging, inflating, deflating. Replaceable gauge unit.



SUPERIOR SCHRADER GAUGES

tell tire pressures accurately in 20 seconds, and you can inspect tire tread condition at the same time. Make money this easy way—drivers are more air pressure-conscious since tubeless tires.





Use these quality Schrader products in your service work. Get that extra business!



A. SCHRADER'S SON . BROOKLYN 38, N. Y.
Division of Scovill Manufacturing Co., Inc.

FIRST NAME IN TIRE VALVES

FOR ORIGINAL EQUIPMENT AND REPLACEMENT

Made in America to American Standards of Quality


New Products Continued from page 63

Ignition Parts

Services Ford-built cars from 1949 to 1960

Holley Carburetor: A new ignition parts assortment package to service all Ford-built cars from 1949 to 1960 is announced. The HC-548 Distributor Parts Assortment is packaged in a display carton. The assortment con-

tains thirteen contact sets, twelve condensers, five rotors and three caps, of which two contact sets, one condenser and one rotor are free to the dealer. A sales catalog is also included in each kit. Write: Director of Advertising, Holley Carburetor Co., 11955 East Nine Mile Rd., Box A, Warren, Mich.



Street.

And now, the Model MR, together with all Hall-Toledo valve seat grinding equipment, carries a written, one year guarantee—your assurance of the finest in quality, precision and workmanship from the leader in the industry.

Write today for full details.



Grinder. Ask your jobber to demonstrate this combination in action, or fill in the coupon below.

Please send information on the items checked. No obligation.

Valve seat grinders for Automotive, Diesel and Aircraft engines. Valve Guide Reamer and Seat Inserter. Expanding Pilots, Grinding Wheels Cylinder Hones.

Zone

State

and saves time. It counterbores head or block

for new valve seat rings, reams integral valve guides oversize. The MR also coredrills, reams for new guide bushings and removes old valve seat inserts. But the MR also uses standard Hall-Toledo expanding pilots, to make it a perfect

companion to the Model EJ Eccentric Valve Seat

Hot Water Heater

Designed To Fit Into Small And Compact Cars

Arvin Industries, Inc.: A new space-saving hot water heater is



introduced. It is designed to conserve leg room in small and compact passenger cars. Available in both 6 and 12-volt models complete with fittings, the 803C and 804C heater is 7 inches square. It has a 12,000 BTU heat capacity. A 6 by 5% by 2-inch copper radiator core of unique design allows air to pass through the heater with minimum restriction. Cold air is pulled through the core and hot air is pushed straight on through the heat control door at the bottom. This eliminates air-slowing back pressures, it is stated. A positive three-direction heat control permits the driver to determine the amount of heat needed, also the direction of the air flow. Write: H. Dukes, Sales Serv. Mgr., Arvin Industries, Inc., 13th & Big Four Rd., Columbus, Ind.

Point Setting Tool

Reduces time of setting distributor breaker gap



Herbrand Division of The Bingham-Herbrand Corp. A new tool that is said to reduce the time of setting distributor breaker point

Continued on page 87



"Our Yellow Pages advertising pulls 50% of our business!" says S. Bossart, Gen. Mgr., City Motor Exchange, Inc., Oklahoma City, Okla. "14 years in the motor rebuilding business have convinced me that the two best ways of pulling customers are Yellow Pages advertising and word-of-mouth recommendations. We've made a point of asking people how they come to us—so we're sure that 50% come in through the Yellow Pages! Again and again, customers say they've seen our other advertising, but when they're ready to buy, it's our Yellow Pages ads that direct them to us!"



Display ad above (shown reduced) appears under AUTOMOBILE REPAIRING. Call the Yellow Pages man at your Bell Telephone office today to help plan your program.

Display this emblem. It builds your business!





NEW LITERATURE DESCRIPTIONS

Winter Catalog

Covers anti-freeze and testing equipment



E. Edelmann & Co.: A new winter sale catalog of antifreeze, battery and pressurized cooling system testers is offered. Front-page feature of the new catalog is company's No. 909 "Magic Eye" Freeze-D-Tector. This instrument tests any radiator solution. As it has only one chart to dial and one reading to take, a glance shows the freezing point of any solution. The figures are magnified by its "Magic Eye" of unbreakable Lucite. The inside spread illustrates Edelmann Zero Testers for all solutions and single solutions. Write: E. Edelmann & Co., 2332 W. Logan Blvd., Chicago 47, Ill.

Installer Catalog

Contains catalog pricing schedule on exhaust system parts



Maremont Muffler Division: 1960 Installer Catalog contains the latest catalog pricing schedule and technical information on exhaust system parts and related accessories, Also included in the catalog is a listing of all the merchandising aids offered by the company. Write: Maremont Muffler Division, 168 No. Michigan Ave., Chicago 1, Illinois.

Brake Lining Catalog

Designed for use in determining lining needed

The Automotive Parts and Accessories Division of Wagner Electric Corporation: Announced is the publication of a forty-eight page catalog listing brake lining blocks. The catalog



is designed for easy use in determining lining needed for commercial vehicles with straight air, vacuum, electric or other mechanical cam type brakes. With every listing of lining set numbers, the corresponding brake sizes are shown. Vehicle model reference enables users to see the basic models, any options or variations, plus all brake sizes. Write: W. W. Dannemaier, Asst. Sales Promotion Mgr. Automotive Div., Wagner Electric Corp., 6400 Plymouth Ave., Saint Louis 33. Mo.

Continued on page 88

Henry took his wife to her first cocktail party. The drinks flowed pretty freely. After a while, his wife drew him aside and whispered:

"Please don't take any more to drink, Henry. You won't believe this, but your face is beginning to blur!" FRAM AND FRAM SUPPLIERS
REWARD DEALERS WITH GIFTS
THAT ARE ABSOLUTELY FREE!

MILLION\$\$\$ GIVEAWAY



These gifts are yours ABSOLUTELY FREE ... personal gifts ... for your home and workshop ... for every member of your family!

HERE'S HOW YOU GET YOUR FREE GIFTS:

- For every 24 Fram Filters you buy your Fram Supplier will give you two gift certificates ABSOLUTELY FREE.
- 2 Certificates may be redeemed for your choice of fabulous nationally advertised merchandise.
- 3 Gifts may be secured for two certificates, some for three, four, five, six, ten, twelve, etc.
- 4 Certificates may be redeemed at any time or accumulated and redeemed for gifts in higher value categories. (Offer expires Dec. 31st, 1960.)

Gifts are ABSOLUTELY FREE...they don't cost you a penny. They're your reward for selling Fram Filters. Get your gift Certificate Book from your Fram Supplier...start saving valuable Gift Certificates today.

CURRENT FRAM NATIONAL ADVERTIS-ING MAKES FRAM FILTERS EASIER TO SELL THAN EVER BEFORE! Outstanding 4-color ads in the Saturday Evening Post ...billboards on major highways...exciting point-of-sale material!

Get your share of valuable free gifts. ORDER FROM YOUR FRAM SUPPLIER TODAY! FRAM OIL AIR FUEL WATER FILTERS

YOUR FIRST LINE OF ENGINE PROTECTION

FRAM CORPORATION, Providence 16, R. I.

Alternator Service Continued from page 45

excitation of the fields. It depends entirely on battery voltage supplied to the fields thru the small brushes riding on the two collector rings of the rotor. Next look at the following:

Open Circuit in Load Relay Coil Pitted Load Relay Contacts Open Field Circuit Defective Wiring Between Battery and Regulator High Resistance at Battery Ter-

Defective Rectifier or Alternator Stator

Loose or Slipping Belt

Using Electrical Accessories
With Engine Not Operating

Quick Alternator Tests

To make a quick check of the alternators electrical condition on

the vehicle: first turn on the ignition switch, but don't start the engine. Using a D.C. voltmeter connect test leads across both field terminals. The meter should indicate full battery voltage. If not, then check wire from regulator "F" terminal to alternator. Next, check from alternator to ground. With battery voltage at field terminal. check for field coil and brush condition. Disconnect field wire at alternator and strike it against TERMI-NAL from which it was removed. A light spark should be visible with a normal system.

Calendar of Events

Nov. 15—Connecticut Automotive Trades Assn. convention, Statler Hotel, Hartford.

Nov. 16-17—South Carolina Automotive Wholesalers Assn. convention, Wade Hampton Hotel, Columbia.

Nov. 17-20—California Automotive Wholesalers Assn. convention, Hotel El Dorado, Sacramento.

Nov. 17-19—Florida Automotive Wholesalers Assn. convention, Washington Hotel, Jacksonville.

Nov. 17-18—Seventh Annual National Forum of Automotive Air Conditioning, Sheraton Hotel, Dallas, Texas.

Nov. 18-20—Automotive Wholesalers of Illinois convention, St. Nicholas Hotel, Springfield, III.

Dec. 2-9—Automotive Electric Assn. annual meeting, Edgewater Beach Hotel, Chicago.

Dec. 4-5—Georgia Automotive Wholesalers Assn. annual meeting, Atlanta.

Jan. 28—Feb. I, 1961—National Automobile Dealers Assn. annual convention, San Francisco.

Feb. 13-14, 1961—Automotive Booster Clubs, International annual meeting, Statler-Hilton Hotel, Los Angeles, Calif.

Feb. 14, 1961—General Membership Meeting, Automotive Affiliated Representatives, Biltmore Hotel, Los Angeles, Calif.

Feb. 14-15, 1961—Automotive Service Industry Assn. national convention, Biltmore Hotel, Los Angeles, Calif.

Feb. 16-19, 1961—Pacific Automotive Show presents ASI Show, Sports Arena, Los Angeles Memorial Coliseum, Los Angeles, Calif.



MOTOR MOUNT CHECK-UP

Nothing makes a motorist happier than the feeling you did a complete job.

He wants his car working perfectly.

That's why it always pays to check motor mounts on every motor repair or transmission job. It takes but a few minutes. Replace old or oil soaked mounts and send the motorist home smiling with a smoother,

better performing car.

Individually Boxed. Every Motor Mount packed in Illustrated

> and plainly with full

Call your favorite jobber. He stocks a complete line of Armor-Flex Motor Mounts for all popular makes and models. DOAN

MANUFACTURING

BEOA

1725 London Road . Cleveland 12, Ohio A DIVISION OF ANCHOR INDUSTRIES, INC.



EXTRA TRADE-IN DOLLARS

for your old valve seat grinder or grinder set!

SKIL VALVE SEAT GRINDERS (Standard and Heavy Duty Modeis). Cool running, easy handling. Popular 45° angle drive for working in tight quarters. Heavy duty model takes 2° and larger stones.

Right now, any valve seat grinder or grinder set—regardless of age—is worth extra trade-in dollars.

Here's how it works:

Buy a Skil valve seat grinder or set from your Skil Jobber. Get a whopping big extra trade-in price for your old seat grinder or set whatever its condition. But hurry, this offer is limited.

Call your Skil Jobber right now! Look under "Tools— Electric" in the Yellow Pages. Or write: Skil Corporation, 5033 Elston Ave., Chicago 30, Ill., Dept. 102K. In Canada: Skiltools Limited, Trenton, Ontario.

SKIL VALVE SEAT GRINDING SETS. Select from four sets—two low cost basic sets or two sets that include a wide assortment of stones, pilots, etc., for either general purpose or heavy-duty work.



. AND SKILSAW POWER TOOLS


Tune-up, Mechanical Solutions Continued from pg. 61

and roller assy. tube and worm, and all bearings and shims. We adjusted this unit to factory spec. and aligned it to the frame. We then aligned front end and road tested. We could not notice any improvement. While religning brakes we repacked or re-

placed and adjusted all wheel bearings. We than installed four shocks and tightened rear spring U bolts.

S. E. Palmer, Shop Foreman Cut Bank Motors Cut Bank, Montana I WOULD suggest installing heavier rear springs or using helper springs. Also sometimes a stiff tie rod end, or ball joint can cause this condition. Make sure these points are well lubricated and free.

Treat your friends as you would a bank account—refrain from drawing too heavily on either.





Address.

State

City

203 Commercial St. . Paw Paw, Mich.



Ben Guill

Moore Announces NADA Appointment

Ben Guill, Washington legislative consultant and former member of the House of Representatives, was recently named legislative liaison representative for the National Automobile Dealers Association. Announcement of Mr. Guill's selection was made by James C. Moore, NADA Executive Vice President.

A resident of Washington since 1950, Mr. Guill is well known among governmental departments, agencies and on Capitol Hill. Since leaving his post as Vice Chairman of the Federal Maritime Board on January 1 of this year, he has acted as Washington consultant on legislative matters for several industries. Prior to his service on the Federal Maritime Board, Mr. Guill served as Executive Assistant and legislative liaison to Postmaster General Arthur E. Summerfield.

Served in 18th District

Mr. Guill served as Member of Congress from the 18th Congressional District of Texas. He is a Tennesseean by birth. Aside from a period of service in the Armed Forces during World War II, he has been in the business field.

HAVE YOU TRIED

American Brakeblok's New Linings For Police Cars and Taxis?



The Interceptor lining is designed to operate efficiently at peak temperatures. Its materials are high in friction for maximum braking power. Grueling law enforcement agency road-tests prove this lining meets every braking emergency with a wide margin of safety.

The Special Service lining was developed for multi-stop service such as taxis and light city-delivery trucks. Extensive "on-the-job" testing proves Special Service lining outlasts ordinary friction materials 3 to 1 in rural mail carrier operation too.

American Brakeblok

P. O. BOX 21 . BIRMINGHAM, MICHIGAN





ORDER BOTH FROM YOUR NAPA JOBBER.

AMERICAN BRAKEBLOK

Chilton's MOTOR AGE . November 1960

Winter Merchandisina Continued on page 49

fully. It should be quiet with no leaks. If not, carbon monoxide fumes are likely to escape into the car. The infiltration of fumes is more dangerous during the winter than at any other time. A rusty, leaking muffler or exhaust pipe can be deadly if the motorist is stalled in traffic or a blizzard.

Sell your customers on the need for winter tune-ups. This is an excellent way to increase business and profit. Engine tuneups are essential to fast cold weather starting and help avoid stalling. The mechanic in his tuneup should check the entire ignition system. This should include points, condenser, spark plugs, automatic choke, voltage regulator and manifold heat control valve.

By now all cars should have antifreeze coolants added to the cooling system. If not, immediately, sell your coolant and installation service in order to prevent freeze-ups when the temperature drops. Also check for leaks in the radiator and hose. See that rusted clamps are replaced. Look the thermostat over carefully to see that it is working properly. Inspect the fan belt for wear and cracks.

You should have on hand an inventory of snow tires and tire chains. Sell your customers on the wisdom of putting on snow tires before snow arrives. Also every motorist should have a pair of reinforced tire chains for use in hazardous winter driving conditions. Chains will help prevent skidding accidents.

When customers drive in don't overlook the possibility of selling them your alignment and wheel balancing services. Out of balance wheels will shimmy. They will reduce the life of tires 25 to 50 per cent. A shimmy will also cause them to wear unevenly. If tires are excessively worn urge your customers to replace them.



Check your customer's defroster, heater and windshield wipers. Be sure that they are in excellent condition. Make any necessary adjustments or replacements if they are not operating with maximum efficiency. The heater-defroster should be capable of keeping the windshield clear at all times.

Offer to check headlights, stop lights, turn signals. Both headlights should work on upper and lower beams. Be sure to have an adequate inventory of bulbs and fuses on hand when they are needed.

Continued on next page

MORRIS CHARLES TO

Each one of these fine cars

BEHORR









comes Lucas equipped. For









greater profits and more



ROVER

CITRORN



satisfied customers always









replace Lucas with Lucas.



UCAS ELECTRICAL SERVICES, INC.

New York - Chicago - Houston - Los Angeles - San Francisco - Jacksonville - Seattle - Boston - Denver



Winter Time Merchandising . . .

Advertise your brake relining services and adjustment services in your winterizing campaign. All customers should be urged to have their car's brakes checked. Minimize skidding by checking for equal traction on all wheels. Add brake fluid if needed. Make sure that there are no leaks and that brake linings are free of grease. They should be relined if found badly worn and in dangerous condition. Also check the emergency brake.

Urge your customers to come in for a change to winter weight oil lube job. It is also a good policy to advise your customer on how to start his car on ice or snow. Also what speeds are best under most winter driving conditions. Give tips on how to come out of a skid safely and why signalling for stops as well as turns is very important during the winter. Customers appreciate your concern for their safety.

Advise your customer on the wisdom of carrying a bottle of glycerine and water in his glove compartment. It will free windshields of snow and ice quickly. Also advise them on adding fuel system antifreeze to gasoline and adding windshield washer anti-freeze. See that the glass is clear and does not have any cracks or discoloration.

New Products Continued from page 78


gaps has been announced. No. 2110 "Snap Gap" Point Setting Tool, makes time savings through the elimination of engine rotation and removal of the distributor. The Herbrand "Snap Gap" professional Mechanic's Set consists of five micro-precision split rings covering practically all American-made cars.

Also a complete range of special feeler gauges and companion adapters which establish accurate breaker point gaps.

Write: William L. Faulkner,

curate breaker point gaps. Write: William L. Faulkner, Adv. Mgr., The Herbrand Division, Bingham-Herbrand Corp., Cor. Stone and Lake Sts., Fremont, Ohio.

Continued on page 89



NEW! POWER STEERING REPAIR KITS

FROM WEATHERHEAD

No more fumbling, no more searching, no more sending out for extra parts. Now Weatherhead brings you complete power steering overhaul and rebuilding kits for pumps, gear assemblies and cylinders, with individually packaged, easily identified parts in sealed transparent envelopes, and detailed instructions in every master

kit. And all parts are manufactured to original equipment specifications by original equipment suppliers.

Your Weatherhead jobber has a complete assortment of these new kits to fit all popular makes and models. He can deliver your order from stock. No excuse to lose a repair job—ever. Just tell him what you need.



New Literature Continued from page 80

Illustrated Catalog

Describes culindrical grinder

Van Norman Machine Co., a division of Van Norman Industries, Inc.: A eight-page, three-color, illustrated catalog describes the 418 Cylindrical company's Grinder. Photographs and schematic drawings, offer detailed catalog illustrates the versatility catalog also describes seven op-Mass. or Phone MU 9-3663.

descriptions of the grinder. The of the 418 for diversified, close tolerance grinding during short runs or high production. The tional accessories for the 418. Wm. Hyland, Western Sales Mgr., Van Norman Machine Co., 3640 Main St., Springfield 7,

universal

REMOVES BEARINGS, REPLACES BEARINGS. EASILY! ACCURATELY!

STOP sending your customers away. Give them the universal joint servicing they need. The Speedee U-Joint Tool makes it easy—and

SPEEDEE U-JOINT TOOL makes it profitable-and easy-to service universal joints. It's a complete tool designed just for this service. Here you have the first practical way to do the entire job, quickly, accurately . . . without a bench vise or other costly equipment. Now you avoid the risk of bent, damaged driveshafts. No more drivelines thrown out of balance. No more customer complaints. The SPEEDEE U-Joint Tool is so simple, so foolproof, almost anyone can use it with immediate success.

> Ask Your Jobber for a Demonstration, or Write Direct.

Introductory Price only \$1995 complete!

A Product of

LEGVOLD ENTERPRISES, INC.

Muffler Catalog

Covers U.S. and Foreign Car Exhaust Systems

The AP Parts Corporation: Two-



hundred scale drawings of U.S. and foreign passenger car exhaust systems and a special section on the new AP oval shape Fiberglas Packed Muffler are featured in the 1960 AP Dealer Catalog. It is an 80-page catalog. Write: H. C. Stivers, Sales Mgr., The AP Parts Corp., 1801 Spielbusch Ave., Toledo 1, Ohio.

Comparison Charts

Contains set of welding rod and electrode comparison charts

The American Welding Society: Publication of a newly revised 48 page booklet containing a set of welding rod and electrode comparison charts has been announced. The brand names of 78 companies are listed. Fifteen AWS-ASTM specifications are involved and brands as well as manufacturers names are contained in two indexes. With the aid of the comparison charts it is possible to see at a glance in which classification a filler metal belongs, irrespective of the brand name or number. Write: Edward A. Fenton, Tech. Sec., American Welding Society, 33 Warren, Mich. or phone JEfferson 6-1900.

Professor: "Jones, I want you to compare the death rate of the 15th century—the time of Christopher Columbus-with that of today."

Jones: "That's easy, prof. The death rate's the same—one per per-



New Products

Continued from page 87

Valve Seat Insert

Comes in three different types

McQuay-Norris Manufacturing Co.: A new line of valve seat inserts has been introduced. It comprises three different types gray iron, hardened alloy, and stainless steel. The gray iron inserts are the most widely used. Hardened alloy inserts are of higher quality and will give longer life under more difficult operating conditions. The stainless steel inserts are of premium quality. They are designed for heavy duty use, and are recommended for use where hard faced valves and chrome top



rings are needed. Write: Mc-Quay-Norris Mfg. Co., 2300 Marconi Ave., St. Louis 10, Missouri.

Body Polisher

Designed to clean new paint finish



MoPar Parts and Accessories, Chrysler Motors Corp.: Lustur-Seal Haze Cream in a 16 ounce pressurized container is being marketed. The new MoPar Haze Cream is for use on the new melamine enamels, acrylic lacquers. and previously-used finishes. It contains no harmful elements or abrasives, it is stated, MoPar Haze Cream is designed to chemically clean new paint finish. It will remove road grease, tree sap, and other foreign materials. Write: John T. Davis, Adv. Supervisor, Chrysler Motors Corp., MoPar Div., 7000 E. Eleven Mile Road, Center Line, Mich. or phone JE 9-3000.

Oil Filters

Designed for foreign cars

Lee Filter Corporation: The assortment, designated No. LFC-12, consists of 12 oil filters (11 different numbers) which will fit some 33 different foreign car makes and nearly all models of each dating back, in some cases, to 1941. Packed in corrugated cartons, the LFC-12 assortment Continued on page 90



Power Brake Tester

Measures hydraulic pressure and vacuum of power brake units

Wagner Electric Corp.: An-

nounced is the introduction of the Wagner Lockheed Power Brake Tester. The instrument measures hydraulic pressure and vacuum of power brake units. It is marketed with adapter parts for testing various makes of units. The power brake tester may be used as bench equipment or used to test brake units on the vehicle. A mobile cart, available as an accessory, facilitates using the tester on the vehicle. A vacuum pump is available for



use when the vehicle's vacuum is not used in testing power brake units. Write: W. W. Dannemaier, Asst. Sales Promotion Mgr., Automotive Div., Wagner Electric Co., 6400 Plymouth Ave., St. Louis 33, Missouri.


Swivel Air Hoist

Offers maximum undercar clearance

Globe Hoist Company: Only "fist high" from the ground the swivel arm superstructure of company's design refined "Frame-Kontact" Hoist is said to offer maximum undercar clearance. Also easier adjustment to handle all cars. Other include swiveling features chassis contact pads adjustable to three height positions, extra



long sleeve supports for the pads, reversible pad position, brass swivel arm bearings and greater under-car accessibility accomplished by a narrow bolster and wider spacing of swivel arms. Write: Globe Hoist Co., E. Mermaid Lane at Queen St., Phila., 18, Pa.



Lift Adapters

Designed to bring up-to-date twin post lifts

Weaver Manufacturing Co.: New adapters to fit into the rear



saddles of Weaver Twin Post Lifts equipped with Adjustable Rear Adapters are available. They make possible lifting of any car-old or new-with a conventional rear suspension system, or an unusual one, company states. The Universal Rear Wheel Adapters were specifically designed to bring up to date even the oldest Weaver Twin Post Lifts and to prevent obsolescence of equipment resulting from changing automotive design. The adapters permit raising by the rear wheels, while the front end is raised by the usual Weaver Twin Post Method—at the outer ends of the front lower control arms-for completely relaxed front suspension. Write: Weaver Mfg. Co., Div. of Dura Corp., 2171 S. 9th St., Springfield, Illinois or 'phone CE 6-9520.

Air Nozzies

For spraying polychromatic lacquer and acrylic enamel



Binks Manufacturing Company: To meet the special conditions inherent in the spray application


of polychromatic lacquer and acrylic enamel, the company has developed a special set of low-pressure air nozzles. Reducing the air pressure aids in preventing mottling, but sacrifices good atomization. To retain both, the quality of the finish and efficiency of atomization, the new nozzles have been designed to operate at high efficiency at pressures as low as 40 pounds. Four nozzle types are offered: the 36

SE for Binks Model 7 spray guns, the 66 SG for Model 18, 19 and 29 guns, and the 63 PH and 63 PH-1 for Model 18, 19, 29 and 21 guns. Write: Binks Mfg. Co., 3114 Carroll Ave., Chicago 12, Ill.

Rust Remover

Kills surface rust

Martin-Senour Co.: A product has been introduced that is said Continued on page 94



Add an extra \$8,000, \$12,000, \$15,000 a Year SERVICING RADIATORS!

Now, the world's largest radiator servicing equipment manufacturer offers the complete package: Equipment, merchandising, "Pays-for-Itself" payment plan, complete factory school (free training for you or your man).

And Radiator Servicing produces top profits, quickly!

"\$900 Monthly Average", first 4 months-M. J. Wilson Co., Shelbyville, III.

"\$13,500 First Year", -Automotive Service Co., New Castle, Ind.

"\$800 Monthly Average", first 7 months—Walterboro Auto Parts, Waterboro, S. C.

FREE! Mail coupon today for Inland's New "Blueprint for Profits", a 32-page booklet showing various shop combinations. Tells exactly what you'll need to set up a complete radiator servicing dept. Gives prices, outlines "Pays-for-Itself" plan, describes experiences of others.

INLAND MFG. CO., Dept. MA-11, 1108 Jackson St., Omaha 2, Nebr.

| SERVICING RADIATORS | Please send new free | INLAND MFG. CO., Dept. MA-11, 1108 Jackson St., Omaha 2, Nebr. Please send new free book, "Blueprint For Profits." | | |
|---------------------------|------------------------|--|--|--|
| for profital | FIRM | (PLEASE PRINT | | |
| | ADDRESS. | | | |
| Art | CITY | ZONESTATE | | |
| | BY. | TITLE | | |
| and AMD menefacturing com | If dealer, make of car | If dealer, make of car sold | | |
| HILLAND MANAGEMENT | Are you now operating | a radiater dept.? Yes No | | |


Corvair by Chevrolet Tempest by Pontiac





...electrical systems

Delco-Remy systems provide electrical energy for the needs of motion in General Motors new size cars, too. Special electrical systems were developed by Delco-Remy working closely with Chevrolet, Pontiac, Buick and Oldsmobile. In all four new cars, these lighter units deliver the same kind of reliable high performance that has been built into Delco-Remy electrical systems for over fifty years.



Special by Buick

F-85 by Oldsmobile






by Delco-Remy

Delco-Remy equipment for the Corvair, Tempest, Special and F-85 includes • Generators • Regulators • Cranking Motors • Distributors • Ignition Coils • Horns • Flexible Cable Controls • Directional Signal and Control Switches • and Delco Batteries.

Delco-Remy electrical systems

From the highway to the stars

DIVISION OF GENERAL MOTORS, ANDERSON, INDIANA



New Products Continued from page 91

to stop rust. It etches both steel and aluminum in preparation for painting. Twin Etch, it is stated, kills surface rust on contact. It penetrates deep into pits and pores to destroy hard-to-get rust. The "brush-on, flush-off" method of applying Twin Etch adds to ease of use and eliminates the need for re-doing paint jobs.

Write: Martin-Senour Co., 2500 S. Senour Ave., Chicago, Ill.

Dwell-Tach Tester

Can be read without preliminary setting

Kal-Equipment Company: A combination Dwell-Tach Tester is being marketed. The hand-

held instrument is unique, it is stated, in that both the dwell meter and tachometer scales are



read directly without preliminary setting or calibration. One lead is connected to side of the distributor, one lead to ground. A switch is set for the number of cylinders. Then the thumb switch is pressed forward for reading of point dwell. When released, the switch automatically returns to the tachomèter position for a direct reading of r.p.m. Write: Kal-Equipment Co., 411 Washington St., Otsego, Mich.

Anchor Clamps

Permits pulling from the point of impact without damaging car

Blackhawk Automotive Division: Secure anchoring of the Damage-Dozer Body and Frame Straightener to underbody "pinch welds" of unitized cars is said to be assured with new EK-30 anchor clamps. Offered in



right and left-hand models, model No. EK-229 and EK-230 respectively, the clamps permit pulling from the point of impact (down or out, to front or back) without damaging the car at anchor point. Besides using for pulling, the anchor clamps have offset holes for use with Safety Continued on page 96



HERBRAND DIVISION . THE BINGHAM-HERBRAND CORPORATION . FREMONT, OHIO

THE CHILTON MANUALS PAGE



By Paul A. Murphy Editor of Chilton's Flat Rate and Auto Repair Manuals

Ignition Timing Revision

The recommended setting for ignition timing on the 1960 Ford car, 6 cylinder and 292 V8 engines with automatic transmissions, has been revised from 6° before top dead center to 10° before top dead center. This new 10° setting will generally provide satisfactory engine performance with the fuels available in most areas.

If the engine should not perform satisfactorily at this setting, the timing can be retarded within the allowable range of 2° before top dead center to 10° before top dead center. Caution: This revised timing applies to cars equipped with automatic transmissions only.

Reaming Valve Guides

Some mechanics are under the opinion that by increasing the guide diameter the valve will float more and thus produce a possible cure for valve sticking.

What they fail to realize is that when a valve is allowed to float in the guide, the guide loses control of the valve stem to a point where the valve will strike the seat unevenly.




WATCH THE FORDS go by was the obvious comment in Flora, III., recently when the 1961 Ford cars and trucks were introduced. Ford Motor Co. officials loaned a new Ford to every family in the town for one week who had at least one member of the family as a licensed driver. Flora residents responded with enthusiasm in this mammoth "test drive". Scene above is center-city Flora.

Go Weaver all the way!

SERVICE MORE CARS PER DAY— GET MAXIMUM EQUIPMENT LIFE

A Weaver-equipped shop is a profitable shop! Every item in the Complete Line of Weaver Service Shop Equipment is designed to make your job easier, and your mechanics more productive. You are sure of dependability, long service life, maximum anti-obsolescence. And, Weaver service-trained representatives show you how to get the most from your equipment.



Ask your jobber for details.

WEAVER MANUFACTURING DIVISION . DURA CORPORATION Springfield, III., U.S.A.

A COMPLETE LINE-AND NO ONE BUILDS IT BETTER THAN WEAVER



SERVICE SHOP EQUIPMENT

OVER 50 YEARS SERVING THE AUTOMOTIVE SERVICE INDUSTRY

Complete Weaver line includes: Twin Post* Lifts • Triple Post Lifts • Frame Type, Roll-On and Free-Wheel Single Post Lifts • Unit Lifts • Bumper Jacks • Car Washers • Wheel Alignment Equipment • Headlight Testers • Brake Testers • Wheel Balancing Equipment • Jocks • Wheel Dollies • and Air Compressors (*Registered Trademarks)

New Products

. . Continued from page 94

idea

BROOKLYN 7. NEW YORK

Stands and support tube. With this setup shafts and radius bars are cleared while the car is kept level at all times. The clamps, which can be used singly or in pairs are attached by tightening four cap screws. Write: Robert D. Barnard, Adv. Dept., Blackhawk Automotive Division, Dept. 51G, 5325 W. Rogers St., Milwaukee, Wis.

Spray De-Icer

Melts frost and ice on car windshields

Union Carbide Consumer Products Company: A new automotive chemical packaged in a 16-ounce size spray can melts frost and ice on car windshields, lights, locks and windows, company claims. It prevents inside

glass fogging and keeps ice from forming for hours. It also provides wheel traction under cer-



tain icing conditions, it was stated. The "Prestone" Spray De-Icer AS-241 has a propellant system that shoots a spray of De-Icer at temperatures ranging down below 0°F. It is harmless to car finishes, company claims. Write: D. C. Parker, Union Carbide Consumer Products Co., Div. of Union Carbide Corp., 30 E. 42nd St., New York 17, N.Y., or phone Murray Hill 7-8000.

Two-Jaw Puller

Removes Generator Pulley Without Damage

Owatonna Tool Co.: The use of a small, 2-jaw Grip-O-Matic puller to remove Autolite generator pulleys (press fit) without damage to parts is announced. The puller, No. 1000½-L, weighs 14 oz. It has approximately ¾-



ton capacity. OTC shaft protector No. 625-6 with tip filed off is used with the puller when removing Autolite generator pulleys. C. Kyle Peterson, Adv. Mgr. Owatonna Tool Co., 321 N. Cedar St., Owatonna, Minn.



Snaplock clamps. . . . They're a cinch to put on --

save us valuable time -- and

guarantee a leakproof grip."

The pacesetter in hose clamps since 1913

the quality of



Preference for EIS — The Brake Parts Line — is based on proved advantages. EIS Brake Parts build your reputation for top-quality replacements! EIS Brake Parts are built to rigid specifications, thoroughly inspected, packaged in easy-to-read cartons and described in quick-reference catalogs! Add the EIS reputation for fast delivery from any one of 36 strategically located warehouses and, sure as stopping, the profits in EIS Brake Parts have got to show up in every sale—in every job!



A BARREL OF PROFIT!

Calibrated Ride Control With Any Loa

CHECK THE
DIFFERENCE
BETWEEN WORN AND
GOOD SHOCKS

MONRO-MATIC ABSORBERS

> HAVE YOUR CAR COMPLETELY Safety Checked



Buy Monro-Matics by the barrelget this **NEW Demonstrator FREE**

Now, a great new idea to help you sell shock absorbers like you've never sold them before! Packed in a steel barrel that doubles as a hard-working display are 14 of the most popular Monro-Matic shocks and 4 Monroe Super Load-Levelers. Fastened to the underside of the barrel lid is a shock absorber demonstrator. Flip the lid, weight the barrel with sand or water, and the demonstrator is ready to clinch many a sale for you!

Add this new merchandising idea to the far-reaching Monroe promotional drive, and you can't miss. Monro-Matics get a tremendous push, month-after-month, in LIFE, THE SATURDAY EVENING POST, POPULAR MECHANICS and SPORTS ILLUS-TRATED. Every morning Monday through Friday, millions of car owners hear the Westbrook Van Voorhis "Monroe News" program and every morning and late afternoon millions more listen to BILL STERN on the "Monroe Sportsreel." Both of these popular broadcasters sell Monro-Matics on more than 325 stations of the Mutual Network. All this, plus a mountain of promotional material-ready to help you tie in directly with the hard-hitting national campaign!

DON'T MISS OUT ON THIS ONE! See your Monroe jobber now.

14 Monro-Matic Shock Absorbers **BD-18 Assortment**

4 Super Load-Levelers \$228.20 Your selling price

\$140.90 YOUR PROFIT 587.30

FREE

\$10 Shock Demonstrator

- \$ 5 Painted Barrel Test Stand
- 2 Shock Absorber Window Banners
- 2 Load-Leveler Window Banners
- 10 ft. Plastic Outdoor Banner
- 100 Hand-out Leaflets

MONROE AUTO EQUIPMENT COMPANY, Monroe, Michigan

In Canada, Monroe-Acme Ltd., Toronto, Ontario In Mexico, Mex-Par, Box 28154, Mexico City WORLD'S LARGEST MAKER OF RIDE CONTROL PRODUCTS

MONRO-MATIC

SHOCK ABSORBERS



Electronic Detection Continued from page 47

years the only means of locating leaks. It can be used for locating all leaks down to about 8 or 10 ounces per year. When searching for leaks, the probe may be moved about 1/4" per second.

The electronic leak detector, a relative newcomer to the auto service shop, can be used to locate leaks down to ½ ounce per year. Its probe may be moved up to 2" per second when searching for leaks.

The halide torch consists of a burner on top of a small tank of gas or alcohol. Some of the air for combustion is drawn into the flame (chimney fashion) through a tube connected near the bottom of the flame. A flexible extension of this tube is used as a probe to locate leaks. When the open end of this tube passes near a leak, refrigerant gas will be drawn into the flame. If the leak is large enough, the flame will change color. This indicates that a leak has been located.

The electronic leak detector, when plugged into a lighting circuit (120 V, 50/60 cycles) is ready to operate one minute after being turned on.

The one dial on the control unit is an ON-OFF switch, it also regulates sensitivity when turned.

A light in the probe flashes for about one second when the tip of the probe passes near a leak. Thus the leak can be easily and quickly pinpointed. The minimum leak to be detected can be pre-set by checking the detector against a reference each time it is used.

When searching for leaks, the user should adjust the reference leak to equal the minimum size leak to be detected. Then adjust the leak probe light will give one very short flash each time the probe "sniffs" the reference.

With the tip of the probe lightly touching the surface, move the probe along seams and around joints at a speed of 1 or 2 inches per second. When the probe tip passes a leak about the same as (or greater than) the reference, the probe light will flash.

Large leaks of several ounces per year will usually cause the lamp to flash twice. When the light flashes, lift the probe about 15 inches. If the lamp flashes only when the same spot is touched with the probe tip, the leak has been "pinpointed." If the probe light flashes when other nearby spots are touched, reduce sensitivity until a flash occurs only for one spot. A large leak can thus be pinpointed.

A $1_8^{\prime\prime\prime}$ diameter extension tube for the probe permits reaching restricted areas that cannot be reached with the larger plastic probe.

Halogen leak detection techniques are currently being extended by auto servicemen to many other useful applications in the shop. An example would be leaking tires. Leaks that cause tires to go soft in a week or two sometimes cannot be located by using the water immersion test.

To locate such leaks, increase the normal tire pressure about 4 pounds per square inch. Do this by adding R-12 from a commercially-available pressurized container. With leak detector sensitivity set at ½ oz. per year, the offending leak can be located.

To locate leaks in radiators, drain all water and seal all openings. Then pressurize radiator to about 5 pounds gage by adding R-12 Continued on page 102



Doublebarreled truck profit opportunity for dealers:

TOTALLY DIFFERENT TYPES

OF CHEVY TRUCKS FOR '61!



REAR-ENGINE CORVAIR 95's-Here's the newest thing in moving loads since the horse went out of style! Three Corvair 95 models-two pickups and a panel-have joined Chevy's '61 fleet, each one with more load space than a conventional half-tonner. Yet they measure more than two feet shorter from bumper to bumper! Corvair 95's feature an air-cooled engine in the rear; 4-wheel independent suspension; integral body-frame construction; nearly fifty-fifty weight distribution front and rear, loaded or unloaded; enough capacity to handle up to 1,900 pounds of payload on a nimble 95-inch wheelbase!



TORSION-SPRING '61 CHEVROLETS-They're the latest editions of the trucks that revolutionized trucking with their load-saving, road-paving independent front suspension. Torsion-spring trucks proved worth more because they work more! With these two totally different types of trucks for '61, Chevrolet dealers have more models to offer, more ways to profit than ever before! . . . Chevrolet Division of General Motors, Detroit 2, Mich.

THE GREATEST SHOW ON WORTH! CHEVROLET



Electronic Detection Continued from page 100

through the drain valve. This will result in absolute pressure of about 20 psia.

With leak detector sensitivity at ½ ounce, all leaks down to two oz./year (equivalent R-12 leak) can be located.

To determine if water is seeping into the engine cylinder from the water jacket, pour about one cup of trichlorethylene into the radiator. (Some high test gasolines contain a halogen. Before adding trichlorethylene to radiator, allow leak detector to sniff exhaust while engine is idling. If leak detector gives no signal, proceed.)

Start the engine, speed it up once, and then alow it to idle. Adjust the leak detector to respond to a leak of 1/2 ounce per year. Let the engine

idle. If the light in the probe flashes each time the probe is brought into the exhaust stream (at a point about six inches from the end of the tail pipe) indication is that the head gasket is leaking between water jacket and cylinder. Stop engine. Remove spark plugs one at a time. "Sniff" with the detector probe. The probe light will indicate the cylinder into which water is leaking. Determining which cylinder eliminates need for removing both heads of a V-8.

Exhaust System Leaks

Exhaust-system leaks are sometimes difficult to locate (exhaust manifold seals, joints in exhaust pipe and to muffler, leaking spark plugs, etc.). The following procedure is helpful:

Pour an ounce of trichlorethylene into the oil of the air filter. Allow the engine to idle with fan belt removed to eliminate wind. Adjust sensitivity of the leak detector so that when allowed to sniff the heat riser shaft end, the leak detector gives a short flash.

Then probe around the manifold and all joints that might leak. Leaks equal to or greater than at the heatriser shaft can be detected. The reason? Because some of the trichlorethylene in the air filter will go into the engine and through the combustion chamber into the exhaust.



"Well now, settle down, boss you told me to put in a supply."

STATEMENT REQUIRED BY THE ACT OF AUGUST 24, 1912. AS AMENDED BY THE ACTS OF MARCH 3, 1933, JULY 2, 1946 AND JUNE 11, 1960 (74 STAT. 208) SHOWING THE OWNERSHIP, MANAGEMENT, AND CIRCULATION OF CHILTON'S MOTOR AGE, published monthly at Philadelphia 30, Pa. for October, 1960.

- 1. The names and addresses of the publisher, editor, managing editor, and business managers are: Publisher, Russell W. Case, Jr., Ridley Creek Road, Media, Pa. Editor, Frank P. Tighe, 1017 Drexel Avenue, Drexel Hill, Pa. Managing Editor, William H. Wolfe, 517 Bradford Road, Oreland, Pa. Business Manager, Russell W. Case Jr., Ridley Creek Road, Media, Pa.
- 2. The owner is: (If owned by a corporation, its name and address must be stated and also immediately thereunder the names and addresses of stockholders owning or holding I percent or more of total amount of stock. If not owned by a corporation, the names and addresses of the individual owners must be given. If owned by a partnership or other unincorporated firm, its names and addresses, as well as that of each individual member, must be given.) Chiton Company, Chestnut and 56th Sts., Philadelphia 39, Pa.

Holders of more than 1 per cent of the capital stock outstanding of Chilton Company: Mary M. Acton, 260 Sycamore Avenue, Merion Station, Pa.; Mrs. Beulah Fahrendorf, Chateu LaFayette, Scaradale, New York: Dorothy S. Johnson, Route I. Putnam Valley, New York; Stiroet, Philadelphia, Pa.; Mary M. Meton, Surviving Trustee U.W./O Chrence A. Musselman, Dec'd, c/o R. F. Irwin, Jr., 2318 Packarti Bldg., Philadelphia, Pa.; Hary M. Acton, Surviving Trustee U.W./O Chrence A. Musselman, Dec'd, c/o R. F. Irwin, Jr., 2318 Packarti Bldg., Philadelphia, Pa., Beneficiaries, Mary M. Acton and David Acton; J. Howard Pew, 1608 Walnut Street, Philadelphia, Pa.; J. N. Pew, Jr., 1608 Walnut Street, Philadelphia, Pa.; J. N. Pew, Jr., 1608 Walnut Street, Philadelphia, Pa.; Mary Ethel Pew, 1608 Walnut Street, Philadelphia, Pa.; Mary Chrestoff, M. S. Street, New York; Alberta C. Sly, and Street, New York; Alberta C. Sly, and John E. Sly; Soleil Farns, Inc. 1606 Walnut Street, Philadelphia, Pa.; Charlotte M. Techune, 160 E. 48th Street, New York; Steere & Company, c/o Girard Trust Corn Exchange Bank, Philadelphia 2, Penna.

- 2. The known bondholders, mortgagess, and other security holders owning or holding 1 per cent or more of total amount of bonds, mortgages, or other securities are: (If there are none, so state.) None.
- 4. Paragraphs 2 and 3 include, in cases where the stockholder or security holder appears upon the books of the company as trustee or in any other fiduciary relation, the name of the person or corporation for whom such trustee is acting; also the statements in the two paragraphs show the affiant's full knowledge and belief as to the circumstances and conditions under which stock-holders and security holders who do not appear upon the books of the company as trustees, hold stock and securities in a capacity other than that of a bona fide owner.
- 5. The average number of copies of each issue of this publication sold or distributed, through the mails or otherwise, to paid subscribers, during the 12 months preceding the date shown above was: (This information is required by the act of June 11, 1880 to be included in all statements regardless of frequency of issue.) 67,008.

(Signature of publisher) R. W. Case, Jr.

Sworn to and subscribed before me this 21st day of September, 1960.

PHILIP J. SHIRE, JR.

(My commission expires January 7, 1963)



order from your jobber


NU-MA-CO PLASTICS BRAKE HOLE COVERS

- Newly designed construction
- Engineered to fit all Bendix brakes
 Insist on the original brake plugs
- priced to give you big profits

 Patented, other patents pending.
- NEWNAN MACHINE COMPANY P. O. Box 737, Providence 1, R. I.

order from your jobber





STEP UP YOUR TUNE-UP AND LIGHT REPAIR PROFITS with Delco-Remy's new cabinet and identification programs

Tune-up and light repair is a real money-maker—and Delco-Remy offers a program to help you cash in big on it with quality ignition parts for <u>all</u> popular American cars and light trucks. A parts cabinet for every inventory need. Saves you time and space, provides a complete coverage inventory. The cabinet program includes INVENTORY CONTROL CARDS TUNE-UP SPECIFICATIONS NEW CATALOGS ADJUSTABLE SHELVING DIVIDED AND NUMBERED PARTS DRAWERS—plus many other profit building features.

A-1057 & A-1059 CABINET COMBINATION.

MAXIMUM STORAGE, MINIMUM SPACE.

Dimensions 72½" high, 28½" wide, 15" deep.





A-1055 A REAL TIME AND SPACE SAVER. Dimensions 17" high, 28\%" wide, 15" deep.



FRESH NEW SALES BUILDING IDENTIFICATION FOR YOU!

The new Delco-Remy identification program helps you PROFIT by tying in with national consumer advertising on two network TV shows.

A-140 Three-dimensional portable sign. Use wherever needed. Contains utility tray for tools. Dimensions 30% x 25% x 7½.

A-1049 Three-dimensional electrical sign. In window or on wall—positive identification. Dimensions 14" x 13" x $6\frac{1}{2}$ ".



GET THE COMPLETE DETAILS ON THE DELCO-REMY PROGRAM FROM YOUR UNITED MOTORS SERVICE PARTS SUPPLIER

More Reliable GM Products Distributed Through



OLDS DEALERS HAVE ITI

The "Plus Business" Car!

Hot new number

in the LOW-PRICE FIELD!

F-85

. . . every inch an OLDSMOBILE!



Here's an all-new kind of car in the low-price field—more agile to drive, more economical to operate! Sized to seat six in comfort! Not too big . . . not too small . . . just right! So sturdy and road-sure it'll go all day without tiring! Smooth and quiet in the Oldsmobile tradition! A profitable package to sell!



Built for the buyer who wants something better in a smaller car!

Your prospects can choose from Sedans or Wagons . . . beautiful interiors in either glamorous fabrics or all-Morocceens. Let them check the quality, roominess, equipment . . . be sure they drive a new F-85! Once they take the wheel, they'll know this is an Oldsmobile!

OLDSMOBILE DIVISION . GENERAL MOTORS CORPORATION . LANSING, MICH.

For 1961 . . . the low-price F-85 makes it better than ever to be with OLDS!

ORDER YOUR PACKARD CABLE NIEEN OTHER TO OTHER TO







High- and Low-Tension Cable



Packard Electric has a complete line of quality automotive cables. They are used on more cars than all other makes combined. From Connectors to Highand Low-Tension Cable, through Battery Cable and T.V.R.S. (Television-Radio Suppressor) Cable, Packard Electric Products have a well-earned reputation for reliability and are packaged for profit and convenience.

AND ENJOY



Engine Compartment Cable

VALUABLE CDECIAL D



SPECIAL BONUS!

SPECIAL DEAL-

A CASCO ELECTRIC BLANKET

FOR ONLY \$11.95 A \$20 order for any combination of Packard products qualifies you. All you have to do is figure your cable needs for the season. Ask your U-M-S supplier to explain just how easy it is to get one of these Casco Electric Blankets, twin or double size.





They see it! They love it! But, wow— when they drive it!



SALES OF BUICK'S NEW-SIZE SPECIAL ARE AS LIVELY AS ITS RARIN' NEW GO!

"Sure looks like the big Buick." "Look at the beautiful upholstery!" "You'd never guess it's a smaller car — it's so beautifully scaled." These are just a few of the raves dealers report about the Special. And they say that when folks get the feel behind the wheel — wow! — how the buying temperature soars!

The reason? The Special's no "compromise car"

— and no mistake. Sure it saves and handles like the best of the compacts. But, its big Comfort Zone has more total head, leg, and hip room than the compacts. Thanks to its zippy 155 HP aluminum V-8 and aluminum transmission, it has twice the pow per pound of most compacts. It's got the same smooth-riding kind of Control Arm suspension as full-size '61 Buicks. And, it's got Buick's sleek Clean Look of action.

In short, the Special is a *Buick* — in room, in ride, in go, in pride. And, the public is eating it up!

SPECIAL-SIZE



BUICKSPECIAL

THE BEST OF BOTH WORLDS

IMPACT!

THAT'S THE BIG WORD FOR MCCORD'S NEW MUFFLER PROGRAM!

Yes, now the power, the speed you need to compete for exhaust system service profits are yours in the impact wrench the automotive aftermarket has been waiting for ... the revolutionary new McCord multi-purpose, air-powered impact wrench. It's smaller, simpler, more rugged and powerful than any other impact wrench available ... air or electric.



- # It's compact (7½" long) . . . light-in-weight (5 lbs. 5 oz.)
- # Has no electric motor, commutator or brushes... fewer moving parts
- Operates effectively on low volumes of air . . . as low as 40 lbs. pressure
- Generates little heat and no commutator sparks

 Provides infinitely variable speed control, higher torque
- * Can be disassembled and assembled with one Allen Wrench

Add them all up and the McCord Air Impact Wrench is easier, safer to use, less costly to operate and maintain, more versatile and efficient than any impact wrench in sight.



NOW, LOOK AT THE PRICE ...

with the purchase ... at one time ... of 6 McCord Mufflers of your choice, this amazing air impact wrench is yours for

JUST \$71.35 (a \$143.20 value!)

including two ½" drive socket wrenches . . . ½" and %6" hex



Also available, as an optional extra, this sturdy metal tool box... specially designed to carry the impact wrench and sockets, plus the McCord air gun and chisels. Price, \$4.60.

Hurry! Get your order in for the new McCord Air Impact Wrench. See your McCord Jobber TODAY!

MCCORD CORPORATION

DETROIT 11 . MICHIGAN

Still the Leader In the Co

RAMBLER FOR 1961

RAMBLER AMERICAN

The Economy Compact

The recognized Economy King is all-new in style and beauty for '61. More compact than ever-even easier to park and garage. See the new American Beauty with room for a family of six.





The All-Purpose Compact

Only Rambler Classic gives you the Best of Both: big car room and comfort . . . compact car economy and handling ease. Choose from two great engines-America's only Die-Cast Aluminum Six-or high performance V-8.

AMBASSADOR V-8 by Rambler

The Luxury Compact

Here is the fine balance of the elegant and the agile. Luxurious room for six 6-footers combined with trim exterior size . . . stronger, safer Single-Unit construction combined with your choice of 250 or 270 H.P. V-8 engines.




RAMBLER...The New World

mpact Car Field...



See These New Rambler Exclusives



AMERICA'S ONLY DIE-CAST ALUMINUM SIX

The new engine proved by over 2 million test miles. Reduces front-end weight by 80 pounds. Aluminum die-cast under enormous pressure to a flawless perfection that has never before been possible.



NEW WARRANTED CERAMIC-ARMORED MUFFLER

A Rambler first! Muffler and tail-pipe coated with a special ceramic material that protects against corrosion—are warranted against defects for as long as the original owner owns a 1961 Rambler.



NEW CUSHIONED ACOUSTICAL CEILINGS OF MOLDED FIBER-GLASS

Deadens road noises by at least 30%. Increases headroom. Insulates against summer heat and winter cold. Permanently shaped for perfect fit. Standard on 1961. Rambler Classic and Ambassador models.





Premiere Showing: At the National Auto Show

NEW RAMBLER AMERICAN CONVERTIBLE

On display for the first time—America's favorite compact in America's most glamorous body style!

Standard of Basic Excellence

Why FORD, GM, CHRYSLER & Others RECOMMEND

Thread Repair Kits

To Restore All Stripped Threads Quickly and Permanently

The reasons are simple - with Heli-Coil Stainless Steel Wire Screw Thread Inserts you can:

- · restore threads to original dimensions no need
- provide armor clad protection to all tapped holes especially important in aluminum - permanently prevent wear, stripping, corrosion, galling, and seizing.
- make thread repairs in just minutes for only pennies per hole.

Use Heli-Coil EZY-KITS that contain individual EZY-PACKS of Inserts in selected sizes, plus installation tools. Popular combinations of packs for cars and trucks are sup-plied in all thread series and sizes. MM sizes in all reaches for spark plug holes are also available.




For descriptive literature and name of your local Heli-Coil Jobber, write .



3011 Shelter Rock Lane, Danbury, Connecticut

In Canada: ARMSTRONG BEVERLEY ENGINEERING LTD. 6975 Jeanne Mance St., Montreal 15, Que. @ 100a



Typical presentation for 6 cylinder engine reduced from 5-inch screen

THE MOST INFORMATION FOR EXACT TUNE-UPS!

Only the EnginScope details each cylinder simultaneously - only the EnginScope provides a trace for each cylinder.

Every minute detail of each cylinder's Ignition cycle presented with all cylinders simultaneously to help you do precision tune-ups.

Applicable to commercial and military vehicles, including shielded ignition systems.

DYNAMIZE YOUR CARS

write for details on the fabulous

EnginScope

I'M TIRED OF BEING *SOAKED!



Order from your jobber

Prices start at about \$2.50

or write for FREE FOLDER "Facts on Jacks" JACK-PACK MFG. CO., 2115 N. Marinna Ave., Los Angeles 32, Calif.



STOP PAYING FOR DAMAGED BUMPERS

Use a **LEE** Front End Lift

Lifts all cars by center plate between the A-frame or any stable cross member. Small ... easy to handle. About 4' long ... stores in 29 sq. inches.

- 1. Raises all four wheels with aid of two rocker-head stands.
- 2. No special adapters required.
- 3. By rocking front end down, rear is easily

AUTOMOTIVE EQUIPMENT MFG, CO.


Buy Bonds

ADVERTISERS' INDEX

This Advertisers' Index is published as a convenience, and not as part of the advertising contract. Every care will be taken to index correctly. No allowance will be made for errors or failure to insert.

| A | Fram Corp | 81 | P | |
|--|--|------|---|-----|
| AC Spark Plug Div 65 thru 69 Agency-D. P. Brother & Co., Inc. | Agency-McCann-Marschalk Co. | | Packard Electric Div 10 Agency—Campbell-Ewald Co. | 15 |
| Albertson & Co., Inc | Gabriel Co | 72 | Pennzoil Agency-Fuller & Smith & Ross, | 0 |
| Aluminum Industries, Inc 8-9 Agency—Applegate Advg. Agency, | Agency—Gray & Rogers Advg. Gates Rubber Co | | Inc. Perfect Circle Corp2nd Cove | or |
| American Brakelok Div | Agency-Harold Walter Clark, Inc. General Electric Co | 18 | Agency-Compton Advg., Inc. Permatex Chemical Products, Inc 10 | |
| American Motors Corp 108-109 Agency-Geyer, Morey, Madden & | General Electric Co. Agency-Batten, Barton, Durstine & Osborn, Inc. General Motors Corp. | 27 | Agency—De Garmo, Inc. Porter Co., Inc., H. K., Thermoid Div. | |
| Ballard, Inc. American Telephone & Telegraph | Agency-Campbell-Ewald Co. | 4/ | Agency Erwin Wasey, Ruthrauff | er |
| Co. 79 Agency—Cunningham & Walah, Inc. | н | | & Ryan, Inc. Purolator Products, Inc. | 4 |
| Armstrong-Victor Div 6 Agency-Buchen Co. | Hall-Toledo, Inc | 78 | Agency-J. Walter Thompson Co. | |
| Automotive Equipment Mfg. Co 110 Agency-Mays & Co. | Hamon Co., Harvey E | 84 | R | |
| | Heli-Coil Corp | 110 | Radiator Specialty Co |)2 |
| В | Heller Tool Co | 71 | £11C. | |
| Black & Decker Mfg. Co | Herbrand Tools | 94 | 5 | |
| Bosch Corp., Robert | Agency-Slayton-Racine, Inc. | | Schrader's Son, A | 77 |
| Breeze Corp., Inc | The second second second | | Skil Corp | 83 |
| Buick Motor Div | Ideal Corp | 96 | Standard Motor Products Inc | ı |
| C | Ingersoll-Rand Co | 29 | | 89 |
| Champion Spark Plug Co30-31 | Inland Mfg. Co | 91 | | 02 |
| Chevrolet Motor Div | J | | T | |
| Chrysler Motors Corp., Mopar Div. 11 Agency-N. W. Ayer & Son, Inc. | Jack-Pack Mfg. Co | 110 | Thermoid Div., H. K. Porter Co., Inc. | er. |
| Agency-Duffy, McClure & Wilder, Inc. | K | | Agency-Erwin Wasey, Ruthrauff & Ryan, Inc. | |
| Commercial Credit Corp | K-D Mfg. Co | 90 | Thompson-Ramo-Wooldridge, Inc. Replacement Div | 3 |
| Inc. | Ken Tool Mfg. Co. | 80 | | 76 |
| D | Agency-Norman Malone Assoc. | | Agency-Atlantic Bernstein Associ- ales | |
| Delco Moraine Div., G. M. Corp 73 | L | | Tung-Sol Electric, Inc., Automotive | 12 |
| Agency—Campbell-Ewald Co. Delco-Remy Div., G. M. Corp 92-93 | Legvold Enterprises, Inc | 88 | Agency—E. M. Freystadt Assoc., Inc. | |
| Agency—Campbell-Ewald Co. Ditzler Color Div., Pittsburgh Plate Glass Co | Lucas Electrical Services, Inc | 86 | Tungsten Contact Mfg. Co., Inc 10 Agency—The Furman Co., Inc. | 00 |
| Glass Co | Agency-McCarty Co. | | U | |
| Agency-William Glazer Advg. | M | | United Motors Service Div., G. M. | |
| Dow Corning Corp | McCord Corp | 107 | Corp | 03 |
| Du Mont Laboratories, Inc., Allen B. 110 Agency—Lescarboura Advg., Inc. | Monroe Auto Equipment Co | | | |
| | Moper Div., Chrysler Motors Corp., Agency-N. W. Ayer & Son, Inc. | . 11 | V | |
| E | | | Victor Mfg. & Gasket Co | ō |
| Eis Automotive Corp 97 Agency—The Furman Co., Inc. | N N | | w | |
| Electric Autolite Co. Spark Plugs Div24-25, 74-75 | New Britain Machine Co | 7 | Wagner Electric Corp16- | 17 |
| Agency-Grant Advg., Inc. | Newnan Machine Co | 102 | Agency-Arthur R. Mogge, Inc. | 87 |
| F | | | Agency-Carlson & Co., Inc. | 95 |
| Ford Motor Co. | 0 | | Agency-Clark & Boberts, Inc. | |
| Parts & Service Div | Agency-D. P. Brothers & Co., Inc. | 104 | Wilkening Mfg. Co | 37 |





Two secretaries who worked in a car dealership were chatting during the coffee break. The blonde spoke to the redhead: "My boy friend and I are having a slight disagreement. I'm holding out for a big wedding but he wants to break the engagement!"

Mechanic: "May I have the afternoon off to go shopping with my wife?"

Service Manager: "I'm afraid not." Mechanic: "Good. I can't thank you enough."

Definition of vision: Something we have after we find out that we guessed correctly.

A man stood on a busy street corner waiting for the traffic to slacken so he could cross. But the cars continued to roar by without pause. Fion the other side of the street. "How did you get across?" he yelled.

The answer floated back: "I was

born over here!"

Wife to mechanic-husband while out on a Sunday drive: "Slow up a bit, dear. That nice-looking policeman who's been following us wants to pass."

Doctor: "This peculiar behavior you mention about your son, after all isn't it a matter of heredity?" Proud Mama: "Certainly not!

There's never been the slightest trace of heredity in our family."

Definition of a pedestrian: A person who is both a husband and father and didn't think the family needed two cars.





MOTOR SALES "Selas Rotom, Good Morning!"

Small-town garage 'racks up' big-city sales:

50 to 75 belts a month by checking every belt!

Ferde Bosch, Owner
F & G Service
Casselton, North Dakota, says

"Although we're located in a very small town off Interstate Highway 94, we average 50 to 75 belt sales a month! We do this by checking every belt on every car coming into our garage. When we find a bad belt our complete stock of Gates Belts means a sure sale and a happy customer.

"Gates Belts are tops in quality and the Gates Catalog and Dial Finder make it easy to find and install the right belt in a matter of minutes.

"We find that we get a large coverage of popular cars with a minimum investment, and as a profit maker, the Gates Belt is the one at the top!"

Start Making More Profit—TODAY—on Fan Belts!

Call your nearby Gates Supplier and tell him you want to "go" Gates. At no cost to you, he will have a factory-trained Gates Representative install attractive belt racks, clean up your stock, provide Catalogs and a Belt Finder and give you

tested methods that boost belt sales. He will also help you get your stock in shape for maximum profits without loss of one penny on present stock.

The Gates Rubber Company
Denver Colorado



World's Largest Maker of V-Belts



To find belt wear always turn belt over — The underside of the belt...not the top...tells the true condition of the belt.

REPLACE BELTS












TPAS20

8212

Gates Vulco V-Belts

NEW ECONOMY FROM Thermoid





DRTOBLOCK

New Low-Cost Blocks for Medium-Duty Service

"Portoblocks" are specially designed for use on rigs where tough operation is not critical. Yet these new brake blocks, produced by Thermoid quality manufacturing methods, are far superior to conventional economy priced brands. They provide even better stopping and better service than some "so-called" first-grade blocks selling at far higher prices.

In fact, "Portoblocks" are made and finished to the same precision standards as Thermoid's first-line "Pressure-Forged" blocks.

Get the full story on new "Portoblocks" from your

Thermoid Distributor or write Thermoid Division, H. K. Porter Company, Inc., 200 Whitehead Road, Trenton 6, New Jersey.

New "Portoblocks" have:

- Safe stopping ability
- Excellent resistance to fade
- · High-grade materials, including brass chips
- · Precision ground for exact fit
- · No-squeal construction

THERMOID DIVISION



H. K. PORTER COMPANY, INC.

PORTER SERVES INDUSTRY with steel, rubber and friction products, asbestos textiles, high voltage electrical equipment, electrical wire and cable, wiring motors, fans, blowers, specialty alloys, paints, refractories, tools, forgings and pipe fittings, roll formings and stampings, wire rope and strand.

